

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

DATE: **August 18, 2016**

<p>T0: NAVIGATION INTEREST</p>	<p>FROM:</p>
---------------------------------------	--------------

RIVER/HARBOR NAME AND STATE: Connecticut River Below Hartford, North Cove, Old Saybrook, CT; Dwg. No. CRB-1028, Sheets 1-2 of 2, Dated 18 August 2016

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (Nautical miles)	MLLW DEPTH (feet)			
<p><u>CONDITION SURVEY</u></p> <p><u>11-Foot Channel</u></p> <p>From about 20' seaward of Buoy GC-15 upstream 2,239' to 11-Foot Anchorage</p>	6/16	100	.37	11.0	3.6	4.2	(1) 3.2
<p><u>11-Foot Anchorage</u></p> <p>Thence upstream about 950' to the 6-Foot Anchorage</p>	6/16	650	12.3 acres	11.0		2.5 available	(2)
<p><u>6-Foot Anchorage</u></p> <p>Thence upstream about 1280' to the upstream end of the 6-Foot Anchorage</p>	6/16	580	17.0 acres	6.0		3.1 available	(3)

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 2.3' within 5' of limit.
- (2). Except for shoaling to 1.8' within 5' of north anchorage limit.
- (3). Except for shoaling to 2.7' within 5' of north anchorage limit and shoaling to 2.1' within 5' of south anchorage limit.