
DAM INTAKE DEBRIS REMOVAL U.S. ARMY CORPS OF ENGINEERS UNION VILLAGE DAM THETFORD, VT PERFORMANCE WORK STATEMENT


Informational Photos



Informational Photo 1: Access Road 45-degree turn showing guardrail, ledge, and road gate.




Informational Photo 2: Set up area for crane at intake



Informational Photo 3: Example of debris in the intake at Union Village Dam. For informational purposes.

Informational Map



Informational Map 1: Approximate locations of the service areas and access roads.