

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

PAGE 1 OF 1 PAGE

DATE: **June 7, 2012**

T0:

FROM:

RIVER/HARBOR NAME AND STATE: Bucksport Harbor, Bucksport, ME
Dwg. No. PBH-2697, Sheet(s) 1 of 1, Dated 7 June 2012

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH Nautical (miles)	MLLW DEPTH (feet)			
<p><u>CONDITION SURVEY</u></p> <p><u>16-Foot Middle Ground Area</u></p>	8/11	230 x 1,040 x 1,370	20.3 acres	16.0		2.6 available	

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

(1). Encroaching by floats in the northeastern portion of anchorage.