QUALITY ASSURANCE REPORT (QAR) DAILY LOG OF CONSTRUCTION								591				Page 1 of 0	
DAIL! 200 OF CONCINCTION									DATE 31 Jul 2020 - Friday				
PROJECT Durham Meadows Waterline Remedial Design									CONTRACT NUMBER W912WJ19C0002				
CONTRACTOR Ludlow Construction Co., Inc.								WEATHER Weather Ca					
								Temperatu	re Min 78 °F I ation No Wind	Иах 95 °	F		
	PORTION OF S		AY SUITABLE	FOR OP				TEMPERATURE WIND					
STRUCTURAL EXC VATION	VATION		NKMENT	CONCR		TRUCTURE		MINIMUM	MAXIMU				
10	00 %	100 %	100 %		100 %		100 %	78		95 °F 0 MPH OUR PRECIPITATION			
HAS ANYTHING DEVELOPED ON THE WORK WHICH MIGHT LEAD TO A CHANGE ORDER OR FINDING FO FACT?					INCHES ENDING								
LEAD TO A	CHANGE ORDER	OR FINDING	FO FACT?		YES	(Explain)			0.00			М	
SUPERVISORY	NUMB OFFICE	ER OF GOVER	RNMENT EMF		TOTAL	LABOR		FEET	RIVI	ER STAC	SE TIME		
1	0		0		TOTAL		0		0.0		IIIVIL		
	OF CONTRACTO			2	NUMBER (3 DF SHIFTS	0	1 1	X 2		3	М	
SUPERVISORY	SKILLED	LABORERS	TOTAL		FROM	ТО	FF	ROM T	0	FROM		ТО	
0	0		0	0			0 M	М	N		М	М	
	ch a list of the follo TE: if the contractor								of contractor	personn	el onsite.		
QA NARRAT													
Work Perfor	•					Ĺ	Inresolv	red Issue: No	Sh	ift: 1			
Kurt Mintel On 17:	I												
Curb stops - 281 Main St 183+23, 281 Main #2 184+28, 281 #3 184+46 One CT State Police and one certified flagger. No Ledge encountered													
Tank Site:													
Rebar Inspection - ongoing Concrete was scheduled for LEAN Concrete footing (60 CY) for 1300 - this was canceled due to the testing requirement for the pipe stubs. Build rounded forms for the precast dome panels.													
Maple Stre	et Stream Cross	ing:											
Continue at the stream crossing at Maple Ave - install 12" DI pipe. The stream is still not open, per Jon Pio he will be opening up the stream on Monday.													
Pickett Lan	ne:												
Install brick	sidewalk at the	stream cross	ing where it	was rem	noved								
Items- 46: WORKING ON STREAM CROSSING ON MAPLE AVE - install 20LF of 36" conduit and back fill													
0034: 1" Co 0040: Piero 0054: Rock	urb Stops = 3 - 2 opper Pipe = 193 cing under sidew	3.00 LF alks = 22LF avation: = 0	83+23, 281	Main #2	184+28, 281	#3 184+46							
CQC Inspec	tion Phases Att	ended and Ir	structions	Given:		L	Inresolv	ed Issue: No	Sh	ift: 1			
1. #4 bars 2. Rebar no 3. Rebar pi 4. Pipe Pit on whether	of rebar for the toplaced 12" OC a ot closer the 2" froperly tied toget rebar 12" OC - y the pipe pit is the 5.5" above the fo	round the per rom the form ther - YES res, some reb ne correct size	- YES ear is closer e.	together		to the plans	s calling	foe 46 pieces	of rebar- th	ere is a	question	1	
Miscellaneo	us Remarks and	d Visitors to	Project:			L	Inresolv	red Issue: No	Sh	ift: 1			

Kurt Mintell
Left a paint mark for Armand to see (proposed water into basement) (147 Main) waiting for his response if the location works, per conversation- the CBYD the utilities are actually on the lot next door not on his property - notified Mike Pio to inform CBYD of this.

QA	REPRESENTATIVE'S SIGNATURE	DATE	RE/PROJECT ENGR'S INITIALS		DATE
	<u> </u>	J :==: J.			
	Kurt Mintell Noted damaged curb on Pickett under guardrail f	from stream crossing - KEEP OPI	EN		
	Miscellaneous Remarks and Visitors to Project:		Unresolved Issue: No	Shift: 1	
	Email to Karen Keane @ 289 Main Street that we	e would be installing her curb stop	o on Monday (AUG 3)		
	DOT Correspondence - NONE				
	Upon discussion with Armand and Mike Pio - the	water service will be installed on	Monday (August 3,2020)		