

**CHIMNEY WRAPPING ASBESTOS ABATEMENT
U.S. ARMY CORPS OF ENGINEERS
NORTH SPRINGFIELD LAKE
SPRINGFIELD, VT
Scope of Work
February 2016**



Informational Photo 1. Chimney exhaust in the North Springfield Lake Gatehouse.

**CHIMNEY WRAPPING ASBESTOS ABATEMENT
U.S. ARMY CORPS OF ENGINEERS
NORTH SPRINGFIELD LAKE
SPRINGFIELD, VT
Scope of Work
February 2016**



Informational Photo 2. Torn chimney wrapping located near the top of the exhaust pipe

**CHIMNEY WRAPPING ASBESTOS ABATEMENT
U.S. ARMY CORPS OF ENGINEERS
NORTH SPRINGFIELD LAKE
SPRINGFIELD, VT
Scope of Work
February 2016**



Informational Photo 3. Base of Chimney Exhaust

**CHIMNEY WRAPPING ASBESTOS ABATEMENT
U.S. ARMY CORPS OF ENGINEERS
NORTH SPRINGFIELD LAKE
SPRINGFIELD, VT
Scope of Work
February 2016**



Informational Photo 4. Chimney wrapping on chimney pipe in bulkhead gate storage area.