

**GATE HOUSE PAINT REMOVAL
U.S. ARMY CORPS OF ENGINEERS
WEST THOMPSON LAKE
NORTH GROSVENORDALE, CT
Scope of Work**

Information Photos



Informational Photo Number 1: Gate House Ceiling



Informational Photo Number 2: Gate House Ceiling

**GATE HOUSE PAINT REMOVAL
U.S. ARMY CORPS OF ENGINEERS
WEST THOMPSON LAKE
NORTH GROSVENORDALE, CT
Scope of Work**

Information Photos



Informational Photo Number 3: Gate House Ceiling



Informational Photo Number 4: Gate House Ceiling

**GATE HOUSE PAINT REMOVAL
U.S. ARMY CORPS OF ENGINEERS
WEST THOMPSON LAKE
NORTH GROSVENORDALE, CT
Scope of Work**

Information Photos



Informational Photo Number 5: Generator Room, No Paint Removal on plaster coated walls.




Informational Photo Number 6: Gate House, South Wall

**GATE HOUSE PAINT REMOVAL
U.S. ARMY CORPS OF ENGINEERS
WEST THOMPSON LAKE
NORTH GROSVENORDALE, CT
Scope of Work**

Information Photos



Informational Photo Number 7: Gate House, South East Corner



Informational Photo Number 8: Gate House, North East Corner

**GATE HOUSE PAINT REMOVAL
U.S. ARMY CORPS OF ENGINEERS
WEST THOMPSON LAKE
NORTH GROSVENORDALE, CT
Scope of Work**

Information Photos



Informational Photo Number 9: Gate House, West Wall