REPLACE HYDRAULIC CONTROL VALVES
U.S. ARMY CORPS OF ENGINEERS
WEST THOMPSON LAKE, NORTH GROSVENORDALE, CT
MANSFIELD HOLLOW LAKE, MANSFIELD CENTER, CT
Scope of Work

Informational Photos of West Thompson Lake

Informational Photo Number 1 – Existing 3 Vickers Hydraulic Control Valves



Informational Photo Number 2 – Hydraulic System Layout from As Built Drawing TH-1781.036



Informational Photo Number 3 – Hydraulic System Layout from As Built Drawing TH-1781.036

REPLACE HYDRAULIC CONTROL VALVES
U.S. ARMY CORPS OF ENGINEERS
WEST THOMPSON LAKE, NORTH GROSVENORDALE, CT
MANSFIELD HOLLOW LAKE, MANSFIELD CENTER, CT
Scope of Work
Informational Photos of Mansfield Hollow Lake

Informational Photo Number 4 – Existing Logan Hydraulic Control Valve #1

Informational Photo Number 5 – Existing Logan Hydraulic Control Valve #2

Informational Photo Number 6 – Existing Logan Hydraulic Control Valve #3

Informational Photo Number 7 – Existing Logan Hydraulic Control Valve #4

Informational Photo Number 8– Existing Logan Hydraulic Control Valve #5



Informational Photo Number 9 – Hydraulic System Layout from As Built Drawing TH-1-1223-58