

**REPORT OF CHANNEL CONDITIONS  
100 TO 400 FEET WIDE  
(ER 1130-2-520)**

PAGE 1 OF 1 PAGE

DATE: **October 29, 2015**

**T0:**  
**NAVIGATION INTEREST**

**FROM:**

RIVER/HARBOR NAME AND STATE: Oak Bluffs Harbor, Martha's Vineyard, MA  
Dwg. No. OAK-2, Sheet 1 of 1, Dated 29 October 2015

MINIMUM DEPTHS IN  
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)			
<p><b><u>CONDITION SURVEY</u></b></p> <p><b><u>10-Foot Channel</u></b></p> <p>From about 175' seaward of FI R-2 upstream 860' to upstream end of Federal Navigation Project</p>	9/15	75 to 120	.14	10.0	(1) 10.0	10.0	(2) 10.0

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 7.3' within 10' of limit.
- (2). Except for shoaling to 9.2' within 15' of limit.