

**REPORT OF CHANNEL CONDITIONS  
400 FEET WIDE OR GREATER  
(ER 1130-2-316)**

DATE: **December 2, 2011**

TO:	FROM:
-----	-------

RIVER/HARBOR NAME AND STATE: Owls Head Harbor, Owls Head, Maine Dwg. No. 2695, Sheet 1 of 1, Dated 2 December 2011	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
---	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH Nautical (miles)	MLLW DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	
<b><u>CONDITION SURVEY</u></b>  <b><u>6-Foot Anchorage</u></b>	11/10		8.12 acres	6.0		5.6	(1) Available	

**GENERAL NOTE:** The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

**FOOT NOTES:**

(1). Except for shoaling to 1.7' within 100' along west limit; shoaling to 2.3' within 230' radius at the northernmost corner of limit; encroachment by docks and floats in the vicinity of Owls Head Lobster and Ship to Shore Lobster Companies.