

**DEBRIS REMOVAL – LOG BOOM
U.S. ARMY CORPS OF ENGINEERS
NORTH HARTLAND LAKE
NORTH HARTLAND, VT
PERFORMANCE WORK STATEMENT**

Informational Photos



Informational Photo 1: Debris at the North Hartland Lake Log Boom during cleaning. The photo is intended to provide context to the nature of the work and set up area.

Informational Photos



Informational Photo 2: Debris in the water and field at North Hartland Lake along the Western Log Boom. Access road along the base of the dam and under the bridge. Photo taken April 4, 2025

Informational Map

U.S. Army Corps of Engineers
North Hartland Lake
Crane Access Map

Log Boom Area



Informational Map 1: Approximate locations of the service areas and access roads. Debris in map is not what is currently located on site.