

**GARAGE DEMOLITION  
U.S. ARMY CORPS OF ENGINEERS  
BIRCH HILL DAM  
ROYALSTON, MA  
Performance Work Statement  
Informational Photos**



**Informational Photo 1:** Garage With Low Hanging Utility Line Hazard

**GARAGE DEMOLITION**



**U.S. ARMY CORPS OF ENGINEERS  
BIRCH HILL DAM  
ROYALSTON, MA  
Performance Work Statement**

**Informational Photos**



**Informational Photo 2:** East Side Painted Door and Door Frame

**GARAGE DEMOLITION  
U.S. ARMY CORPS OF ENGINEERS  
BIRCH HILL DAM  
ROYALSTON, MA  
Performance Work Statement**

**Informational Photos**



**Informational Photo 3:** East Side Painted Garage Door Frame



**GARAGE DEMOLITION  
U.S. ARMY CORPS OF ENGINEERS  
BIRCH HILL DAM  
ROYALSTON, MA  
Performance Work Statement**

**Informational Photos**



**Informational Photo 4:** North Side Painted Roof Trim and Window Frame



**GARAGE DEMOLITION  
U.S. ARMY CORPS OF ENGINEERS  
BIRCH HILL DAM  
ROYALSTON, MA  
Performance Work Statement**

**Informational Photos**



**Informational Photo 5: North Side Overview**



**GARAGE DEMOLITION  
U.S. ARMY CORPS OF ENGINEERS  
BIRCH HILL DAM  
ROYALSTON, MA  
Performance Work Statement**

**Informational Photos**



**Informational Photo 6: South Side Painted Roof Trim**

**GARAGE DEMOLITION  
U.S. ARMY CORPS OF ENGINEERS  
BIRCH HILL DAM  
ROYALSTON, MA  
Performance Work Statement  
Informational Photos**



**Informational Photo 7:** West Side Painted Roof Trim and Window Frame



**GARAGE DEMOLITION  
U.S. ARMY CORPS OF ENGINEERS  
BIRCH HILL DAM  
ROYALSTON, MA  
Performance Work Statement**

**Informational Photos**



**Informational Photo 8: West Side Painted Window Frame**



**GARAGE DEMOLITION  
U.S. ARMY CORPS OF ENGINEERS  
BIRCH HILL DAM  
ROYALSTON, MA  
Performance Work Statement  
April 2022**

**Informational Photos**



**Informational Photo 9: Garage Interior**