

Informational Maps/ Photos



Map 1: Image showing Mansfield Hollow Dam inlet area. Orange log boom (orange circle) and weir box structure (yellow circle) is visible in bottom left of image.



Map 2: Image showing access road leading to debris removal area. Yellow line indicates USACE access gate (combination will be provided at contract award), blue square indicates project office and orange line indicates road access to debris removal site.



Map 3: Image showing working area where crane is proposed to be staged. 90 ft crane is recommended due to natural working pad location.



Image 1: Image showing current condition of log boom and weir box structures. Most of the debris is located at the left side of the log boom structure and debris on weir boxes is exclusively on the top of them (15ft from the bottom of the dam structure).



Image 2: Image showing current condition of log boom structure. Most of the debris present is small (3-5ft. in length) with one or two full sized trees stuck to the structure.



Image 3: Image showing current condition of weir box structures. Most of the debris present is larger, full-size trees (10-15+ ft.) stuck on top of the weir box structures.