

**REPORT OF CHANNEL CONDITIONS
LESS THAN 100 FEET WIDE
(ER 1130-2-520)**

DATE: **April 25, 2014**

<p>T0: NAVIGATION INTEREST</p>	<p>FROM:</p>
---------------------------------------	--------------

<p>RIVER/HARBOR NAME AND STATE: Connecticut River below Hartford, Connecticut Dwg. No. CRB-1025, Sheet(s) 1-2 of 2, Dated 25 April 2014</p>	<p>MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD</p>
-------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			DEPTH AVAILABLE
		WIDTH (feet)	LENGTH (Nautical miles)	MLLW DEPTH (feet)	
<p><u>PARTIAL CONDITION SURVEY</u></p> <p><u>Eight Mile River 8-Foot Channel</u></p> <p>From about 20' seaward of Buoy GC-1 upstream 2,055' to naturally deep area (about 160' upstream of Buoy GC-7)</p>	8/13	75	.34	8.0	(1) 7.9

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 5.8' within 35' of channel limits. Previous results (July 2009), which included coverage not available on this survey, show an available depth of 7.2' with shoaling to 5.7' within 10' of south limit and shoaling to 6.3' within 5' of north limit.