

**REPORT OF CHANNEL CONDITIONS  
LESS THAN 100 FEET WIDE  
(ER 1130-2-520)**

DATE: **April 23, 2014**

<p>T0: <b>NAVIGATION INTEREST</b></p>	<p>FROM:</p>
---------------------------------------	--------------

<p>RIVER/HARBOR NAME AND STATE: Wethersfield Cove, Connecticut River Below Hartford, CT; Dwg. No. CRB-1026, Sheet 1 of 1, Dated 23 April 2014</p>	<p>MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD</p>
---	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			DEPTH AVAILABLE
		WIDTH (feet)	LENGTH (Nautical miles)	MLLW DEPTH (feet)	
<b><u>AFTER-DREDGE SURVEY</u></b>					
<b><u>6-Foot Channel</u></b>					
From about 35' seaward of R Bn-2 upstream 1,860' to anchorage (about 320' upstream of R Bn-4)	4/14	60 to 100	0.31	6.0	(1) 5.0
<b><u>6-Foot Anchorage</u></b>					
	4/14	1,300 x 1,050	29.2 acres	6.0	(2) 6.0

**GENERAL NOTE:** The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

**FOOT NOTES:**

- (1). Except for shoaling to 2.9' within 15' of channel limit in vicinity of Interstate 91 Bridge.
- (2). Except for shoaling to 5.8' within 40' along southwest anchorage limit and shoaling to 5.3' within 40' of the 6-foot channel.