

**REPORT OF CHANNEL CONDITIONS  
100 TO 400 FEET WIDE  
(ER 1130-2-520)**

PAGE 1 OF 1 PAGE

DATE: **December 21, 2016**

**TO: NAVIGATION INTEREST**

**FROM:**

RIVER/HARBOR NAME AND STATE: Aunt Lydia's Cove, Chatham, Massachusetts  
Dwg. No. AUN-18, Sheets 1-5 of 5, Dated 21 December 2016

MINIMUM DEPTHS IN  
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)			
<p><b><u>CONDITION SURVEY</u></b></p> <p><b><u>8-Foot Channel</u></b></p> <p>From the start of the 8-Foot Channel upstream about 1,500' to the end of channel</p>	11/16	100	.25	8.0	(1) 7.0	7.0	7.2
<p><b><u>8-Foot Anchorage</u></b></p> <p>From the end of the 8-Foot Channel upstream 1,470' to upstream end of 8-Foot Anchorage</p>	11/16	190 to 300	8.7 acres	8.0		(2) 2.1	

**GENERAL NOTE:** The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

**FOOT NOTES:**

- (1). Except for shoaling to 6.0' within 5' of limit.
- (2). Except for shoaling to 1.7' within 20' of east limit, and shoaling to 1.0' within 140' of north end of limit.