

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

PAGE 1 OF 1 PAGE(S)

DATE: **March 1, 2017**

TO: **NAVIGATION INTEREST**

FROM:

RIVER/HARBOR NAME AND STATE: Beals Harbor, Beals, Maine
Dwg. No. BEA-2764, Sheet 1 of 1, Dated 1 March 2017

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)			
<u>AFTER DREDGE SURVEY</u>							
<u>10-Foot Anchorage</u>	02/17		11.1 acres	10.0		(1) 7.2	

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

(1). Except for shoaling to 5.3' within 120' along western limit; shoaling to 5.9' within 10' along southern and eastern limits; Project not dredged to grade due to widespread ledge reported by Contractor during 2017 dredging.