

REPORT OF SOILS FIELD COMPACTION TESTING

CLIENT: Ludlow Construction Co., Inc.

> 19 Carmelina's Circle Ludlow, MA 01056 Attn: Mr. Mike Pio

PROJECT: **Durham Meadows Waterline**

Durham, CT

DATE: August 28, 2020

REPORT #: 19-75-012-095 Page 1 of 1

General Location: South Main Street (Route 17)

Field Rep: **Hunter Davis**

General Contractor: Ludlow Construction Co., Inc. **Earthwork Contractor:** Ludlow Construction Co., Inc.

Air Temp: 82°F

Weather: Partly Cloudy Soil ID#: 3519-608

Soil Type: Light gray gravel with silt and sand

Proctor Sample Source: Haynes Group

lbs/ft³ **Proctor Value:** 138.9 **Optimum Moisture:** 7.8%

Troxler 3430 **Gauge Type: Required Compaction:** 95.0%

6 , p				
TEST	DEPTH/ELEV.	MOISTURE	DRY DENSITY	COMPACTION
NUMBER	(in/ft)	(%)	(pcf)	(%)
1	8"/ 4" BFG	2.1%	141.7	100.0+
LOCATION:	Station #939+50			
2	8"/ 4" BFG	2.4%	136.5	98.3%
LOCATION:	Station #939+50			
3	8"/ 4" BFG	1.7%	133.9	96.4%
LOCATION:	Station #938+00			
4	8"/ 4" BFG	2.2%	134.1	96.5%
LOCATION:	Station #938+00			
LOCATION:				
LOCATION:				
LOCATION:				
LOCATION:				

REMARKS: BFG - Below Finish Grade