

REPORT OF SHOTCRETE FIELD & LABORATORY TESTING

REPORT #:

CLIENT: PROJECT: **DN Tanks** Middletown CT

11 Teal Road

Wakefield, MA 01880 Attn: Mr. Jake Sreca

20-07-161-018

Middletown, CT

224 Talcott Ridge Drive

Page 1 of 1

October 19, 2020 **General Location:** Tank Exterior

DATE:

Specific Location: Exterior Side Panels Field Representative: **Gregory Vachon General Contractor:** DN Tanks, Inc. Supplier: CT Ready Mix

Yards Placed: **Design Strength** 4500 7.0 yards³

Date Cast: 10/12/2020 **Date Received:** 10/13/2020

Air Temperature: 58°F

Weather: Cloudy w/ Light Rain

TICKET #	SHOTCRETE	SLUMP TEST (in)	AIR CONTENT (%)	TEMPERATURE (°F)	ELAPSED TIME		
	PANEL #	(ASTM C143)	(ASTM C231)	(ASTM C1064)	BATCH	FINAL	TOTAL (MIN)
1009033	1	0.50"	5.90%	68°F	1:15 PM	4:00 PM	165

*Specimens conditioned in accordance with ASTM C42

LABORATORY COMPRESSIVE STRENGTH TESTING ASTM C39

Specimen #	Date Tested	Age (days)	Area (in²)	Load (lbs)	Strength (psi)	Average Strength (psi)
1	10/19/20	7	9.00	35290	3920	
2	10/19/20	7	9.00	36980	4110	4210
3	10/19/20	7	9.00	41520	4610	
4	11/09/20	28				
5	11/09/20	28				
6	11/09/20	28				
7		Hold				
8		Hold				
9		Hold				

REMARKS: Mix E

Reviewed By:	Dariene Danieis
_	