CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION PROJECT Durham Meadows Waterline Remedial Design REPORT NUMBER 552 DATE 22 Jun 2020 - Monday CONTRACT NUMBER W912WJ19C0002

WEATHER

Weather Caused No Delay Temperature Min 68 °F Max 93 °F No Precipitation 7 MPH Wind

QC NARRATIVES

JOB SAFETY

SAFETY:

Crews arrived at 7:00am, Departed at 3:00pm

*SSHO Rob Peddicord:

Ludlow Construction Co., Inc.

*Monitored 3 main crews production activities: Jonathon Pio, Billy DaCRuz, Quincy Cope foremen

*Jonathon Pio's crew: Installing pipe at Maiden Lane and Rt 17

*2 State Patrol for traffic control

*Billy DaCruz crew back at Water Tank area, placing fill material

*Quincy Cope crew installing pipe on Maiden Lane

*2 certified flaggers as traffic control. (Certs on record)

*1 Laborer pressurizing pipe on Pickett Lane

*Borrow/Dump Yard: 1 Operator loading dumps with trench backfill material; maintaining waste piles

*Performed daily checklist inspections on Daily Report; Crews wearing all required PPE, Following Trench Safety, Crews alert of surroundings. Safety in compliance with EM 385-1-1. COVID-19 precautions being followed. (SEE Attached Ludlow SSHO Daily PDF

Report)

*Checked dumptruck haul roads for debris.

*Checked silt fencing for SWPP; no ruptures

*Office work: The SSHO continued collecting and filing crew paperwork for Lift Plans, Confined Spaces, and Daily Equipment Inspections (See Lift Plan PDFs attached to RMS).

TESTS REQUIRED BY SPECIFICATIONS, PERFORMED, AND THE RESULTS

Compaction Tests on Maiden Lane;.

Pressure Testing on 17; Started at STA 195+26.5, Ended at STA 209+25; Test Started at 12:45 PM and Ended at 2:34 PM: 150 Pounds Held. Test Passed.

WORK PERFORMED TODAY

WORK PERFORMED TODAY Onsite 7:00 AM; Offsite 3:00 PM PERSONAL; Project Manager 1 Superintendent 6 Operators 5 Labors 11 Truck Drivers 6

VISITERS:

SUBCONTRACTORS ON SITE:

Police Officers = 2 Flagger = 2 WORK COMPLETED;

12" DI Pipe: 265 Feet of 12 Inch Pipe at STA 417+55 TO STA 416+05

12" DI Restrained Pipe: 114 Feet of TR Flex Pipe at STA 400+00 TO STA 400+74/ STA 413+53 TO STA 413+13

Water Service Corp: 3 - 1" Water Service Corp at STA 415+10, STA 414+72, STA 413+36

Bank Run Gravel: 43.38 CYs Bank Run Gravel

Saw Cut= 122 Feet of Saw Cut on State Roads 17

Saw Cut= 610 Feet of Saw Cut in Town Roads

Water Tank Access Road; Fill was placed. Equipment was moved back to Water Tank Area.

Pressure Test was performed on Water Line today. Test Passed.

		REPORT NUMBER		D 0 11	
CONTRACTORS OUA	ALITY CONTROL REPORT (QCR)	552		Page 2 of 4	
	OF CONSTRUCTION	DATE			
		22 Jun 2020 -	- Monday	/	
PROJECT		CONTRACT NUMBER			
Durham Meadows Waterlin	ne Remedial Design	W912WJ19C			
QA/QC:	ne remedia Beoign	VV312VV013O			
QA Kurt Mintell and QA Bob was corrected and resent.	Christie spoke with QC Jerry Brandon about Ti	hursday's Report being r	eturned for	r corrections. F	Report
PROJECT LAISON COORDINA					
PREP/INITIAL DATES	(Preparatory and initial dates held and ad	vance notice)			
Preparatory Inspections held toda					
No preparatory inspections	s neid today				
Initial Inspections held today					
No initial inspections held t	today				
ACTIVITY START/FINISH					
Activity No Description					
No activities were started o	r finished today				
QC REQUIREMENTS					
Requirement No Type	Description			Results	
CT-00168 QC Test	Pressure Testing on 17; Started at STA			Awaiting	Results
	Test Started at 12:45 PM and Ended at Passed.	2:34 PM: 150 Pounds He	eld. Test		
ISSUED QA/QC DEFICIENCY		s issued)			
	,	,			
Item No Location	Description				
No QC Deficiency items we	·				
	re issued today	corrected)			
No QC Deficiency items we	re issued today ENCY (Report QC and QA Deficiency items	corrected)			
No QC Deficiency items we	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today	, , , , , , , , , , , , , , , , , , ,			
No QC Deficiency items were CORRECTED QA/QC DEFICIENT Item No Location No QC Deficiency items were	re issued today ENCY (Report QC and QA Deficiency items Description	, , , , , , , , , , , , , , , , , , ,			
No QC Deficiency items were CORRECTED QA/QC DEFICIENT Item No Location	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today	, , , , , , , , , , , , , , , , , , ,		Last Day	
No QC Deficiency items were CORRECTED QA/QC DEFICIENT Item No Location No QC Deficiency items were CONTRACTORS ON SITE	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today	ere on site)		Last Day	
No QC Deficiency items were CORRECTED QA/QC DEFICIENT Item No Location No QC Deficiency items were CONTRACTORS ON SITE	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we	ere on site)		Last Day	
No QC Deficiency items were CORRECTED QA/QC DEFICIENT IN THE Location No QC Deficiency items were CONTRACTORS ON SITE Name	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we	ere on site)			Hours
No QC Deficiency items were CORRECTED QA/QC DEFICIENT ITEM NO Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we	ere on site)		Last Day Number of Employees	Hours Worked
No QC Deficiency items were CORRECTED QA/QC DEFICIENT ITEM No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire LABOR HOURS	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we rest or last day on the site	ere on site)		Number of	Worked
No QC Deficiency items were CORRECTED QA/QC DEFICIENT ITEM No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire LABOR HOURS Employer	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we rest or last day on the site Labor Classification	ere on site)		Number of Employees	Worked
No QC Deficiency items were CORRECTED QA/QC DEFICIENT ITEM NO Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire LABOR HOURS Employer Ludlow Construction Co., Inc.	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we rest or last day on the site Labor Classification TRUCK DRIVER, GROUP 1	ere on site)		Number of Employees 6.0	Worked 48.0
No QC Deficiency items were CORRECTED QA/QC DEFICIENT Item No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire LABOR HOURS Employer Ludlow Construction Co., Inc. Ludlow Construction Co., Inc.	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we rest or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1	ere on site)		Number of Employees 6.0 11.0	Worked 48.0 88.0
No QC Deficiency items were CORRECTED QA/QC DEFICIENT ITEM No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire LABOR HOURS Employer Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc.	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we rest or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR	ere on site)		Number of Employees 6.0 11.0 0.0	Worked 48.0 88.0 8.0
No QC Deficiency items were CORRECTED QA/QC DEFICIENT Item No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire LABOR HOURS Employer Ludlow Construction Co., Inc.	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we rest or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER	ere on site)		Number of Employees 6.0 11.0 0.0 1.0	Worked 48.0 88.0 8.0 8.0
No QC Deficiency items were CORRECTED QA/QC DEFICIENT Item No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire LABOR HOURS Employer Ludlow Construction Co., Inc.	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we rest or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER OPERATOR HEAVY EQUIPMENT 1 SSHO	ere on site)		Number of Employees 6.0 11.0 0.0 1.0 5.0 1.0	Worked 48.0 88.0 8.0 8.0 40.0 8.0
No QC Deficiency items were CORRECTED QA/QC DEFICIENT Item No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire LABOR HOURS Employer Ludlow Construction Co., Inc.	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we rest or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER OPERATOR HEAVY EQUIPMENT 1 SSHO QUALITY CONTROL SYSTEM MGR	ere on site)		Number of Employees 6.0 11.0 0.0 1.0 5.0 1.0 1.0	Worked 48.0 88.0 8.0 8.0 40.0 8.0 8.0
No QC Deficiency items were CORRECTED QA/QC DEFICIENT Item No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire LABOR HOURS Employer Ludlow Construction Co., Inc.	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we ret or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER OPERATOR HEAVY EQUIPMENT 1 SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR	ere on site)		Number of Employees 6.0 11.0 0.0 1.0 5.0 1.0	Worked 48.0 88.0 8.0 8.0 40.0 8.0
No QC Deficiency items were CORRECTED QA/QC DEFICIENT Item No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire LABOR HOURS Employer Ludlow Construction Co., Inc. Vellieux Sawcutting Total hrs worked to date:	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we ret or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER OPERATOR HEAVY EQUIPMENT 1 SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR	ere on site) First Day		Number of Employees 6.0 11.0 0.0 1.0 5.0 1.0 1.0 8.0	Worked 48.0 88.0 8.0 40.0 8.0 8.0 0.0
No QC Deficiency items were CORRECTED QA/QC DEFICIENT Item No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire LABOR HOURS Employer Ludlow Construction Co., Inc. Vellieux Sawcutting	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we ret or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER OPERATOR HEAVY EQUIPMENT 1 SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR	ere on site) First Day		Number of Employees 6.0 11.0 0.0 1.0 5.0 1.0 1.0 8.0	Worked 48.0 88.0 8.0 8.0 40.0 8.0 8.0 0.0
No QC Deficiency items were CORRECTED QA/QC DEFICIENT Item No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire LABOR HOURS Employer Ludlow Construction Co., Inc. Vellieux Sawcutting Total hrs worked to date: EQUIPMENT HOURS Serial Number	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we rest or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER OPERATOR HEAVY EQUIPMENT 1 SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR 19,344.5 Hrs worked MTD:	ere on site) First Day		Number of Employees 6.0 11.0 0.0 1.0 5.0 1.0 8.0 33.0 Idle Hours	Worked 48.0 88.0 8.0 8.0 40.0 8.0 208.0 Operating Hours
No QC Deficiency items were CORRECTED QA/QC DEFICIENT Item No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their fire LABOR HOURS Employer Ludlow Construction Co., Inc. Vellieux Sawcutting Total hrs worked to date:	re issued today ENCY (Report QC and QA Deficiency items Description re corrected today (Report first and/or last day contractors we rest or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER OPERATOR HEAVY EQUIPMENT 1 SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR 19,344.5 Hrs worked MTD:	ere on site) First Day		Number of Employees 6.0 11.0 0.0 1.0 5.0 1.0 8.0 33.0	Worked 48.0 88.0 8.0 8.0 40.0 8.0 0.0 208.0

CONTRACTORS	NIALITY CONTROL REPORT (OCR)	REPORT NUMBER Page 3 of 4			
	QUALITY CONTROL REPORT (QCR) LOG OF CONSTRUCTION	DATE			
		22 Jun 2020 - Monday			
ROJECT		CONTRACT NUMBER			
Durham Meadows Waterline Remedial Design		W912WJ19C0002			
E-4 0336FCRAB	E-4 Cat 336 Track Hoe Jon		8.0	0.0	
T-36	Dump Truck T-36 Jon		0.0	8.0	
B-5	Sweeper B-5 Billy		8.0	0.0	
E-20 ECR145DL,	E-20 Volvo Excavator E-20 Jon		0.0	8.0	
E-19 Cat	E-19 Cat 314C Trackhoe Quincy		0.0	8.0	
T-50	T-50 PU Jon		0.0	8.0	
T-46	T- 46 Saw Truck		8.0	0.0	
T-77 PU	T-77 PU Billy		0.0	8.0	
T-27 Dump	T-27 Dump Quincy		0.0	8.0	
E-9 Track Hoe	E-9 336 Track Hoe Billy		6.0	2.0	
T-60	Dump Truck T-60 Jon		0.0	8.0	
T-64	Dump Truck T-64		8.0	0.0	
B-5 Sweeper	B-5 Sweeper Jon		4.0	4.0	
R-4 Roller Billy	Roller Compacter Billy		8.0	0.0	
TE 15 Excavator	TE-15 Track Hoe Billy		8.0	0.0	
T-84 PU	T-84 PU Billy		0.0	8.0	
T-78 PU	T-78 PU Jon		6.0	2.0	
L-18 950	L-18 Loader Jon		0.0	8.0	
R-18 Roller	R-18 Compactor JON		4.0	4.0	
D1 Cat	D-1 Cat D-5 Dozer Billy		0.0	8.0	
T-86	T-86 Dump Truck Billy		8.0	0.0	
T-21 Dump	T-21 Dump Jon		8.0	0.0	
R-17 Roller	R-17 Roller Billy		6.0	2.0	
G-3 Volvo Grader	G-3 Road Grader OFF SITE		8.0	0.0	
T-59 Dump	T-59 Dump Billy		0.0	8.0	
TE-13 Excavator	TE-13 EX Billy		8.0	0.0	
PV-1 Paver	PV-1 Paver Billy		8.0	0.0	
E-18 EX	E-18 EX Quincy		8.0	0.0	
L-11 Load	L-11 Load Quincy		0.0	8.0	
R-11 Roller	R-11 Roller Quincy		0.0	8.0	
B-7 Sweep	B-7 Sweep Quincy		4.0	4.0	
T-80 Dump	T-80 Dump Quincy		8.0	0.0	
T-13 Dump Truck	T-13 Dump Quincy		0.0	8.0	
T-31 PU Work	T-31 PU Quincy		0.0	8.0	
T-15 Pick Up	T-15 PU Quincy		6.0	2.0	
T-65 Pick UP	T-65 PU Quincy		8.0	0.0	
T-74 Pick UP	T-74 PU Quincy		8.0	0.0	
T-41	Ludlow Pressure Test Truck T-41 Billy		8.0	0.0	
Total operating hrs to date:		r hrs MTD: 2,424.0 T	otal: 172.0	148.0	

	ALITY CONTROL REP		REPORT NUMBER	Dogo	1 of 1
CONTRACTORS QUA		PORT (QCR)	552	rage	4 of 4
DAILY LOG OF CONSTR		TION	DATE		
2721 20					
PROJECT			22 Jun 2020 - Monday CONTRACT NUMBER		
	na Damadial Dagian				
Durham Meadows Waterli	ne Remediai Design		W912WJ19C0002		
CONTRACTOR CERTIFICATION	On hehalf of the sent	actor I cortify that the	is Panart is complete and as	orrect and	I all aquinment and
SOME STATE OF THE	material used and wor	actor, i certify that thi k performed during th	is Report is complete and conis Reporting period are in o	omplianc	e with the contract
	plans and specification	s, to the best of my kno	owledge, except as noted abo	ve.	
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE
		ı			i