REPORT NUMBER Page 1 of 3 576 **CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION** DATE 16 Jul 2020 - Thursday **PROJECT CONTRACT NUMBER** W912WJ19C0002 Durham Meadows Waterline Remedial Design **WEATHER** Ludlow Construction Co., Inc. Weather Caused No Delay Temperature Min 64 °F Max 83 °F No Precipitation 9 MPH Wind

QC NARRATIVES

JOB SAFETY

SAFETY:

Crews arrived at 7:00am, Departed at 3:00pm

*SSHO Rob Peddicord:

- *Monitored 2 main crews production activities: Jonathon Pio, Billy DaCRuz, foremen
- *Jonathon Pio's crew: Continued 2nd Stream Crossing at Pickett Lane; approx stations 531+50 to 532+50
- * ENVIRONMENTAL: Spill kits, barrels on hand. Two silt pits used; constructed of hay bails, sand bags, and gravel placed atop filter fabric. Frack Tank also utilized.
- *One certified flagger for traffic control. (LC labor. Certs on record)
- *Billy DaCruz crew at Rt 17, installing Water Services
- *1 State Patrol and 1 CTC flagger for traffic control (CTC cert on record)
- *Borrow/Dump Yard: 1 Operator loading dumps with trench backfill material; maintaining waste piles
- *1 Labor checking chlorine samples and flushing the line.
- *Performed daily checklist inspections on Daily Report; Crews wearing all required PPE, Following Trench Safety, Crews alert of surroundings. Safety in compliance with EM 385-1-1. COVID-19 precautions being followed. (SEE Attached Ludlow SSHO Daily **PDF**

Report, with attached photos)

- *Checked dumptruck haul roads for debris.
- *Checked silt fencing for SWPP; no ruptures.
- *Office work: The SSHO continued collecting and filing crew paperwork for Lift Plans, AHAs, and Daily Equipment Inspections (See Lift Plan PDFs attached to RMS).
- *DN Tanks Proj Mgr on site, mobilizing some supplies and equipment to site.
- *In continued communication with Scott Scorpa of DN Tanks at Water Tank site. SSHO received Site Orientation, Covid Orientation, Emergency Contacts for 2 new crew members. Received Equipment Initial Inspection sheet for Skytrack forklift
- *Weekly Progress Meeting

TESTS REQUIRED BY SPECIFICATIONS, PERFORMED, AND THE RESULTS

Chlorine Samples were taken on Rt 17 Main Waterline:

Compaction Tests were taken at 360 Main Street

WORK PERFORMED TODAY

WORK PERFORMED TODAY Onsite 7:00 AM; Offsite 3:00 PM

PERSONAL; Project Manager 1 Superintendent 5 Operators 5 Labors 9 Truck Drivers 3

VISITERS:

SUBCONTRACTORS ON SITE:

Turner = 1DT Tanks = 3 Police: 1 Cert Flaggers = 1

Flagger = 1

WORK COMPLETED;

REPORT NUMBER Page 2 of 3 576 **CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION** DATE 16 Jul 2020 - Thursday CONTRACT NUMBER **PROJECT** W912WJ19C0002 Durham Meadows Waterline Remedial Design JON'S Crew: Jon's Crew Continued with STA 530+50 to STA 533+00 Stream Crossing on Pickett Lane. BILLY's Crew: Water Service 1" Corp; Water Service 1" Curb Stops; 2 - 1 Inch Curb Stops were installed STA 164+50 and STA 167+20 Water Service 1" Copper Line; 101 Feet of Copper Line was Installed. Bank Run Gravel; 18.44 CY's was installed. Saw Cut: 98 Feet of Saw Cut in State Roads Water Tank Installation: Continue bringing in Material and Shooting Elevations. Rebar was Brought in and unloaded. Chlorine Samples were taken on Rt 17 Main Water Line. QA/QC: PROJECT LAISON COORDINATOR: Job Narrative: Prepared for the Weekly Progress Meeting. Weekly Progress Meeting. Daily site visit to the stream crossing on Pickett Lane. Started on the minutes of the Weekly Progress Meeting. Went out to Billy's jobsite and notified the businesses that will have the services installed tomorrow, Friday. July 17th. Notified Liberty Bank, The Red Barn and the Mobil Station of the work scheduled for tomorrow, Friday, July 17th. PREP/INITIAL DATES (Preparatory and initial dates held and advance notice) Preparatory Inspections held today No preparatory inspections held today Initial Inspections held today No initial inspections held today **ACTIVITY START/FINISH** Activity No Description No activities were started or finished today **QC REQUIREMENTS** Requirement No Description Results Type CT-00182 QC Test Awaiting Results Chlorine Tests were taken on Main Line on RT 17: Failed CT-00183 QC Test Awaiting Results Tests were taken at 360 Main Street: Waiting for Results **ISSUED QA/QC DEFICIENCY** (Describe QA and QC Deficiency items issued) Item No Location Description No QC Deficiency items were issued today **CORRECTED QA/QC DEFICIENCY** (Report QC and QA Deficiency items corrected) Item No Location Description No QC Deficiency items were corrected today **CONTRACTORS ON SITE** (Report first and/or last day contractors were on site) Name First Day Last Day No Contractors had their first or last day on the site **LABOR HOURS** Number of Hours

Employees

Worked

Employer

Labor Classification

CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION				REPORT NUMBER 576	Pa	ge 3 of 3	
				DATE	urodov		
PROJECT				16 Jul 2020 - Th	ursaay		
Durham Meadows Waterline Remedial Design				W912WJ19C000)2		
Ludlow Construction Co., Inc.	TRUCK DRIVER, GF	ROUP 1			-	3.0	24.0
Ludlow Construction Co., Inc.	LABORER, GROUP	1				9.0	72.0
Ludlow Construction Co., Inc.	CIRCULAR SAW OP	ERATOR				0.0	0.0
Ludlow Construction Co., Inc.	PROJECT MANAGE	R				0.0	0.0
Ludlow Construction Co., Inc.	OPERATOR HEAVY	EQUIPMENT 1				5.0	40.0
Ludlow Construction Co., Inc.	SSHO					1.0	8.0
Ludlow Construction Co., Inc.	QUALITY CONTROL	SYSTEM MGR				1.0	8.0
Vellieux Sawcutting	CIRCULAR SAW OP	ERATOR				0.0	0.0
Total hrs worked to date:	22,056.5 Hrs	s worked MTD:	1,640.	0 To	tal:	19.0	152.0
EQUIPMENT HOURS						Idla	Operating
Serial Number	Description					Idle Hours	Operating Hours
L-20	L-20 Kumatsu Front End	Loader Billy				4.0	4.0
TE-6 Ex	TE-6 Volvo J	on				6.0	2.0
E-4 0336FCRAB	E-4 Cat 336 Track Hoe	Jon				0.0	8.0
T-36	Dump Truck T-36	Jon				8.0	0.0
B-5	Sweeper B-5	Billy				6.0	2.0
E-20 ECR145DL,	E-20 Volvo Excavator E-2	20 Jon				0.0	8.0
T-50	T-50 PU	Jon				4.0	4.0
T-77 PU	T-77 PU	Billy				4.0	4.0
E-9 Track Hoe	E-9 336 Track Hoe	Billy				8.0	0.0
T-64	Dump Truck T-64					8.0	0.0
B-5 Sweeper	B-5 Sweeper	Jon				4.0	4.0
R-4 Roller Billy	Roller Compacter	Billy				4.0	4.0
TE 15 Excavator	TE-15 Track Hoe	Billy				4.0	4.0
T-84 PU	T-84 PU	Billy				0.0	8.0
T-78 PU	T-78 PU J	on				6.0	2.0
L-18 950	L-18 Loader	Jon				4.0	4.0
R-18 Roller	R-18 Compactor JC	DN				4.0	4.0
D1 Cat	D-1 Cat D-5 Dozer	Billy				8.0	0.0
T-86	T-86 Dump Truck	Billy				0.0	8.0
T-21 Dump	T-21 Dump Jo	n				8.0	0.0
R-17 Roller	R-17 Roller Billy					8.0	0.0
T-59 Dump	T-59 Dump Bi	illy				8.0	0.0
TE-13 Excavator	TE-13 EX	Billy				8.0	0.0
T-41	Ludlow Pressure Test Tru	uck T-41 Billy				8.0	0.0
Total operating hrs to date:	18,677.5 Idle hrs MT	D: 1,374.0 C	Opr hrs M	ITD: 818.0	Total:	122.0	70.0
MISHAP REPORTING	(Describe mishaps))					
No mishaps reported toda	ау						
CONTRACTOR CERTIFICATION	On behalf of the contr	actor I cortify that	t thic P	anort is complete on	d correct	and all on	uinment and
	material used and wor plans and specification	k performed durin	g this F	Reporting period are	in complia		
QC REPRESENTATIVE'S SIGNATUI	RE	DATE	S	JPERINTENDENT'S INIT	ALS	DATE	