CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION		REPORT NUMBER Page 1 of 3  594  DATE			
		03 Aug 2020 - Mond	ay		
PROJECT		CONTRACT NUMBER			
Durham Meadows Waterline Remedial Design		W912WJ19C0002			
CONTRACTOR	WEATHER				
Ludlow Construction Co., Inc.	•	sed No Delay Min 76°F Max 91°F Sipitation 9 MPH Wind			

### **QC NARRATIVES**

# JOB SAFETY

SAFETY:

Crews arrived at 7:00am, Departed at 3:00-3:30pm

- \*SSHO Rob Peddicord:
- \*Monitored 2 main crews production activities; Foremen Jonathon Pio and Billy DaCRuz,
- \*Monitored DN Tanks activities at the Water Tank, Foreman Al Kendall
- \*Jonathon Pio's crew: Continued Streamcrossing #3 at Maple Ave
- \*1 Labor flagger, (Certs on record) Road Closed signs at both ends of Maple, additional one in the middle White Farm entrance intersection, additional one at Rt 17/Old Cemetery Rd

PROGRESS: Pipe has been installed into both creek bank, out of the streambed. Streambed and creekbanks reconstructed.

- \*Billy DaCruz crew at Rt 17, Installing Water Services
- \*1 State Patrol, 1 CTC tech for traffic control (Cert on record)
- \*Borrow/Dump Yard: 1 Operator loading dumps with trench backfill material; maintaining waste piles
- \*Performed daily checklist inspections on Daily Report; Crews wearing all required PPE, Following Trench Safety, Crews alert of surroundings. Safety in compliance with EM 385-1-1. COVID-19 precautions being followed. (SEE Attached Ludlow SSHO Daily PDF

Report, with attached pics)

- \*Checked dumptruck haul roads for debris.
- \*Checked silt fencing for SWPP; no ruptures.
- \*Office work: The SSHO continued collecting and filing crew paperwork for Lift Plans, AHAs, and Daily Equipment Inspections (See Lift Plan PDFs attached to RMS).
- \*Received daily reports from DN Tanks; COVID self cert, SSHO Daily Report, Weekly Safety Meeting
- \*Received paperwork for 2 new crewman from DN Tanks: Site Orientation, Covid Orientation, Emergency Contact

# SAFETY INSPECTION (Report violations, corrective instruction/action taken):

CONCERN: Pedestrians ignored "Sidewalk Closed" signs, and walked through the area of Crew #2 while they were installing Water Services. The SSHO investigated after being notified by USACE rep, Kurt Mintell. The crew was instructed to be more cognizant of pedestrians and to either deny them access, or personally guide them through the area. NOTE: a pickup truck was also parked as a barrier on the sidewlk

# **WORK PERFORMED TODAY**

WORK PERFORMED TODAY Onsite 7:00 AM; Offsite 3:30 PM

PERSONAL; Project Manager 1 Superintendent 5 Operators 5 Labors 9 Truck Drivers 4

VISITERS:

SUBCONTRACTORS ON SITE:

Police = 1 Cert Flaggers = 1 Flagger = 1

WORK COMPLETED;

JON'S Crew

46: PUT STREAM BACK TO ORGINAL CONDITIONS ON MAPLE LANE

BILLY's Crew:

Water Service 1" Curb Stop; 1 - 1 Inch Curb Stops was installed at STA 182+50

Water Service 1" Copper Line; 68.7 Feet of Copper Line was Installed.

# CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION PROJECT REPORT NUMBER 594 DATE 03 Aug 2020 - Monday CONTRACT NUMBER Page 2 of 3 594 CONTRACT NUMBER CONTRACT NUMBER Page 2 of 3 CONTRACT NUMBER

W912WJ19C0002

Rock and Boulder = 21.3 CY's

Saw Cut: 63.0 Feet of Saw Cut in State Roads

Durham Meadows Waterline Remedial Design

Water Tank Installation:

AL's Crew:

Building Wall Casting Beds.

Securing Material for Storm.

### QA/QC

QA Kurt Mintell Discussed with QC Jerry Brandon and HSSO Rob Peddicord the "side walk closed" signs that are being used on Rt 17 (or Main Street).

### PROJECT LAISON COORDINATOR:

Onsite with Billy's crew on Main Street installing water services. Installing Karen Keane's service. She was notified in advance on Friday, July 31, 2020.

Onsite with Jonathan's crew on Maple Avenue installing 12" Dip at the stream crossing.

PM:

Onsite at the tank site in Middletown and Main Street in Durham.

## **PREP/INITIAL DATES**

(Preparatory and initial dates held and advance notice)

Preparatory Inspections held today

# No preparatory inspections held today

Initial Inspections held today

# No initial inspections held today

### **ACTIVITY START/FINISH**

Activity No Description

# No activities were started or finished today

### **QC REQUIREMENTS**

Requirement No Type Description Results

### No QC requirements were completed today

## **ISSUED QA/QC DEFICIENCY**

(Describe QA and QC Deficiency items issued)

Item No Location Description

# No QC Deficiency items were issued today

# CORRECTED QA/QC DEFICIENCY

(Report QC and QA Deficiency items corrected)

Item No Location Description

### No QC Deficiency items were corrected today

**CONTRACTORS ON SITE** (Report first and/or last day contractors were on site)

Name First Day Last Day

# No Contractors had their first or last day on the site

LABOR HOURS Employer	Labor Classification	Number of Employees	Hours Worked
Ludlow Construction Co., Inc.	TRUCK DRIVER, GROUP 1	4.0	32.0
Ludlow Construction Co., Inc.	LABORER, GROUP 1	9.0	72.0
Ludlow Construction Co., Inc.	CIRCULAR SAW OPERATOR	0.0	0.0
Ludlow Construction Co., Inc.	PROJECT MANAGER	0.0	0.0
Ludlow Construction Co., Inc.	OPERATOR HEAVY EQUIPMENT 1	5.0	40.0
Ludlow Construction Co., Inc.	SSHO	1.0	8.0

			REPOR	T NUMBER	Do	ge 3 of 3	
CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION			594		га	y <del>c</del> o ui o	
			DATE				
			03 /	Aug 2020 - N	londay		
ROJECT			CONTR	CONTRACT NUMBER			
Durham Meadows Waterline Remedial Design			W9	12WJ19C00	)2		
Ludlow Construction Co., Inc.	QUALITY CON	TROL SYSTEM MGR	•			1.0	8.0
Vellieux Sawcutting	CIRCULAR SA	W OPERATOR				0.0	0.0
Total hrs worked to date:	23,904.5	Hrs worked MTD:	160.0	To	otal:	20.0	160.0
EQUIPMENT HOURS						Idle	Operating
Serial Number	Description					Hours	Hours
L-20	L-20 Kumatsu Fron	t End Loader Bill	у			4.0	4.0
TE-6 Ex	TE-6 Volvo	Jon				6.0	2.0
E-4 0336FCRAB	E-4 Cat 336 Track	Hoe Jon				4.0	4.0
T-36	Dump Truck T-36	Jon				8.0	0.0
B-5	Sweeper B-5	Billy				6.0	2.0
E-20 ECR145DL,	E-20 Volvo Excava	tor E-20 Jon				4.0	4.0
T-41	Ludlow Pressure Te	est Truck T-41 Billy				8.0	0.0
T-50	T-50 PU	Jon				4.0	4.0
T-77 PU	T-77 PU	Billy				4.0	4.0
E-9 Track Hoe	E-9 336 Track Ho	e Billy				8.0	0.0
T-64	Dump Truck T-64	·				8.0	0.0
B-5 Sweeper	B-5 Sweeper	Jon				4.0	4.0
R-4 Roller Billy	Roller Compacter	Billy				4.0	4.0
TE 15 Excavator	TE-15 Track Hoe	Billy				4.0	4.0
T-84 PU	T-84 PU	Billy				0.0	8.0
T-78 PU	T-78 PU	Jon				6.0	2.0
L-18 950	L-18 Loader	Jon				4.0	4.0
R-18 Roller	R-18 Compactor	JON				4.0	4.0
D1 Cat	D-1 Cat D-5 Dozer					8.0	0.0
T-86	T-86 Dump Truck	Billy				0.0	8.0
T-21 Dump	T-21 Dump	Jon				8.0	0.0
R-17 Roller	R-17 Roller	Billy				8.0	0.0
T-59 Dump	T-59 Dump	Billy				8.0	0.0
TE-13 Excavator	TE-13 EX	Billy				8.0	0.0
Total operating hrs to date:			Opr hrs MTD:	62.0	Total:	130.0	62.0
rotal operating in a to date.	10,000.0 Iuie II		opi inσ wild.	UZ.U	i otai.	100.0	02.0
MISHAP REPORTING	(Describe mis	shaps)					