REPORT NUMBER Page 1 of 3 595 CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION DATE 04 Aug 2020 - Tuesday PROJECT CONTRACT NUMBER W912WJ19C0002 Durham Meadows Waterline Remedial Design CONTRACTOR WEATHER Ludlow Construction Co., Inc. Weather Caused No Delay Temperature Min 70 °F Max 84 °F 0.05 IN Precipitation 36 MPH Wind **QC NARRATIVES** JOB SAFETY SAFETY: Crews arrived at 7:00am, Departed at 3:00-3:30pm *SSHO Rob Peddicord: *Monitored 2 main crews production activities; Foremen Jonathon Pio and Billy DaCRuz, *Monitored DN Tanks activities at the Water Tank; Foreman Al Kendall. NOTE: Only 2 people on site due to pending storms, no production work *Jonathon Pio's crew: Connecting Streamcrossing #3 at Maple Ave *1 Labor flagger, (Certs on record) Road Closed signs at both ends of Maple, additional one in the middle White Farm entrance intersection. additional one at Rt 17/Old Cemetery Rd PROGRESS: Pipe has been installed into both creek bank, out of the streambed. Streambed and creekbanks reconstructed. Now connecting south end of Streamcrossing to pipe beneath Maple Ave. *Billy DaCruz crew at Rt 17, Installing Water Services *2 CTC tech for traffic control (Certs on record) *Borrow/Dump Yard: 1 Operator loading dumps with trench backfill material; maintaining waste piles *1 Labor prepping DN Tanks pressure testing for inlet pipes *Performed daily checklist inspections on Daily Report; Crews wearing all required PPE, Following Trench Safety, Crews alert of surroundings. Safety in compliance with EM 385-1-1. COVID-19 precautions being followed. (SEE Attached Ludlow SSHO Daily PDF Report, with attached pics) *Checked dumptruck haul roads for debris. *Checked silt fencing for SWPP; no ruptures. *Office work: The SSHO continued collecting and filing crew paperwork for Lift Plans, AHAs, and Daily Equipment Inspections (See Lift Plan PDFs attached to RMS). *Received daily reports from DN Tanks; COVID self cert, SSHO Daily Report, WORK PERFORMED TODAY WORK PERFORMED TODAY Onsite 7:00 AM ; Offsite 3:30 PM PERSONAL; Project Manager 1 Superintendent 5 **Operators 5** Labors 9 **Truck Drivers 4** VISITERS: SUBCONTRACTORS ON SITE: Cert Flaggers = 3 Flagger = 1 WORK COMPLETED; JON'S Crew: 6: 246.5 FEET OF 12 INCH TR FLEX: STA 904+50 TO 902+03.5 22: 1 -12 INCH GATE VALVE: STA 904+49 46: FINISHED RUNNING PIPE ON THE DURHAM GROUND FAIR SIDE AND UP THE FIELD TOWARD THE ROAD. STA 904 + 69.5 TO 904+50 BILLY's Crew: Water Service 1" Curb Stop; 42.0 Feet of 1 Inch Curb Stops was installed at House Number 174. NOTE: (Tap is in the wrong place, A new tap will be installed to get the STA Numbers.)

Shem Cross Trenches on Rt 68

| | | REPORT NUMBER | Page 2 of 3 | | | |
|--|--|-------------------------------|-------------------|-----------------|--|--|
| CONTRACTORS QUA | LITY CONTROL REPORT (QCR) | 595 | Tage 2 010 | | | |
| DAILY LOG | OF CONSTRUCTION | DATE | | | | |
| | | 04 Aug 2020 - Tues | sday | | | |
| PROJECT | | CONTRACT NUMBER | | | | |
| Durham Meadows Waterlir | | W912WJ19C0002 | | | | |
| Help Jon's Crew on Maple Ave. | | | | | | |
| Water Tank Installation: | | | | | | |
| AL's Crew: Building Wall Casting Beds. | | | | | | |
| Securing Material for Storm. | | | | | | |
| QA/QC: | | | | | | |
| QA Kurt Mintell Discussed with 17 (or Main Street). | n QC Jerry Brandon and HSSO Rob Peddicord th | e "side walk closed" signs th | at are being used | on Rt | | |
| | | | | | | |
| PROJECT LAISON COORDIN | ATOR: | | | | | |
| PREP/INITIAL DATES | (Preparatory and initial dates held and advar | nce notice) | | | | |
| Preparatory Inspections held toda | • | | | | | |
| No preparatory inspections | held today | | | | | |
| Initial Inspections held today | | | | | | |
| No initial inspections held t | oday | | | | | |
| ACTIVITY START/FINISH | | | | | | |
| Activity No Description | | | | | | |
| | | | | | | |
| No activities were started o | r finished today | | | | | |
| QC REQUIREMENTS | | | | | | |
| Requirement No Type | Description Results | | | | | |
| | | | | | | |
| No QC requirements were c ISSUED QA/QC DEFICIENCY | | aquad) | | | | |
| | | ssued) | | | | |
| Item No Location | Description | | | | | |
| No QC Deficiency items we | ro issued today | | | | | |
| CORRECTED QA/QC DEFICIE | - | rrected) | | | | |
| Item No Location | Description | | | | | |
| Location | Description | | | | | |
| | | | | | | |
| No QC Deficiency items we | • | | | | | |
| CONTRACTORS ON SITE | (Report first and/or last day contractors were | e on site) | | | | |
| Name | | First Day | Last Day | | | |
| | | | | | | |
| No Contractors had their fir | st or last day on the site | | | | | |
| LABOR HOURS Employer | Labor Classification | | Number of | Hours Worked | | |
| Ludlow Construction Co., Inc. | TRUCK DRIVER, GROUP 1 | | Employees 4.0 | 32.0 | | |
| Ludlow Construction Co., Inc. | LABORER, GROUP 1 | | 9.0 | 72.0 | | |
| Ludlow Construction Co., Inc. | CIRCULAR SAW OPERATOR | | 0.0 | 0.0 | | |
| Ludlow Construction Co., Inc. | PROJECT MANAGER | | 0.0 | 0.0 | | |
| Ludlow Construction Co., Inc. | OPERATOR HEAVY EQUIPMENT 1 | | 5.0 | 40.0 | | |
| Ludlow Construction Co., Inc. | SSHO | | 1.0 | 8.0 | | |
| Ludlow Construction Co., Inc. | QUALITY CONTROL SYSTEM MGR | | 1.0 | 8.0 | | |
| Vellieux Sawcutting | CIRCULAR SAW OPERATOR | | 0.0 | 0.0 | | |
| . onoux outrouting | | | 0.0 | 5.0 | | |
| | | | | | | |

| CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION | | | REPOR | INUMBER | Page 3 of 3 | |
|---|-------------------|-----------------------|-------------------------------|-----------------------------|--------------|-----------|
| | | | 595 | | | |
| | OG OF CONSTR | | DATE 04 Aug 2020 - Tuesday | | | |
| ROJECT | | | | AUG 2020 - TU ACT NUMBER | esuay | |
| Durham Meadows Wate | arlina Romodial D | lesian | | 2WJ19C0002 |) | |
| Total hrs worked to date: | 24,064.5 | Hrs worked MTD: | 320.0 | Tota | | 160.0 |
| | 24,004.5 | This worked with. | 520.0 | TOLE | al. 20.0 | 100.0 |
| QUIPMENT HOURS | | | | | Idle | Operating |
| Serial Number | Description | | | | Hours | Hours |
| L-20 | L-20 Kumatsu Fr | ont End Loader Billy | | | 4.0 | 4.0 |
| TE-6 Ex | TE-6 Volvo | Jon | | | 6.0 | 2.0 |
| E-4 0336FCRAB | E-4 Cat 336 Tra | ck Hoe Jon | | | 4.0 | 4.0 |
| T-36 | Dump Truck T-36 | 6 Jon | | | 8.0 | 0.0 |
| B-5 | Sweeper B-5 | Billy | | | 6.0 | 2.0 |
| E-20 ECR145DL, | E-20 Volvo Exca | vator E-20 Jon | | | 4.0 | 4.0 |
| T-41 | Ludlow Pressure | Test Truck T-41 Billy | | | 8.0 | 0.0 |
| T-50 | T-50 PU | Jon | | | 4.0 | 4.0 |
| T-77 PU | T-77 PU | Billy | | | 4.0 | 4.0 |
| E-9 Track Hoe | E-9 336 Track H | loe Billy | | | 8.0 | 0.0 |
| T-64 | Dump Truck T-64 | 1 | | | 8.0 | 0.0 |
| B-5 Sweeper | B-5 Sweeper | Billy | | | 4.0 | 4.0 |
| R-4 Roller Billy | Roller Compacte | r Billy | | | 4.0 | 4.0 |
| TE 15 Excavator | TE-15 Track Hoe | - | | | 4.0 | 4.0 |
| T-84 PU | T-84 PU | Billy | | | 0.0 | 8.0 |
| T-78 PU | T-78 PU | Jon | | | 6.0 | 2.0 |
| L-18 950 | L-18 Loader | Jon | | | 4.0 | 4.0 |
| R-18 Roller | R-18 Compactor | JON | | | 4.0 | 4.0 |
| D1 Cat | D-1 Cat D-5 Doz | | | | 8.0 | 0.0 |
| T-86 | T-86 Dump Truc | - | | | 0.0 | 8.0 |
| T-21 Dump | T-21 Dump | Jon | | | 8.0 | 0.0 |
| R-17 Roller | R-17 Roller | Billy | | | 8.0 | 0.0 |
| T-59 Dump | T-59 Dump | Billy | | | 8.0 | 0.0 |
| TE-13 Excavator | TE-13 EX | Billy | | | 8.0 | 0.0 |
| Total operating hrs to date: | | | Opr hrs MTD: | 124.0 | Total: 130.0 | 62.0 |
| | , | | | _ | | |
| | | nishaps) | | | | |
| AISHAP REPORTING | (Describe r | | · | | | |