# CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION PROJECT Durham Meadows Waterline Remedial Design CONTRACTOR Ludlow Construction Co., Inc. REPORT NUMBER 611 DATE 20 Aug 2020 - Thursday CONTRACT NUMBER Weather Weather Weather Caused No Delay

Temperature Min 54 °F Max 81 °F No Precipitation 5 MPH Wind

#### **QC NARRATIVES**

#### JOB SAFETY

SAFETY:

Crews arrived at 7:00am, Departed at 3:00-3:30pm

\*SSHO Rob Peddicord:

- \*Monitored 2 Ludlow crews production activities; Foremen Jonathon Pio and Billy DaCRuz,
- \*Monitored DN Tanks activities at the Water Tank; Foreman Al Kendall.
- \*Jonathon Pio's crew: Installing Hydrants at Maple Ave
- \*1 Labor flagger, (Certs on record) Road Closed sign at north end of Maple, one at Rt 17/Old Cemetery Rd intersection
- \*Billy DaCruz crew on Rt 17, installing Water Services
- \*2 State Patrol, 1 CTC tech as traffic control (CTC certs on record)
- \*Borrow/Dump Yard: 1 Operator loading dumps with trench backfill material; maintaining waste pile
- \*DN TANKS: Poured 40cy of concrete for wall and roof panels
- \*Performed daily checklist inspections on Daily Report; Crews wearing all required PPE, Following Trench Safety, Crews alert of surroundings. Safety in compliance with EM 385-1-1. COVID-19 precautions being followed. (SEE Attached Ludlow SSHO Daily PDF Report)
- \*Checked dumptruck haul roads for debris.
- \*Checked silt fencing for SWPP; no ruptures. Some silt fence on Main St sagging after tropical storm winds
- \*Office work: The SSHO continued collecting and filing crew paperwork for Lift Plans, AHAs, and Daily Equipment Inspections (See Lift Plan PDFs attached to RMS).
- \*Received daily reports from DN Tanks; COVID self cert, SSHO Daily Report, Lift Plans for panel forms

# TESTS REQUIRED BY SPECIFICATIONS, PERFORMED, AND THE RESULTS

Slump Tests taken at Tank Site: Pour Walls and Dome Panels.

#### **WORK PERFORMED TODAY**

WORK PERFORMED TODAY Onsite 7:00 AM; Offsite 4:30 PM

PERSONAL; Project Mana

Project Manager 1 Superintendent 5 Operators 5 Labors 8 Truck Drivers 4

VISITERS:

SUBCONTRACTORS ON SITE:

Northern Steel - 4 DN Tanks - 5 Turner - 1 Police - 1 Cert Flagger - 2

WORK COMPLETED:

JON'S Crew:

26: 4 HYDRANT ASSEMBLIES INSTALLED: STA 916+40.5, STA 913+40, STA 906+88, AND STA 900+07.5

62: 16 FEET OF TOWN SAW CUT

BILLY's Crew:

Water Service 1-inch Curb Stops; 2 - 1 Inch Curb Stops at STA 192+50/ and 228 Main Street

Water Service 1-inch Copper Line: 101.2 Feet of Copper Line

Soil Piercing for Sidewalk: 8 Feet

# CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION PROJECT REPORT NUMBER 611 DATE 20 Aug 2020 - Thursday CONTRACT NUMBER CONTRACT NUMBER CONTRACT NUMBER

W912WJ19C0002

Rock and Boulder: 2.29 CY's Saw Cut State Roads: 138.6 Feet

**Durham Meadows Waterline Remedial Design** 

Water Tank Installation:

DN Tanks;

Pour Wall and Dome Panels Reinforce Wall and Dome Panels

Reinforce Floor

#### QA/QC:

#### PROJECT LAISON COORDINATOR:

Prepared for the Weekly Progress Meeting to be held today at 10:00 am. Met with Christina and Alex Muro at # 119 Maple Avenue to address their concerns about the location of the proposed water service. This will be brought up at the Weekly Progress meeting. 10:00 -11:00 am. Weekly Progress Meeting.

Onsite with Billy's crew installing water services on Main Street.

PM:

Onsite with Jonathan's crew on Maple Avenue.

Started on the Minutes

# PREP/INITIAL DATES

(Preparatory and initial dates held and advance notice)

Preparatory Inspections held today

#### No preparatory inspections held today

Initial Inspections held today

No initial inspections held today

# **ACTIVITY START/FINISH**

Activity No Description

# No activities were started or finished today

# **QC REQUIREMENTS**

Requirement No Typ	pe De	escription	Results
CT-00204 QC	C Test Co	oncrete Pour Walls and Dome Panels: Slump, Air and Temp	Awaiting Results

#### **ISSUED QA/QC DEFICIENCY**

(Describe QA and QC Deficiency items issued)

Item No Location Description

#### No QC Deficiency items were issued today

#### CORRECTED QA/QC DEFICIENCY (Re

(Report QC and QA Deficiency items corrected)

Item No Location Description

# No QC Deficiency items were corrected today

#### **CONTRACTORS ON SITE**

(Report first and/or last day contractors were on site)

Name First Day Last Day

#### No Contractors had their first or last day on the site

LABOR HOURS					
Labor Classification	Employees	Worked			
TRUCK DRIVER, GROUP 1	4.0	32.0			
LABORER, GROUP 1	8.0	64.0			
CIRCULAR SAW OPERATOR	0.0	0.0			
PROJECT MANAGER	1.0	8.0			
OPERATOR HEAVY EQUIPMENT 1	5.0	40.0			
SSHO	1.0	8.0			
	TRUCK DRIVER, GROUP 1  LABORER, GROUP 1  CIRCULAR SAW OPERATOR  PROJECT MANAGER  OPERATOR HEAVY EQUIPMENT 1	TRUCK DRIVER, GROUP 1 4.0  LABORER, GROUP 1 8.0  CIRCULAR SAW OPERATOR 0.0  PROJECT MANAGER 1.0  OPERATOR HEAVY EQUIPMENT 1 5.0			

					ORT NUMBER	Pad	ge 3 of 3	
CONTRACTORS Q	RT (QCR)	61	1	. u				
DAILY LO	OG OF CONST	RUCTION		DATE				
					Aug 2020 -			
PROJECT		D !			TRACT NUMBER			
Durham Meadows Wate		Design CONTROL SYS	TEMMOD	VV	912WJ19C0	002	4.0	0.0
Ludlow Construction Co., Inc.							1.0	8.0
Vellieux Sawcutting		SAW OPERA					0.0	0.0
Total hrs worked to date:	25,632.5	Hrs worl	ked MTD:	1,888.0		Total:	20.0	160.0
EQUIPMENT HOURS							Idle	Operating
Serial Number	Description						Hours	Hours
L-20	L-20 Kumatsu I		er Bil	lly			0.0	8.0
TE-6 Ex	TE-6 Volvo	Jon					6.0	2.0
E-4 0336FCRAB	E-4 Cat 336 Ti		Jon				0.0	8.0
T-36	Dump Truck T-		lon				8.0	0.0
E-20 ECR145DL,	E-20 Volvo Exc		Jon				0.0	8.0
T-41	Ludlow Pressu		-41 Billy				8.0	0.0
T-50	T-50 PU	Jon					4.0	4.0
T-77 PU	T-77 PU		Billy				4.0	4.0
E-9 Track Hoe	E-9 336 Track		Billy				8.0	0.0
T-64	Dump Truck T-						8.0	0.0
B-5 Sweeper	B-5 Sweeper	Billy					6.0	2.0
R-4 Roller Billy	Roller Compac		Billy				6.0	2.0
TE 15 Excavator	TE-15 Track Ho	oe Bil	ly				6.0	2.0
T-84 PU	T-84 PU	Billy					0.0	8.0
T-78 PU	T-78 PU	Jon					6.0	2.0
L-18 950	L-18 Loader	Jo	n				0.0	8.0
R-18 Roller	R-18 Compact						6.0	2.0
D1 Cat	D-1 Cat D-5 D	ozer E	Billy				8.0	0.0
T-86	T-86 Dump Tri	uck	Billy				0.0	8.0
T-21 Dump	T-21 Dump	Jon					8.0	0.0
R-17 Roller	R-17 Roller	Billy					8.0	0.0
T-59 Dump	T-59 Dump	Billy					0.0	8.0
TE-13 Excavator	TE-13 EX	Billy	·			_	8.0	0.0
Total operating hrs to date:	20,423.5 lo	dle hrs MTD:	1,716.0	Opr hrs MTD:	876.0	Total:	108.0	76.0
		e mishaps)						
No mishaps reported tod	ay							
MISHAP REPORTING	(Describe		1,716.0	Opr nrs WTD:	876.0	Total:	108.0	,