CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION		REPORT NUMBER 626 DATE	Page 1 of 3
DAIL! LOS OF CONOTROSTICK		04 Sep 2020 - Frid	lav
PROJECT		CONTRACT NUMBER	,
Durham Meadows Waterline Remedial Design		W912WJ19C0002	
CONTRACTOR	WEATHER		
Ludlow Construction Co., Inc.	Weather Caused No Delay Temperature Min 61 °F Max 83 °F		

No Precipitation 7 MPH Wind

QC NARRATIVES

JOB SAFETY

SAFETY:

Crews arrived at 7:00am, Departed at 3:00-3:30pm

- *SSHO Rob Peddicord:
- *Monitored 2 Ludlow crews production activities; Foremen Jonathon Pio and Billy DaCRuz,
- *Monitored DN Tanks activities at the Water Tank; Foreman Al Kendall.
- *Jonathon Pio's crew: Installing Pipe at Maple Ave
- *1 Labor flagger, 2 CTC flagger as traffic control, (Certs on record) 3 Road Closed signs on Maple.
- *Billy DaCruz crew installing concrete culvert pipes beside the driveway to the Water Tank area
- *1 Laborer saw cutting laterals on Maple
- *Inside Crew 2 traffic zone
- *Borrow/Dump Yard: 1 Operator loading dumps with trench backfill material; maintaining waste piles
- *DN TANKS: poured concrete for overflow encasement
- *JTC tech tested concrete
- *Performed daily checklist inspections on Daily Report; Crews wearing all required PPE, Following Trench Safety, Crews alert of surroundings. Safety in compliance with EM 385-1-1. COVID-19 precautions being followed. (SEE Attached Ludlow SSHO Daily PDF Report)
- *Checked dumptruck haul roads for debris.
- *Checked silt fencing for SWPP; no ruptures.
- *Office work: The SSHO continued collecting and filing crew paperwork for Lift Plans, AHAs, and Daily Equipment Inspections (See Lift Plan PDFs attached to RMS).
- *Received daily reports from DN Tanks; COVID self cert, SSHO Daily Report, and Lift Plans. (Attached SSHO Daily to RMS)

TESTS REQUIRED BY SPECIFICATIONS, PERFORMED, AND THE RESULTS

SWPP Inspection Silt Fence and Drains:

Concrete Pour: Slump 7, 5.6 Air and Temp 77, Ambient Temp 70

WORK PERFORMED TODAY

WORK PERFORMED TODAY Onsite 7:00 AM; Offsite 3:00 PM

PERSONAL; Project Manager 1 Superintendent 5 Operators 5 Labors 9 Truck Drivers 4

VISITERS:

SUBCONTRACTORS ON SITE:

Turner - 1 DN Tanks - 8 Cert Flagger - 3

WORK COMPLETED;

JON'S Crew:

7: 42 FEET OF 8 INCH TR FLEX PIPE: STA 921+14 TO STA 921+56

28: 1 1 INCH CORP: STA 921+38 HOUSE #158 MAPLE ST

26: I FIRE HYDRANT ASSEMBLY: STA 922+67

31: 2 1 INCH CURB STOPS: STA 921+38 (HOUSE #158) AND STA 922+39.5 (HOUSE #162)

34: 31 FEET OF 1 INCH COPPER: #HOUSE 162 MAPLE AVE (STA 922+39.5) 15.5 FEET OF COPPER

CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION

REPORT NUMBER 626

Page 2 of 3

DATE

04 Sep 2020 - Friday

PROJECT

Durham Meadows Waterline Remedial Design

CONTRACT NUMBER
W912WJ19C0002

#HOUSE 158 MAPLE AVE (STA 921+38) 15.5 FEET OF COPPER

62: 130 FEET OF TOWN SAW CUT

BILLY's Crew:

Note: Extra Work, Not in Contract; Extra Lump Sum Drainage: Drainage Inlet Rehab, House # 216, Talbott Ridge Drive. Drainage Extension at STA 19+85

Drainage Extension at STA 19+85 PI # 0087 Water Tank Access Road

Modified Rip Rap Slope Protection at STA 20+60

Water Tank Installation:

DN Tanks:

Pour Overflow Encasement

Strip Wall Panel Forms

Complete shoring beams & plywood

QA/QC:

PROJECT LAISON COORDINATOR:

PREP/INITIAL DATES

(Preparatory and initial dates held and advance notice)

Preparatory Inspections held today

No preparatory inspections held today

Initial Inspections held today

No initial inspections held today

ACTIVITY START/FINISH

Activity No Description

No activities were started or finished today

QC REQUIREMENTS

Requirement No	Туре	Description	Results
CT-00214	QC Test	Concrete Pour: Slump 7. Air 5.6 and Temp 78	Awaiting Results

ISSUED QA/QC DEFICIENCY

(Describe QA and QC Deficiency items issued)

Item No Location Description

No QC Deficiency items were issued today

CORRECTED QA/QC DEFICIENCY

(Report QC and QA Deficiency items corrected)

Item No Location Description

No QC Deficiency items were corrected today

CONTRACTORS ON SITE

(Report first and/or last day contractors were on site)

Name First Day Last Day

No Contractors had their first or last day on the site

LABOR HOURS Employer	Labor Classification	Number of Employees	Hours Worked
Ludlow Construction Co., Inc.	TRUCK DRIVER, GROUP 1	4.0	32.0
Ludlow Construction Co., Inc.	LABORER, GROUP 1	8.0	72.0
Ludlow Construction Co., Inc.	CIRCULAR SAW OPERATOR	0.0	0.0
Ludlow Construction Co., Inc.	PROJECT MANAGER	1.0	8.0
Ludlow Construction Co., Inc.	OPERATOR HEAVY EQUIPMENT 1	5.0	40.0

CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION			626	T NUMBER	F	age 3 of 3			
DAILT LOG OF CONSTRUCTION					Sep 2020 -	Friday			
PROJECT						ACT NUMBER	i iluay		
Durham Meadows Water		Design				2WJ19C00	002		
Ludlow Construction Co., Inc.	SSHO							1.0	8.0
Ludlow Construction Co., Inc.		CONTROL SYS						1.0	8.0
Vellieux Sawcutting	CIRCULAR 	SAW OPERA	ATOR			_		1.0	8.0
Total hrs worked to date:	27,488.5	Hrs wor	rked MTD:	72	0.0	٦	Γotal:	21.0	176.0
EQUIPMENT HOURS								ldle	Operating
Serial Number	Description							Hours	Hours
L-20	L-20 Kumatsu l	Front End Load	der B	illy				4.0	4.0
TE-6 Ex	TE-6 Volvo	Jon						6.0	2.0
E-4 0336FCRAB	E-4 Cat 336 Ti		Jon					4.0	4.0
T-36	Dump Truck T-	36	Jon					0.0	8.0
E-20 ECR145DL,	E-20 Volvo Exc	avator E-20	Jon					4.0	4.0
SCM 1 Vallioux	Saw Cutting Ma	achine						8.0	0.0
T-41	Ludlow Pressu	re Test Truck	Γ-41 Billy	/				0.0	8.0
T-50	T-50 PU	Jon						4.0	4.0
T-77 PU	T-77 PU		Billy					4.0	4.0
T-27 Dump	T-27 Dump	Jor	า					0.0	8.0
E-9 Track Hoe	E-9 336 Track	Hoe	Billy					8.0	0.0
T-64	Dump Truck T-	64						8.0	0.0
B-5 Sweeper	B-5 Sweeper	Bill	у					8.0	0.0
R-4 Roller Billy	Roller Compac	ter	Billy					8.0	0.0
TE 15 Excavator	TE-15 Track Ho	oe B	illy					8.0	0.0
T-84 PU	T-84 PU	Billy	,					8.0	0.0
T-78 PU	T-78 PU	Jon						6.0	2.0
L-18 950	L-18 Loader	Jo	on					4.0	4.0
R-18 Roller	R-18 Compact	or JON						6.0	2.0
D1 Cat	D-1 Cat D-5 D	ozer	Billy					8.0	0.0
T-86	T-86 Dump Tri	ıck	Billy					0.0	8.0
R-17 Roller	R-17 Roller	Billy						8.0	0.0
Total operating hrs to date:	21,349.5 lo	dle hrs MTD:	368.0	Opr hrs	s MTD:	336.0	Total	: 114.0	62.0
MISHAP REPORTING	(Describe	mishaps)							
No mishaps reported toda		. /							