REPORT NUMBER Page 1 of 3 643 **CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION** DATE 21 Sep 2020 - Monday **PROJECT CONTRACT NUMBER** W912WJ19C0002 Durham Meadows Waterline Remedial Design WEATHER Ludlow Construction Co., Inc. Weather Caused No Delay Temperature Min 35 °F Max 65 °F No Precipitation 6 MPH Wind

QC NARRATIVES

JOB SAFETY

SAFETY:

Crews arrived at 7:00am, Departed at 3:00-3:30pm

- *SSHO Rob Peddicord:
- *Monitored 2 Ludlow crews production activities; Foremen Jonathon Pio and Billy DaCRuz,
- *Monitored DN Tanks activities at the Water Tank; Foreman Al Kendall.
- *Monitored saw cutting activities
- *Jonathon Pio's crew: Continued repaving widened trench surface on Rt 17
- *2 Middletown Police, 1 CTC flagger as traffic control, (Certs on record)
- *Billy DaCruz crew temporarily offsite
- *Borrow/Dump Yard: 1 Operator loading dumps with trench backfill material; maintaining waste piles
- *1 Laborer saw pressure testing pipe on Maple
- *DN TANKS: Installing wall slots
- *Vielleux Concrete saw cutting on Rt 17 for wider paving.
- *2 State Patrol for traffic control.
- *Performed daily checklist inspections on Daily Report; Crews wearing all required PPE, Following Trench Safety, Crews alert of surroundings. Safety in compliance with EM 385-1-1. COVID-19 precautions being followed. (SEE Attached Ludlow SSHO Daily PDF Report)
- *Checked dumptruck haul roads for debris.
- *Checked silt fencing for SWPP; no ruptures.
- *Office work: The SSHO continued collecting and filing crew paperwork for Lift Plans, AHAs, and Daily Equipment Inspections (See Lift Plan PDFs attached to RMS).
- *Received daily reports from DN Tanks; COVID self cert, SSHO Daily Report, and Lift Plans. (Attached SSHO Daily to RMS)
- *Two new crew on site: Tim Hendsey, Americo Valadares; Given Site Orientation and COVID Orientation. Filled out Emergency Contact
- *Weekly Safety Meeting: Working around heavy equipment

TESTS REQUIRED BY SPECIFICATIONS, PERFORMED, AND THE RESULTS

Compaction Tests on Asphalt Road: 263.14 SQ YARDS STA 114+95 TO 118+80

WORK PERFORMED TODAY

WORK PERFORMED TODAY Onsite 7:00 AM; Offsite 3:00 PM

PERSONAL; Project Manager 1 Superintendent 5 Operators 4 Labors 7

Truck Drivers 4

VISITERS:

SUBCONTRACTORS ON SITE:

Turner - 1 Police - 4 DN Tanks - 8 Barnhart - 2 Cert Flagger - 1

REPORT NUMBER Page 2 of 3 643 CONTRACTORS QUALITY CONTROL REPORT (QCR) **DAILY LOG OF CONSTRUCTION** DATE 21 Sep 2020 - Monday **PROJECT**

Durham Meadows Waterline Remedial Design

CONTRACT NUMBER W912WJ19C0002

WORK COMPLETED;

JON'S Crew:

Compaction Tests From STA 114+95 TO 118+80

114: 823 FEET OF STATE SAW CUT

116: 263.14 SQ YARDS STA 114+95 TO STA 118+80

117: 263.14 SQ YARDS STA 114+95 TO STA 118+80

119: 11.25 SQ YARDS OF SLIVER SLAB

Water Tank Installation:

DN Tanks; Erect wall slots Install P-Brackets

Set-up to install Dome Ring Form

Repoly Wall Slots

QA/QC:

PROJECT LAISON COORDINATOR:

PREP/INITIAL DATES

(Preparatory and initial dates held and advance notice)

Preparatory Inspections held today

No preparatory inspections held today

Initial Inspections held today

No initial inspections held today

ACTIVITY START/FINISH

Activity No Description

No activities were started or finished today

QC REQUIREMENTS

| Requirement No | Туре | Description | Results |
|----------------|------------|---|------------------|
| CT-00223 | QC Test | Compaction Tests on Rt 17: Awaiting for Results | Awaiting Results |
| ISSUED QA/QC | DEFICIENCY | (Describe QA and QC Deficiency items issued) | |

ISSUED QA/QC DEFICIENCY

Item No Location Description

No QC Deficiency items were issued today

CORRECTED QA/QC DEFICIENCY (Report QC and QA Deficiency items corrected)

Item No Location Description

No QC Deficiency items were corrected today

CONTRACTORS ON SITE (Report first and/or last day contractors were on site)

Name First Day Last Day

No Contractors had their first or last day on the site

| LABOR HOURS | | Number of | Hours |
|-------------------------------|----------------------------|-----------|--------|
| Employer | Labor Classification | Employees | Worked |
| Ludlow Construction Co., Inc. | TRUCK DRIVER, GROUP 1 | 4.0 | 32.0 |
| Ludlow Construction Co., Inc. | LABORER, GROUP 1 | 7.0 | 56.0 |
| Ludlow Construction Co., Inc. | CIRCULAR SAW OPERATOR | 0.0 | 0.0 |
| Ludlow Construction Co., Inc. | PROJECT MANAGER | 1.0 | 8.0 |
| Ludlow Construction Co., Inc. | OPERATOR HEAVY EQUIPMENT 1 | 4.0 | 32.0 |
| Ludlow Construction Co., Inc. | SSHO | 1.0 | 8.0 |
| Ludlow Construction Co., Inc. | QUALITY CONTROL SYSTEM MGR | 1.0 | 8.0 |
| | | | |

REPORT NUMBER Page 3 of 3 643 **CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION** DATE 21 Sep 2020 - Monday CONTRACT NUMBER **PROJECT Durham Meadows Waterline Remedial Design** W912WJ19C0002 CIRCULAR SAW OPERATOR Vellieux Sawcutting 1.0 8.0 Total hrs worked to date: 29.296.5 Hrs worked MTD: 2,528.0 Total: 19.0 152.0 **EQUIPMENT HOURS** Idle Operating Serial Number Description Hours Hours L-20 L-20 Kumatsu Front End Loader Billy 8.0 0.0 TE-6 Ex TE-6 Volvo Jon 6.0 2.0 E-4 0336FCRAB E-4 Cat 336 Track Hoe Jon 8.0 0.0 T-36 Dump Truck T-36 0.0 8.0 Jon E-20 ECR145DL, E-20 Volvo Excavator E-20 0.0 8.0 Jon SCM 1 Vallioux Saw Cutting Machine 0.0 8.0 T-41 Ludlow Pressure Test Truck T-41 Billy 8.0 0.0 T-50 T-50 PU 4.0 4.0 T-77 PU T-77 PU 0.0 Billy 8.0 T-27 Dump T-27 Dump Jon 8.0 0.0 E-9 Track Hoe E-9 336 Track Hoe Billy 8.0 0.0 T-64 Dump Truck T-64 8.0 0.0 B-5 Sweeper B-5 Sweeper Billy 8.0 0.0 R-4 Roller Billy Roller Compacter Billy 8.0 0.0 TE 15 Excavator TE-15 Track Hoe OFF SITE 0.0 Billy 8.0 T-84 PU T-84 PU Billy 8.0 0.0 T-78 PU T-78 PU Jon 6.0 2.0 L-18 950 L-18 Loader 4.0 Jon 4.0 R-18 Roller R-18 Compactor 2.0 JON 6.0 D1 Cat D-1 Cat D-5 Dozer Billy 8.0 0.0 T-86 0.0 T-86 Dump Truck Billy 8.0 R-17 Roller R-17 Roller Billy 8.0 0.0 T-34 Dump Truck T-34 Dump Billy 0.0 8.0 T-8 Dump T-8 Dump 8.0 0.0 Jon PB-3 Paving PB-3 Paving 0.0 8.0 T-92 T-92 Dump Jon 0.0 8.0 T-60 Dump Truck T-60 0.0 8.0 Jon Total operating hrs to date: 22.139.5 Idle hrs MTD: 1,546.0 Opr hrs MTD: 1,126.0 Total: 146.0 70.0 MISHAP REPORTING (Describe mishaps) No mishaps reported today On behalf of the contractor, I certify that this Report is complete and correct and all equipment and CONTRACTOR CERTIFICATION material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above. QC REPRESENTATIVE'S SIGNATURE DATE SUPERINTENDENT'S INITIALS DATE