CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION		REPORT NUMBER 654	Page 1 of 3
		DATE 02 Oct 2020 - Friday	
PROJECT		CONTRACT NUMBER	
Durham Meadows Waterline Remedial Design		W912WJ19C0002	
CONTRACTOR	WEATHER		
Ludlow Construction Co., Inc.		sed No Delay Min 47 °F Max 64 °F Sipitation 4 MPH Wind	

QC NARRATIVES

JOB SAFETY

SAFETY:

Crews arrived at 7:00am, Departed at 3:00-3:30pm

- *SSHO Rob Peddicord:
- *Monitored 2 Ludlow crews production activities; Foremen Jonathon Pio and Billy DaCRuz,
- *Monitored DN Tanks activities at the Water Tank; Foreman Al Kendall.
- *Monitored saw cutting activities
- *Jonathon Pio's crew: Continued repaving widened trench surface on Rt 17
- *1 State Patrol, 1 CTC flagger as traffic control (Certs on record)
- *Billy DaCruz crew temporarily offsite
- *Borrow/Dump Yard: 1 Operator loading dumps with trench backfill material; maintaining waste piles
- *DN TANKS: Attaching wire pulling machine to Water Tank, Patched holes inside Tank, Stripped Dome Supports
- *Vielleux Concrete saw cutting on Rt 17 for wider paving.
- *1 CTC flagger, 1 Laborer for traffic control. (Certs on record)
- *Performed daily checklist inspections on Daily Report; Crews wearing all required PPE, Following Trench Safety, Crews alert of surroundings. Safety in compliance with EM 385-1-1. COVID-19 precautions being followed. (SEE Attached Ludlow SSHO Daily PDF Report)
- *Checked dumptruck haul roads for debris.
- *Checked silt fencing for SWPP; No ruptures
- *Office work: The SSHO continued collecting and filing crew paperwork for AHAs, and Daily Equipment Inspections.
- *Received daily reports from DN Tanks; COVID self cert, SSHO Daily Report. Non-permit Confined Space, Wire Pulling Machine Daily Inspection.(Attached SSHO Daily, NPCS, and Daily Inspection.)

TESTS REQUIRED BY SPECIFICATIONS, PERFORMED, AND THE RESULTS

Compaction Tests on Asphalt Road: STA 146+30 TO 148+70

WORK PERFORMED TODAY

WORK PERFORMED TODAY Onsite 7:00 AM; Offsite 3:30 PM

PERSONAL; Project Manager 1 Superintendent 5 Operators 4 Labors 6 Truck Drivers 4

VISITERS:

SUBCONTRACTORS ON SITE:

Turner - 1 Police - 1 DN Tanks - 7 Cert Flagger - 3

WORK COMPLETED;

JON'S Crew:

114: 474 FEET OF SAW CUT

116: 167.44 SQ YARDS STA 146+30 TO STA 148+70 117: 167.44 SQ YARDS STA 146+30 TO STA 148+70

119: 54.86 SQ YARDS OF SLIVER SLAB

REPORT NUMBER Page 2 of 3 654 **CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION** DATE 02 Oct 2020 - Friday CONTRACT NUMBER **PROJECT Durham Meadows Waterline Remedial Design** W912WJ19C0002 Water Tank Installation: DN Tanks; Place pre-stress wire on tank Patch wall slot holes Strip dome supports QA/QC: PROJECT LAISON COORDINATOR: PREP/INITIAL DATES (Preparatory and initial dates held and advance notice) Preparatory Inspections held today No preparatory inspections held today Initial Inspections held today No initial inspections held today **ACTIVITY START/FINISH** Activity No Description No activities were started or finished today **QC REQUIREMENTS** Туре Requirement No Description Results CT-00236 QC Test Awaiting Results Asphalt was tested: Awaiting Results. STA 146+30 TO 148+70 **ISSUED QA/QC DEFICIENCY** (Describe QA and QC Deficiency items issued) Item No Location Description No QC Deficiency items were issued today CORRECTED QA/QC DEFICIENCY (Report QC and QA Deficiency items corrected) Item No Location Description No QC Deficiency items were corrected today **CONTRACTORS ON SITE** (Report first and/or last day contractors were on site) Name Last Day First Day No Contractors had their first or last day on the site **LABOR HOURS** Number of Hours Employer Labor Classification **Employees** Worked Ludlow Construction Co., Inc. TRUCK DRIVER, GROUP 1 4.0 32.0 Ludlow Construction Co., Inc. LABORER, GROUP 1 6.0 48.0 Ludlow Construction Co., Inc. CIRCULAR SAW OPERATOR 0.0 0.0 PROJECT MANAGER 8.0 Ludlow Construction Co., Inc. 10 Ludlow Construction Co., Inc. **OPERATOR HEAVY EQUIPMENT 1** 4.0 32.0 Ludlow Construction Co., Inc. SSHO 10 8.0 Ludlow Construction Co., Inc. QUALITY CONTROL SYSTEM MGR 8.0 1.0 Vellieux Sawcutting CIRCULAR SAW OPERATOR 1.0 8.0 Total hrs worked to date: 30.600.5 Hrs worked MTD: 288.0 Total: 18.0 144.0 **EQUIPMENT HOURS** Idle Operating Serial Number Description Hours Hours

Durham Meadows Waterline F L-20 L-2 TE-6 Ex TE- E-4 0336FCRAB E-4	Remedial Design 20 Kumatsu Front En	ON) _	CONTRACT NU	20 - Friday	Page 3 of 3	
DAILY LOG OF PROJECT Durham Meadows Waterline F L-20 L-2 TE-6 Ex TE-6 Ex TE-6 E-4 0336FCRAB E-4	Remedial Design 20 Kumatsu Front En	ON	, –	02 Oct 20			
Durham Meadows Waterline F L-20 L-2 TE-6 Ex TE-6 E-4 0336FCRAB E-4	20 Kumatsu Front En			CONTRACT NU			
Durham Meadows Waterline F L-20 L-2 TE-6 Ex TE-6 E-4 0336FCRAB E-4	20 Kumatsu Front En				MBER		
L-20 L-2 TE-6 Ex TE- E-4 0336FCRAB E-4	20 Kumatsu Front En			14/04/01/4/14			
TE-6 Ex TE- E-4 0336FCRAB E-4	-6 Volvo	d Loader		W912WJ1	19C0002		
E-4 0336FCRAB E-4			Billy			8.0	0.0
		Jon				6.0	2.0
T-36 Dur	4 Cat 336 Track Hoe	. Jon				8.0	0.0
	ımp Truck T-36	Jon				0.0	8.0
E-20 ECR145DL, E-2	20 Volvo Excavator E	-20 Jor	n			0.0	8.0
SCM 1 Vallioux Sav	w Cutting Machine					0.0	8.0
T-41 Luc	dlow Pressure Test T	ruck T-41 Bil	lly			8.0	0.0
T-50 T-5	50 PU	Jon				4.0	4.0
T-77 PU T-7	77 PU	Billy				8.0	0.0
T-27 Dump T-2	27 Dump	Jon				8.0	0.0
E-9 Track Hoe E-9	9 336 Track Hoe	Billy				8.0	0.0
T-60 Dur	ımp Truck T-60	Jo	on			0.0	8.0
T-64 Dur	ımp Truck T-64					8.0	0.0
B-5 Sweeper B-5	5 Sweeper	Billy				8.0	0.0
R-4 Roller Billy Rol	ller Compacter	Billy				8.0	0.0
TE 15 Excavator TE-	-15 Track Hoe	Billy OFF S	SITE			8.0	0.0
T-84 PU T-8	84 PU	Billy				8.0	0.0
T-78 PU T-7	78 PU	Jon				6.0	2.0
L-18 950 L-1	18 Loader	Jon				6.0	2.0
R-18 Roller R-1	18 Compactor	JON				4.0	4.0
D1 Cat D-1	1 Cat D-5 Dozer	Billy				8.0	0.0
T-86 T-8	36 Dump Truck	Billy				8.0	0.0
R-17 Roller R-1	17 Roller Billy	y				8.0	0.0
PB1 PB-	3-1 Paver	Jon				8.0	0.0
T-34 Dump T-3	34 Dump Truck	Billy				0.0	8.0
T-92 T-9	92 Dump	Jon				0.0	8.0
T-8 Dump T-8	3 Dump	Jon				8.0	0.0
PB-3 Paving PB-	3-3 Paving					0.0	4.0
Total operating hrs to date: 22,74	49.5 Idle hrs M	1TD: 308.0	Opr hrs N	/ITD: 13	2.0 Total	: 154.0	66.0
MISHAP REPORTING No mishaps reported today	(Describe mishap	s)					