		REPORT NUMBER	Page 1 of 3		
CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION		682	r age r or o		
		DATE			
		30 Oct 2020 - Friday			
PROJECT		CONTRACT NUMBER			
Durham Meadows Waterline Remedial Design		W912WJ19C0002			
CONTRACTOR	WEATHER				
Ludlow Construction Co., Inc.	bw Construction Co., Inc. Weather Cau Temperature 1.50 IN Pre				
QC NARRATIVES JOB SAFETY					
SAFETY: Crews arrived at 7:00am, Departed at 12:00pm *SSHO Rob Peddicord: *Monitored 2 Ludlow crews production activities; Foremen Jonati *Monitored DN Tanks activities at the Water Tank; Foreman AI K	hon Pio and Billy D endall.	aCRuz,			
*Jonathon Pio's crew: RAINOUT					
*Billy DaCruz crew: RAINOUT					
*Borrow/Dump Yard: RAINOUT					
*DN TANKS: Partial day loading out equipment, Clean up site					
*Office work: The SSHO continued collecting and filing crew paperwork for AHAs, and Daily Equipment Inspections.					
*Received daily reports from DN Tanks; COVID self cert, SS COVID to RMS)	SHO Daily Report	. Non-permit Confined Space	. (Attached all except		
WORK PERFORMED TODAY					
WORK PERFORMED TODAY Onsite 7:00 AM ; Offsite 3:30 PM					
Weather caused Critical Delay of Project:					
PERSONAL; Project Manager 1 Superintendent 2 Operators 0 Labors 0 Truck Drivers 0					
VISITERS:					
SUBCONTRACTORS ON SITE: Turner - 0 Police - 0 DN Tanks - 9 Cert Flagger - 0					
WORK COMPLETED;					
JONS CREW Off due to Weather					
BILLYS CREW Off due to Weather					
Water Tank: Al,s Crew. Clean Site Loadout site					
PREP/INITIAL DATES (Preparatory and initial dat	es held and advan	ce notice)			
Preparatory Inspections held today No preparatory inspections held today					
Initial Inspections held today					

DAILY LOO		REPORT NUMBER	D - / -	
DAILY LOO	CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION		Page 2 of 3	1
			iy	
Durham Meadows Waterli		30 Oct 2020 - Frida CONTRACT NUMBER	-	
Duman meadows watern	ne Remedial Design	W912WJ19C0002		
No initial inspections held	•	I		
ACTIVITY START/FINISH				
Activity No Description				
No activities were started of	r finished today			
QC REQUIREMENTS				
Requirement No Type	Description		Results	
No QC requirements were	completed today			
SSUED QA/QC DEFICIENCY	(Describe QA and QC Deficiency iten	ns issued)		
Item No Location	Description			
No QC Deficiency items we	-			
CORRECTED QA/QC DEFICI	ENCY (Report QC and QA Deficiency items	corrected)		
Item No Location	Description			
Name		First Day	Last Day	
No Contractors had their fi	rst or last day on the site			
ABOR HOURS			Number of	Hours
			Employees	Worked
				0.0
				0.0
Ludlow Construction Co., Inc.			0.0	0.0
Ludlow Construction Co., Inc.	OPERATOR HEAVY EQUIPMENT 1		1.0	8.0
Ludlow Construction Co., Inc.			0.0	8.0 0.0
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc.	SSHO		0.0 1.0	8.0 0.0 8.0
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc.	SSHO QUALITY CONTROL SYSTEM MGR		0.0 1.0 1.0	8.0 0.0 8.0 8.0
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Vellieux Sawcutting	SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR		0.0 1.0 1.0 0.0	8.0 0.0 8.0 8.0 0.0
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc.	SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR	3,048.0 Total:	0.0 1.0 1.0 0.0	8.0 0.0 8.0 8.0
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Vellieux Sawcutting	SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR	3,048.0 Total:	0.0 1.0 1.0 0.0 3.0	8.0 0.0 8.0 8.0 0.0 24.0
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Vellieux Sawcutting Total hrs worked to date:	SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR	3,048.0 Total:	0.0 1.0 1.0 0.0	8.0 0.0 8.0 8.0 0.0
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Vellieux Sawcutting Total hrs worked to date:	SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR 33,360.5 Hrs worked MTD:	3,048.0 Total:	0.0 1.0 1.0 0.0 3.0	8.0 0.0 8.0 0.0 24.0 Operating
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Vellieux Sawcutting Total hrs worked to date: EQUIPMENT HOURS Serial Number	SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR 33,360.5 Hrs worked MTD: Description	3,048.0 Total:	0.0 1.0 1.0 0.0 3.0 Idle Hours	8.0 0.0 8.0 0.0 24.0 Operating Hours
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Vellieux Sawcutting Total hrs worked to date: EQUIPMENT HOURS Serial Number L-20	SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR 33,360.5 Hrs worked MTD: Description L-20 Kumatsu Front End Loader Billy	3,048.0 Total:	0.0 1.0 1.0 0.0 3.0 Idle Hours 8.0	8.0 0.0 8.0 0.0 24.0 Operating Hours 0.0
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Vellieux Sawcutting Total hrs worked to date: EQUIPMENT HOURS Serial Number L-20 TE-6 Ex	SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR 33,360.5 Hrs worked MTD: Description L-20 Kumatsu Front End Loader Billy TE-6 Volvo Jon	3,048.0 Total:	0.0 1.0 1.0 0.0 3.0 Idle Hours 8.0 8.0	8.0 0.0 8.0 0.0 24.0 Operating Hours 0.0 0.0
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Vellieux Sawcutting Total hrs worked to date: EQUIPMENT HOURS Serial Number L-20 TE-6 Ex E-4 0336FCRAB	SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR 33,360.5 Hrs worked MTD: Description L-20 Kumatsu Front End Loader Billy TE-6 Volvo Jon E-4 Cat 336 Track Hoe Jon	3,048.0 Total:	0.0 1.0 1.0 0.0 3.0 Idle Hours 8.0 8.0 8.0 8.0	8.0 0.0 8.0 0.0 24.0 Operating Hours 0.0 0.0 0.0
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Vellieux Sawcutting Total hrs worked to date: EQUIPMENT HOURS Serial Number L-20 TE-6 Ex E-4 0336FCRAB T-36	SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR 33,360.5 Hrs worked MTD: Description L-20 Kumatsu Front End Loader Billy TE-6 Volvo Jon E-4 Cat 336 Track Hoe Jon Dump Truck T-36 Jon	3,048.0 Total:	0.0 1.0 1.0 0.0 3.0 Idle Hours 8.0 8.0 8.0 8.0 8.0 8.0	8.0 0.0 8.0 0.0 24.0 Operating Hours 0.0 0.0 0.0 0.0
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Vellieux Sawcutting Total hrs worked to date: EQUIPMENT HOURS Serial Number L-20 TE-6 Ex E-4 0336FCRAB T-36 E-20 ECR145DL,	SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR 33,360.5 Hrs worked MTD: 33,360.5 Hrs worked MTD: Description L-20 Kumatsu Front End Loader Billy TE-6 Volvo Jon E-4 Cat 336 Track Hoe Jon Dump Truck T-36 Jon E-20 Volvo Excavator E-20 Jon	3,048.0 Total:	0.0 1.0 1.0 0.0 3.0 Idle Hours 8.0 8.0 8.0 8.0 8.0 8.0 8.0 8.0	8.0 0.0 8.0 0.0 24.0 Operating Hours 0.0 0.0 0.0 0.0 0.0
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Vellieux Sawcutting Total hrs worked to date: EQUIPMENT HOURS Serial Number L-20 TE-6 Ex E-4 0336FCRAB T-36 E-20 ECR145DL, SCM 1 Vallioux	SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR 33,360.5 Hrs worked MTD: 33,360.5 Hrs worked MTD: Bescription L-20 Kumatsu Front End Loader Billy TE-6 Volvo Jon E-4 Cat 336 Track Hoe Jon E-4 Cat 336 Track Hoe Jon E-20 Volvo Excavator E-20 Jon Saw Cutting Machine	3,048.0 Total:	0.0 1.0 1.0 0.0 3.0 Idle Hours 8.0 8.0 8.0 8.0 8.0 8.0 8.0 8.0	8.0 0.0 8.0 0.0 24.0 Operating Hours 0.0 0.0 0.0 0.0 0.0 0.0
Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Vellieux Sawcutting Total hrs worked to date: EQUIPMENT HOURS Serial Number L-20 TE-6 Ex E-4 0336FCRAB T-36 E-20 ECR145DL, SCM 1 Vallioux T-50	SSHO QUALITY CONTROL SYSTEM MGR CIRCULAR SAW OPERATOR 33,360.5 Hrs worked MTD: Description Billy L-20 Kumatsu Front End Loader Billy TE-6 Volvo Jon E-4 Cat 336 Track Hoe Jon Dump Truck T-36 Jon E-20 Volvo Excavator E-20 Jon Saw Cutting Machine Jon	3,048.0 Total:	0.0 1.0 1.0 0.0 3.0 Idle Hours 8.0 8.0 8.0 8.0 8.0 8.0 8.0 8.0	8.0 0.0 8.0 0.0 24.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0
	Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER			

Durham Meadows Waterline Remedial Design W912WJ19C0002 T-60 Dump Truck T-60 Jon 8.0 0.0 T-64 Dump Truck T-64 8.0 0.0 B-5 Sweeper Jon 8.0 0.0 R-4 Roller Billy Roller Compacter Billy 8.0 0.0 T-78 PU Jon 8.0 0.0 T-78 PU Jon 8.0 0.0 L-18 Loader Jon 8.0 0.0 R-18 Compactor JON 8.0 0.0 L-18 Loader Jon 8.0 0.0 R-18 Compactor JON 8.0 0.0 R-34 Dump T-34 Dump Truck Jon 8.0 0.0 R-34 Dump R-9 Damy <t< th=""><th>CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION 682 DATE 30 Oct 2020 - Friday CONTRACT NUMBER Durham Meadows Waterline Remedial Design CONTRACT NUMBER Durham Meadows Waterline Remedial Design W912WJ19C0002 T-60 Dump Truck T-60 Jon 8.0 00 T-64 Dump Truck T-64 8.0 0 0 Sweeper Jon 8.0 00 T-84 PU FIL Billy 8.0 00 T-78 PU Jon 8.0 00 L18 Loader Jon 8.0 00 L18 Compactor JON 8.0 00 L18 Compactor JON 8.0 00 L18 Compactor JON 8.0 00 L18 Compactor</th></t<>	CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION 682 DATE 30 Oct 2020 - Friday CONTRACT NUMBER Durham Meadows Waterline Remedial Design CONTRACT NUMBER Durham Meadows Waterline Remedial Design W912WJ19C0002 T-60 Dump Truck T-60 Jon 8.0 00 T-64 Dump Truck T-64 8.0 0 0 Sweeper Jon 8.0 00 T-84 PU FIL Billy 8.0 00 T-78 PU Jon 8.0 00 L18 Loader Jon 8.0 00 L18 Compactor
30 Oct 2020 - Friday CONTRACT NUMBER Durham Meadows Waterline Remedial Design W912WJ19C0002 T-60 Dump Truck T-60 Jon 8.0 0.0 T-64 Dump Truck T-64 8.0 0.0 B-5 Sweeper Jon 8.0 0.0 R-4 Roller Billy Roller Compacter Billy 8.0 0.0 T-84 PU T-84 PU Billy 8.0 0.0 T-78 PU T-78 PU Jon 8.0 0.0 R-18 Roller R-18 Compactor JON 8.0 0.0 R-18 Roller R-18 Compactor JON 8.0 0.0 T-86 T-86 Dump Truck Billy 8.0 0.0 T-34 Dump T-34 Dump Truck Jon 8.0 0.0 T-92 T-92 Dump Jon 8.0 0.0 T-86 T-80 p Billy 8.0 0.0 T-92 T-92 Dump Jon 8.0 0.0 T-92 T-92 Du	30 Oct 2020 - Friday CONTRACT NUMBER Durham Meadows Waterline Remedial Design W912WJ19C0002 T-60 Dump Truck T-60 Jon 8.0 0 T-64 Dump Truck T-64 8.0 0 B-5 Sweeper Jon 8.0 0 R-4 Roller Billy Roller Compacter Billy 8.0 0 T-84 PU T-78 PU Jon 8.0 0 T-78 PU T-78 PU Jon 8.0 0 L-18 boder R-18 Compactor Jon 8.0 0 D1 Cat D-1 Cat D-5 Dozer 8.0 0 0 T-86 T-86 Dump Truck Billy 8.0 0 D1 Cat D-1 Cat D-5 Dozer 8.0 0 0 T-86 T-86 Dump Truck Billy 8.0 0 0 D1 Cat D-1 Cat D-5 Dozer 8.0 0 0 T-86 T-86 Dump Truck Jon 8.0 0 0 D1 C
Durham Meadows Waterline Remedial Design CONTRACT NUMBER W912WJ19C0002 T-60 Dump Truck T-60 Jon 8.0 0.0 T-64 Dump Truck T-64 8.0 0.0 B-5 Sweeper B-5 Sweeper Jon 8.0 0.0 R-4 Roller Billy Roller Compacter Billy 8.0 0.0 T-78 PU T-78 PU Jon 8.0 0.0 L-18 950 L-18 Loader Jon 8.0 0.0 R-18 Roller R-18 Compactor Jon 8.0 0.0 D1 Cat D-1 Cat D-5 Dozer 8.0 0.0 0.0 T-36 Dump Truck Billy 8.0 0.0 0.0 T-36 T-86 Dump Truck Billy 8.0 0.0 0.0 T-34 Dump T-34 Dump Truck Jon 8.0 0.	Durham Meadows Waterline Remedial Design CONTRACT NUMBER T-60 Dump Truck T-60 Jon 8.0 0 T-64 Dump Truck T-64 8.0 0 B-5 Sweeper B-5 Sweeper Jon 8.0 0 R-4 Roller Billy Roller Compacter Billy 8.0 0 T-84 PU T-84 PU Billy 8.0 0 T-84 PU T-84 PU Jon 8.0 0 T-84 PU T-84 PU Jon 8.0 0 T-84 PU T-78 PU Jon 8.0 0 L-18 S00 L-18 Loader Jon 8.0 0 L-18 S00 L-18 Compactor JON 8.0 0 T-86 T-86 Dump Truck Billy 8.0 0 0 T-92 T-92 Dump Jon 8.0 0 0 T-34 Dump T-34 Dump Truck Jon 8.0 0 0 T-92 T-92 Dump Jon 8.0 0 0
Durham Meadows Waterline Remedial Design W912WJ19C0002 T-60 Dump Truck T-60 Jon 8.0 0.0 T-64 Dump Truck T-64 8.0 0.0 B-5 Sweeper Jon 8.0 0.0 R-4 Roller Billy Roller Compacter Billy 8.0 0.0 T-84 PU T-84 PU Billy 8.0 0.0 T-78 PU T-78 PU Jon 8.0 0.0 L-18 boder Jon 8.0 0.0 R-18 Roller R-18 Compactor JON 8.0 0.0 D1 Cat D-1 Cat D-5 Dozer 8.0 0.0 0.0 T-86 T-86 Dump Truck Billy 8.0 0.0 0.0 T-84 Dump T-34 Dump Truck Jon 8.0 0.0	Durham Meadows Waterline Remedial Design W912WJ19C0002 T-60 Dump Truck T-60 Jon 8.0 0 T-64 Dump Truck T-64 8.0 0 B-5 Sweeper B-5 Sweeper Jon 8.0 0 R-4 Roller Billy Roller Compacter Billy 8.0 0 T-84 PU T-84 PU Billy 8.0 0 T-78 PU T-78 PU Jon 8.0 0 L-18 S00 L-18 Loader Jon 8.0 0 R-18 Roller R-18 Compactor JON 8.0 0 D1 Cat D-1 Cat D-5 Dozer 8.0 0 0 T-86 T-86 Dump Truck Billy 8.0 0 0 T-34 Dump T-34 Dump Truck Jon 8.0 0 0 T-34 Dump T-34 Dump Truck Jon 8.0 0 0 T-36 Dump T-34 Dump Truck Jon 8.0 0 0 T-92 T-92 Dump Jon
T-60 Dump Truck T-60 Jon 8.0 0.0 T-64 Dump Truck T-64 8.0 0.0 B-5 Sweeper B-5 Sweeper Jon 8.0 0.0 R-4 Roller Billy Roller Compacter Billy 8.0 0.0 T-84 PU T-84 PU Billy 8.0 0.0 T-78 PU T-78 PU Jon 8.0 0.0 L-18 950 L-18 Loader Jon 8.0 0.0 R-18 Roller R-18 Compactor Jon 8.0 0.0 D1 Cat D-1 Cat D-5 Dozer 8.0 0.0 0 T-86 T-86 Dump Truck Billy 8.0 0.0 0 T-34 Dump T-34 Dump Truck Jon 8.0 0.0 0 T-34 Dump T-34 Dump Truck Jon 8.0 0.0 0 T-92 T-92 Dump Jon 8.0 0.0 0 0 T-8 Dump T-8 Dump Billy 8.0 0.0 0 0	T-60 Dump Truck T-64 Jon 8.0 0 T-64 Dump Truck T-64 8.0 0 B-5 Sweeper B-5 Sweeper Jon 8.0 0 R-4 Roller Billy Roller Compacter Billy 8.0 0 T-84 PU T-84 PU Billy 8.0 0 T-84 PU T-78 PU T-78 PU 8.0 0 T-78 PU T-78 PU Jon 8.0 0 L-18 Joader Jon 8.0 0 R-18 Roller R-18 Compactor JON 8.0 0 D1 Cat D-1 Cat D-5 Dozer 8.0 0 0 T-86 T-86 Dump Truck Billy 8.0 0 PB1 PB-1 Paver Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 0 T-49 TR-49 Dump 8.0 0 0 Totale 23,997.5 Idle hrs MTD
T-64 Dump Truck T-64 8.0 0.0 B-5 Sweeper Jon 8.0 0.0 R-4 Roller Billy Roller Compacter Billy 8.0 0.0 T-84 PU T-84 PU Billy 8.0 0.0 T-78 PU T-78 PU Jon 8.0 0.0 L-18 950 L-18 Loader Jon 8.0 0.0 R-18 Roller R-18 Compactor JON 8.0 0.0 D1 Cat D-1 Cat D-5 Dozer 8.0 0.0 0.0 T-86 T-86 Dump Truck Billy 8.0 0.0 PB1 Paver Jon 8.0 0.0 T-34 Dump Truck Jon 8.0 0.0 T-34 Dump Truck Jon 8.0 0.0 T-92 T-92 Dump Jon 8.0 0.0 T-92 Dump Jon 8.0 0.0 0 T-8 Dump T-8 Dump Billy 8.0 0.0 PB-3 Paving T-8 Dump 8.0 0.0 0 T-49 TR-49 Dump 3.600.0 0rteri	T-64 Dump Truck T-64 8.0 0 B-5 Sweeper Jon 8.0 0 R-4 Roller Billy Roller Compacter Billy 8.0 0 T-84 PU T-84 PU Billy 8.0 0 T-78 PU T-78 PU Jon 8.0 0 L-18 950 L-18 Loader Jon 8.0 0 R-18 Roller R-18 Compactor JON 8.0 0 D1 Cat D-1 Cat D-5 Dozer 8.0 0 0 T-86 T-86 Dump Truck Billy 8.0 0 PB1 PB-1 Paver Jon 8.0 0 T-34 Dump Truck Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 0 T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 0 T-49 TR-49 Dump 3,600.0
B-5 Sweeper Jon 8.0 0.0 R-4 Roller Billy Roller Compacter Billy 8.0 0.0 T-84 PU T-84 PU Billy 8.0 0.0 T-78 PU T-78 PU Jon 8.0 0.0 L-18 950 L-18 Loader Jon 8.0 0.0 R-18 Roller R-18 Compactor JON 8.0 0.0 D1 Cat D-1 Cat D-5 Dozer 8.0 0.0 T-86 T-86 Dump Truck Billy 8.0 0.0 PB1 PB-1 Paver Jon 8.0 0.0 T-92 T-92 Dump Jon 8.0 0.0 T-8 Dump T-8 Dump Billy 8.0 0.0 PB-3 Paving T-8 Dump Billy 8.0 0.0 T-8 Dump T-8 Dump Billy 8.0 0.0 PB-3 Paving PB-3 Paving 8.0 0.0 0.0 T-8 Dump T-8 Dump Billy 8.0 0.0 0.0 T-8 Dump T-8 Dump Billy 8.0 0.0 0.0 <td< th=""><th>B-5 Sweeper Jon 8.0 0 R-4 Roller Billy Roller Compacter Billy 8.0 0 T-84 PU T-84 PU Billy 8.0 0 T-78 PU T-78 PU Jon 8.0 0 L-18 950 L-18 Loader Jon 8.0 0 R-18 Roller R-18 Compactor JON 8.0 0 D1 Cat D-1 Cat D-5 Dozer 8.0 0 T-86 T-86 Dump Truck Billy 8.0 0 PB1 PB-1 Paver Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving T-8 Dump Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 0 TR-49 TR-49 TR-49 Dump 8.0 0 0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0</th></td<>	B-5 Sweeper Jon 8.0 0 R-4 Roller Billy Roller Compacter Billy 8.0 0 T-84 PU T-84 PU Billy 8.0 0 T-78 PU T-78 PU Jon 8.0 0 L-18 950 L-18 Loader Jon 8.0 0 R-18 Roller R-18 Compactor JON 8.0 0 D1 Cat D-1 Cat D-5 Dozer 8.0 0 T-86 T-86 Dump Truck Billy 8.0 0 PB1 PB-1 Paver Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving T-8 Dump Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 0 TR-49 TR-49 TR-49 Dump 8.0 0 0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0
R-4 Roller Billy Roller Compacter Billy 8.0 0.0 T-84 PU T-84 PU Billy 8.0 0.0 T-78 PU T-78 PU Jon 8.0 0.0 L-18 950 L-18 Loader Jon 8.0 0.0 R-18 Roller R-18 Compactor JON 8.0 0.0 D1 Cat D-1 Cat D-5 Dozer 8.0 0.0 T-86 T-86 Dump Truck Billy 8.0 0.0 PB1 PB-1 Paver Jon 8.0 0.0 T-34 Dump T-34 Dump Truck Jon 8.0 0.0 T-92 T-92 Dump Jon 8.0 0.0 T-8 Dump Jon 8.0 0.0 0.0 T-92 Dump Jon 8.0 0.0 0.0 T-8 Dump Billy 8.0 0.0 0.0 T-8 Dump Jon 8.0 0.0 0.0 T-8 Dump Billy 8.0 0.0 0.0 T-8 APU T-8 Dump Billy 8.0 0.0 T-8 APU T-8	R-4 Roller Billy Roller Compacter Billy 8.0 0 T-84 PU T-84 PU Billy 8.0 0 T-78 PU T-78 PU Jon 8.0 0 L-18 950 L-18 Loader Jon 8.0 0 R-18 Roller R-18 Compactor JON 8.0 0 D1 Cat D-1 Cat D-5 Dozer 8.0 0 T-86 T-86 Dump Truck Billy 8.0 0 PB1 PB-1 Paver Jon 8.0 0 T-34 Dump T-34 Dump Truck Billy 8.0 0 T-34 Dump T-34 Dump Truck Jon 8.0 0 T-34 Dump T-92 Dump Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump F-8 Dump Billy 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 0 T-49 Tr-49 Dump 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0
T-84 PU Filly Billy 8.0 0.0 T-78 PU T-78 PU Jon 8.0 0.0 L-18 950 L-18 Loader Jon 8.0 0.0 R-18 Roller R-18 Compactor JON 8.0 0.0 D1 Cat D-1 Cat D-5 Dozer 8.0 0.0 T-86 T-86 Dump Truck Billy 8.0 0.0 PB1 PB-1 Paver Jon 8.0 0.0 T-34 Dump Truck Jon 8.0 0.0 T-92 T-92 Dump Jon 8.0 0.0 T-8 Dump T-8 Dump Jon 8.0 0.0 PB-3 Paving PB-3 Paving 8.0 0.0 TR-49 TR-49 Dump 8.0 0.0 Total operating hrs to date: 23.997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0.0 MSHAP REPORTING (Describer bishaps) Storter bishaps/ Storter	T-84 PU T-78 PU Jon 8.0 0 T-78 PU T-78 PU Jon 8.0 0 L-18 950 L-18 Loader Jon 8.0 0 R-18 Roller R-18 Compactor JON 8.0 0 D1 Cat D-1 Cat D-5 Dozer 8.0 0 T-86 T-86 Dump Truck Billy 8.0 0 PB1 PB-1 Paver Jon 8.0 0 T-34 Dump T-34 Dump Truck Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 0 TR-49 TR-49 Dump 3,600.0 0r thrs MTD: 1,380.0 Total: 208.0 0
T-78 PU Jon 8.0 0.0 L-18 950 L-18 Loader Jon 8.0 0.0 R-18 Roller R-18 Compactor JON 8.0 0.0 D1 Cat D-1 Cat D-5 Dozer 8.0 0.0 T-86 T-86 Dump Truck Billy 8.0 0.0 PB1 PB-1 Paver Jon 8.0 0.0 T-34 Dump T-34 Dump Truck Jon 8.0 0.0 T-92 T-92 Dump Jon 8.0 0.0 T-8 Dump T-8 Dump Jon 8.0 0.0 T-8 Dump T-92 Dump Jon 8.0 0.0 T-8 Dump Billy 8.0 0.0 0.0 T-8 Dump Billy 8.0 0.0 0.0 T-8 Dump Billy 8.0 0.0 0.0 PB-3 Paving PB-3 Paving 8.0 0.0 0.0 T-49 TR-49 Dump 3.600.0 0pr hrs MTD: 1.380.0 Total: 208.0 0.0 MISHAP REPORTING (Describarsh) Describarsh Describars	T-78 PU T-78 PU Jon 8.0 0 L-18 950 L-18 Loader Jon 8.0 0 R-18 Roller R-18 Compactor JON 8.0 0 D1 Cat D-1 Cat D-5 Dozer 8.0 0 T-86 T-86 Dump Truck Billy 8.0 0 PB1 PB-1 Paver Jon 8.0 0 T-34 Dump T-34 Dump Truck Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 0 TR-49 TR-49 Dump 3,600.0 0r hrs MTD: 1,380.0 Total: 20.0 0
L-18 950 L-18 Loader Jon 8.0 0.0 R-18 Roller R-18 Compactor JON 8.0 0.0 D1 Cat D-1 Cat D-5 Dozer 8.0 0.0 T-86 T-86 Dump Truck Billy 8.0 0.0 PB1 PB-1 Paver Jon 8.0 0.0 T-34 Dump T-34 Dump Truck Jon 8.0 0.0 T-92 T-92 Dump Jon 8.0 0.0 T-8 Dump T-8 Dump Billy 8.0 0.0 PB-3 Paving T-8 Dump Billy 8.0 0.0 TR-49 TR-49 Dump 8.0 0.0 0.0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0.0	L-18 950 L-18 Loader Jon 8.0 0 R-18 Roller R-18 Compactor JON 8.0 0 D1 Cat D-1 Cat D-5 Dozer 8.0 0 T-86 T-86 Dump Truck Billy 8.0 0 PB1 PB-1 Paver Jon 8.0 0 T-34 Dump T-34 Dump Truck Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Jon 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 0 TR-49 TR-49 Dump 3,600.0 Op rhrs MTD: 1,380.0 Total: 208.0 0
R-18 Roller R-18 Compactor JON 8.0 0.0 D1 Cat D-1 Cat D-5 Dozer 8.0 0.0 T-86 T-86 Dump Truck Billy 8.0 0.0 PB1 PB-1 Paver Jon 8.0 0.0 T-34 Dump T-34 Dump Truck Jon 8.0 0.0 T-92 T-92 Dump Jon 8.0 0.0 T-8 Dump T-8 Dump Billy 8.0 0.0 PB-3 Paving T-8 Dump Billy 8.0 0.0 TR-49 TR-49 Dump 8.0 0.0 0.0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0.0 MISHAP REPORTING	R-18 Roller R-18 Compactor JON 8.0 8.0 0 D1 Cat D-1 Cat D-5 Dozer 8.0 0 T-86 T-86 Dump Truck Billy 8.0 0 PB1 PB-1 Paver Jon 8.0 0 T-34 Dump T-34 Dump Truck Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving T-8 Dump Billy 8.0 0 TR-49 TR-49 Dump 8.0 0 0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0
D1 Cat D-1 Cat D-5 Dozer 8.0 0.0 T-86 T-86 Dump Truck Billy 8.0 0.0 PB1 PB-1 Paver Jon 8.0 0.0 T-34 Dump T-34 Dump Truck Jon 8.0 0.0 T-92 T-92 Dump Jon 8.0 0.0 T-8 Dump T-8 Dump Jon 8.0 0.0 PB-3 Paving PB-3 Paving Billy 8.0 0.0 TR-49 TR-49 Dump 8.0 0.0 0.0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0.0	D1 Cat D-1 Cat D-5 Dozer 8.0 0 T-86 T-86 Dump Truck Billy 8.0 0 PB1 PB-1 Paver Jon 8.0 0 T-34 Dump T-34 Dump Truck Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 TR-49 TR-49 Dump 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0
T-86 Dump Truck Billy 8.0 0.0 PB1 PB-1 Paver Jon 8.0 0.0 T-34 Dump T-34 Dump Truck Jon 8.0 0.0 T-92 T-92 Dump Jon 8.0 0.0 T-8 Dump T-8 Dump Billy 8.0 0.0 PB-3 Paving PB-3 Paving Billy 8.0 0.0 TR-49 TR-49 Dump 8.00 0.0 0.0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0.0	T-86 T-86 Dump Truck Billy 8.0 0 PB1 PB-1 Paver Jon 8.0 0 T-34 Dump T-34 Dump Truck Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 TR-49 TR-49 Dump 8.00 0 0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0
PB1 PB-1 Paver Jon 8.0 0.0 T-34 Dump T-34 Dump Truck Jon 8.0 0.0 T-92 T-92 Dump Jon 8.0 0.0 T-8 Dump Jon 8.0 0.0 PB-3 Paving T-8 Dump Billy 8.0 0.0 PB-3 Paving PB-3 Paving PB-3 Paving 8.0 0.0 TR-49 TR-49 Dump 8.0 0.0 0.0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0.0	PB1 PB-1 Paver Jon 8.0 0 T-34 Dump T-34 Dump Truck Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 TR-49 TR-49 Dump 8.0 0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0
T-34 Dump T-34 Dump Truck Jon 8.0 0.0 T-92 T-92 Dump Jon 8.0 0.0 T-8 Dump T-8 Dump Billy 8.0 0.0 PB-3 Paving PB-3 Paving PB-3 Paving 8.0 0.0 TR-49 TR-49 Dump 8.0 0.0 0.0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0.0	T-34 Dump T-34 Dump Truck Jon 8.0 0 T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 TR-49 TR-49 Dump 8.0 0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0
T-92 T-92 Dump Jon 8.0 0.0 T-8 Dump T-8 Dump Billy 8.0 0.0 PB-3 Paving PB-3 Paving 8.0 0.0 TR-49 TR-49 Dump 8.0 0.0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0.0	T-92 T-92 Dump Jon 8.0 0 T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 TR-49 TR-49 Dump 8.0 0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0
T-8 Dump T-8 Dump Billy 8.0 0.0 PB-3 Paving PB-3 Paving 8.0 0.0 TR-49 TR-49 Dump 8.0 0.0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0.0	T-8 Dump T-8 Dump Billy 8.0 0 PB-3 Paving PB-3 Paving 8.0 0 TR-49 TR-49 Dump 8.0 0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0
PB-3 Paving PB-3 Paving 8.0 0.0 TR-49 TR-49 Dump 8.0 0.0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0.0	PB-3 Paving PB-3 Paving PB-3 Paving 8.0 0 TR-49 TR-49 Dump 8.0 0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0
TR-49 TR-49 Dump 8.0 0.0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0.0 MISHAP REPORTING (Describe mishaps) (Describe mishaps) Image: Comparison of the state of the	TR-49 TR-49 Dump 8.0 0 Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0
Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0.0 MISHAP REPORTING (Describe mishaps) Opr hrs MTD: 1,380.0 Total: 208.0 0.0	Total operating hrs to date: 23,997.5 Idle hrs MTD: 3,600.0 Opr hrs MTD: 1,380.0 Total: 208.0 0
/ISHAP REPORTING (Describe mishaps)	
	AISHAP REPORTING (Describe mishaps)
No mishaps reported today	No mishaps reported today

On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.

QC REPRESENTATIVE'S SIGNATURE	DATE	SUPERINTENDENT'S INITIALS	DATE