REPORT NUMBER Page 1 of 2 840 **CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION** DATE 06 Apr 2021 - Tuesday **PROJECT CONTRACT NUMBER** W912WJ19C0002 Durham Meadows Waterline Remedial Design **WEATHER** Ludlow Construction Co., Inc. Weather Caused No Delay Temperature Min 41 °F Max 69 °F No Precipitation 9 MPH Wind

QC NARRATIVES

JOB SAFETY

SAFETY:

Crews arrived at 7:00am, Departed at 3:00-3:30pm

*SSHO Rob Peddicord:

*Monitored 1 Ludlow crew production activities; Foremen Billy DaCruz

*Crew continued work at the Water Tank Area:

*Placed the 4 panels for the interlocking trench box, in prep for excavating the Altitude Vault pit.

*Excavated the Vault Pit. Temporary fencing placed around open excavation

*Also: Pete Olmos flushing the main water line in town. (See QC Mgr Jerry Brandon Daily for specific details)

*SSHO: Weekly Safety Meeting: Reviewed Site Orientation, Covid Orientation, AHAs. Also discussed making good decisions and the repercussions of making bad decisions

WORK PERFORMED TODAY

WORK PERFORMED TODAY Onsite 7:00 AM; Offsite 3:30 PM

PERSONAL Superintendent 3 Operators 2 Labors 3 Truck Drivers 1

VISITERS:

SUBCONTRACTORS ON SITE:

WORK COMPLETED;

Billie's Crew:

Excavated for Shoring.

Set Shoring for Altitude Vault.

Installed Fencing around Altitude Vault

Flushed Water Lines on 17 Maiden Lane

QA/QC:

QC Jerry Brandon, Safety HSSO, met with QA Curt Mintel.

Discussed Altitude Vault dimension's

Discussed Safety Issue's

PREP/INITIAL DATES

(Preparatory and initial dates held and advance notice)

Preparatory Inspections held today

No preparatory inspections held today

Initial Inspections held today

No initial inspections held today

ACTIVITY START/FINISH

Activity No Description

No activities were started or finished today

QC REQUIREMENTS

Requirement No Type Description Results

No QC requirements were completed today

REPORT NUMBER Page 2 of 2 840 **CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION** DATE 06 Apr 2021 - Tuesday CONTRACT NUMBER **PROJECT** W912WJ19C0002 Durham Meadows Waterline Remedial Design **ISSUED QA/QC DEFICIENCY** (Describe QA and QC Deficiency items issued) Item No Location Description No QC Deficiency items were issued today CORRECTED QA/QC DEFICIENCY (Report QC and QA Deficiency items corrected) Item No Location Description No QC Deficiency items were corrected today **CONTRACTORS ON SITE** (Report first and/or last day contractors were on site) Name First Day Last Day No Contractors had their first or last day on the site LABOR HOURS Number of Hours **Labor Classification Employer Employees** Worked TRUCK DRIVER, GROUP 1 Ludlow Construction Co., Inc. 1.0 8.0 24.0 Ludlow Construction Co., Inc. LABORER, GROUP 1 3.0 CIRCULAR SAW OPERATOR 0.0 0.0 Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. PROJECT MANAGER 0.0 0.0 Ludlow Construction Co., Inc. **OPERATOR HEAVY EQUIPMENT 1** 16.0 2.0 SSHO 8.0 Ludlow Construction Co., Inc. 1.0 QUALITY CONTROL SYSTEM MGR Ludlow Construction Co., Inc. 1.0 8.0 Total hrs worked to date: 36,040.5 Hrs worked MTD: 128.0 Total: 8.0 64.0 **EQUIPMENT HOURS** Idle Operating Serial Number Description Hours Hours TE-6 Ex TF-6 Volvo Billie 0.0 8.0 E-4 0336FCRAB E-4 Cat 336 Track Hoe 8.0 Jon 0.0 L-5 Cat 950K L-5 6.0 2.0 Billie T-77 PU T-77 PU Billy 0.0 8.0 E-9 Track Hoe E-9 336 Track Hoe Billy 6.0 2.0 T-64 Dump Truck T-64 0.0 8.0 B-5 Sweeper B-5 Sweeper Billie 0.0 8.0 T-84 PU T-84 PU Billy 80 0.0 E-8 E-8 Ex Pitt 8.0 0.0 L-10 Pitt L-10 Loader Pitt 8.0 0.0 Total operating hrs to date: 25.305.5 Idle hrs MTD: 88.0 Opr hrs MTD: 72.0 Total: 44.0 36.0 **MISHAP REPORTING** (Describe mishaps) No mishaps reported today CONTRACTOR CERTIFICATION On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above. QC REPRESENTATIVE'S SIGNATURE DATE SUPERINTENDENT'S INITIALS DATE