CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION		REPORT NUMBER Page 1 of 3			
		847			
		DATE			
		13 Apr 2021 - Tuesday			
PROJECT		CONTRACT NUMBER			
Durham Meadows Waterline Remedial Design		W912WJ19C0002			
CONTRACTOR	WEATHER				
Ludlow Construction Co., Inc.	Weather Caused No Delay Temperature Min 40 °F Max 67 °F				
	No Precipitation 8 MPH Wind				
QC NARRATIVES					
JOB SAFETY					
SAFETY: Ludlow Crew arrived at 7:00am, Departed at 3:00-3:30pm United Concrete departed at 5:00pm Barnhart crane departed at 4:00pm *SSHO Rob Peddicord: *Monitored 1 Ludlow crew continuing to work at the Booster Station; graded site, began excavating footings					
*United Concrete and Barnhart placed the Altitude Vault at the Water Tank site. =Safety/AHA meeting held before work began =SSHO verified rigging parts against data given in the approved crane lift plan =Also verified the listed personnel were operating and signaling the crane =SSHO reminded United Crane foreman Wayne Rivera of the hazards of the Sika Grout being used to seal the two Vault sections together. SSHO verified that the crew was equipped and trained in the use of respiratory protection while mixing the grout, per the site Respiratory Protection Program. Also reminded them to use the proper gloves to handle the material =Gave Barnhart crew Site Orientation, Covid Orientation, and Emergency Contact					
WORK PERFORMED TODAY					
WORK PERFORMED TODAY Onsite 7:00 AM ; Offsite 5:PM					
PERSONAL Superintendent 3 Operators 2 Labors 4 Truck Drivers 1					
VISITERS:					
SUBCONTRACTORS ON SITE: United Concrete - 4 Burnhart - 7					
WORK COMPLETED; Billy's Crew: Worked on the Booster Station. Ludlow encountered Water 1 feet below existing grade at the booster station. Pumps installed. Worked on Elevations. Excavated Water Line.					
Water Lines:					
QA/QC: . Preparatory Meeting for Altitude Vault QC Jerry Brandon, Rob Peddicord and QA Kurt Mintel Discussed Vault.					
Public Relations Coordinator:					
PREP/INITIAL DATES (Preparatory and initial date	es held and advan	nce notice)			
Preparatory Inspections held today Connections to Existing Burrie					
Initial Inspections held today					
No initial inspections held today			_		
ACTIVITY START/FINISH					
Activity No Description					

No activities were started or finished today

		REPORT NUMBER	Page 2 of 3	
CONTRACTORS QUALITY CONTROL REPORT (QCR)		847	Fage 2 01 5	
DAILY LO	OG OF CONSTRUCTION	DATE		
		13 Apr 2021 - Tue	esday	
PROJECT		CONTRACT NUMBER		
Durham Meadows Water	line Remedial Design	W912WJ19C0002	2	
QC REQUIREMENTS				
Requirement No Type	Description		Results	
No QC requirements were	completed today			
ISSUED QA/QC DEFICIENC	Y (Describe QA and QC Deficiency items i	ssued)		
Item No Location	Description			
No QC Deficiency items w	vere issued today			
CORRECTED QA/QC DEFIC	CIENCY (Report QC and QA Deficiency items con	rrected)		
Item No Location	Description			
No QC Deficiency items w	vere corrected today			
CONTRACTORS ON SITE	(Report first and/or last day contractors were	e on site)		
Name		First Day	Last Day	
		Filst Day	Last Day	
No Contractors had their	first or last day on the site			
LABOR HOURS				
Employer	Labor Classification		Number of Employees	Hours Worked
Ludlow Construction Co., Inc.	TRUCK DRIVER, GROUP 1		1.0	8.0
Ludlow Construction Co., Inc.	LABORER, GROUP 1		4.0	32.0
Ludlow Construction Co., Inc.	CIRCULAR SAW OPERATOR		0.0	0.0
Ludlow Construction Co., Inc.	PROJECT MANAGER		1.0	8.0
Ludlow Construction Co., Inc.	OPERATOR HEAVY EQUIPMENT 1		2.0	16.0
Ludlow Construction Co., Inc.	SSHO		1.0	8.0
Ludlow Construction Co., Inc.	QUALITY CONTROL SYSTEM MGR		1.0	8.0
Total hrs worked to date:	36,384.5 Hrs worked MTD: 47	72.0 Tota	l: 10.0	80.0
EQUIPMENT HOURS				
Serial Number	Description		Idle Hours	Operating Hours
TE-6 Ex	TE-6 Volvo Billie		4.0	4.0
E-4 0336FCRAB	E-4 Cat 336 Track Hoe Jon		8.0	0.0
L-5	Cat 950K L-5 Billie		0.0	8.0
T-77 PU	T-77 PU Billy		0.0	8.0
E-9 Track Hoe	E-9 336 Track Hoe Billy		4.0	4.0
T-64	Dump Truck T-64		0.0	8.0
B-5 Sweeper	B-5 Sweeper Billie		8.0	0.0
T-84 PU	T-84 PU Billy		0.0	8.0
E-8 Pitt	E-8 Ex		6.0	2.0
L-10 Pitt	L-10 Loader Pitt		6.0	2.0
E-19 Cat	E-19 Cat 314C Trackhoe Billy		4.0	4.0
R-4 Roller Billy	Roller Compacter Billy		6.0	2.0
LB - & Cat	LB-7 Cat 430E Backhoe Billy		6.0	2.0
Total operating hrs to date:	25,535.5 Idle hrs MTD: 290.0 Opr hr	rs MTD: 302.0	Total: 52.0	52.0
MISHAP REPORTING	(Describe mishaps)			

	REPORT NUMBER Page 3 of 3	
CONTRACTORS QUALITY CONTROL REPORT (QCR)	847	
DAILY LOG OF CONSTRUCTION	DATE	
	13 Apr 2021 - Tuesday	
PROJECT	CONTRACT NUMBER	
Durham Meadows Waterline Remedial Design	W912WJ19C0002	
No mishaps reported today		

CONTRACTOR CERTIFICATION

On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.

QC REPRESENTATIVE'S SIGNATURE	DATE	SUPERINTENDENT'S INITIALS	DATE