REPORT NUMBER Page 1 of 3 867 **CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION** DATE 03 May 2021 - Monday **PROJECT CONTRACT NUMBER** W912WJ19C0002 Durham Meadows Waterline Remedial Design **WEATHER** Weather Caused No Delay Ludlow Construction Co., Inc. Temperature Min 51 °F Max 71 °F 0.90 IN Precipitation 6 MPH Wind **QC NARRATIVES JOB SAFETY**

SAFETY:

Crews arrived at 7:00am, Departed at 3:00-3:30pm

*SSHO Rob Peddicord:

*Monitored Ludlow crew at Booster Tank; Continued footings install; poured approx 11cy of concrete

*Also poured a Thrust Block between the Water Tank and the Altitude Vault

*Weekly Safety Meeting: Power Tool Safety

*Received and filed crew paperwork: AHAs, Covid Self Cert, Daily Equipment Inspections

WORK PERFORMED TODAY

WORK PERFORMED TODAY Onsite 7:00 AM; Offsite 3:30 PM

PERSONAL Superintendent 3 Operators 2 Labors 4 Truck Drivers 1 VISITERS:0

visitors: ED from the EPA SUBCONTRACTORS: WORK COMPLETED;

Billy's Crew:

0088: Booster Station:

Concrete was placed at the booster station this date.

Concrete passed the sump test today

Concrete was placed.

pored fittings.

water tank and access road .drove thrust block.

started to put fitting together for 8" drain.

MISC work touch up work for seed

SUMP = 800 AVG IS 4.2

Touch up WS trench for house 166 and tractor work for 172 Maple.

QA/QC: .

QC was on site to watch concrete Being put in place and watched the testing process while it was done.

PREP/INITIAL DATES

(Preparatory and initial dates held and advance notice)

Preparatory Inspections held today

No preparatory inspections held today

Initial Inspections held today

Cast-in-Place Concrete

ACTIVITY START/FINISH

Activity No Description

No activities were started or finished today

QC REQUIREMENTS

Requirement No Type Description Results

No QC requirements were completed today

REPORT NUMBER Page 2 of 3 867 **CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION** DATE 03 May 2021 - Monday CONTRACT NUMBER **PROJECT** W912WJ19C0002 Durham Meadows Waterline Remedial Design **ISSUED QA/QC DEFICIENCY** (Describe QA and QC Deficiency items issued) Description Item No Location No QC Deficiency items were issued today **CORRECTED QA/QC DEFICIENCY** (Report QC and QA Deficiency items corrected) Item No Location Description No QC Deficiency items were corrected today **CONTRACTORS ON SITE** (Report first and/or last day contractors were on site) Name First Day Last Day No Contractors had their first or last day on the site **LABOR HOURS** Number of Hours **Labor Classification Employer Employees** Worked TRUCK DRIVER, GROUP 1 Ludlow Construction Co., Inc. 1.0 8.0 16.0 Ludlow Construction Co., Inc. LABORER, GROUP 1 2.0 Ludlow Construction Co., Inc. CIRCULAR SAW OPERATOR 0.0 0.0 Ludlow Construction Co., Inc. PROJECT MANAGER 1.0 8.0 Ludlow Construction Co., Inc. **OPERATOR HEAVY EQUIPMENT 1** 16.0 2.0 SSHO 8.0 Ludlow Construction Co., Inc. 1.0 Ludlow Construction Co., Inc. QUALITY CONTROL SYSTEM MGR 8.0 1.0 Ludlow Construction Co., Inc. CEMENT HANDLER 10 8.0 37,500.5 72.0 Total hrs worked to date: Hrs worked MTD: 72.0 Total: 9.0 **EQUIPMENT HOURS** Idle Operating Serial Number Description Hours Hours TE-6 Ex Off Site TE-6 Volvo 0.0 0.0 E-4 0336FCRAB E-4 Cat 336 Track Hoe Off Site 8.0 0.0 L-5 Cat 950K L-5 Billie 0.0 8.0 E-19 Cat E-19 Cat 314C Trackhoe Billy 0.0 8.0 T-77 PU T-77 PU Billy 0.0 8.0 T-27 Dump Billy 8.0 T-27 Dump 0.0 E-9 Track Hoe E-9 336 Track Hoe 8.0 0.0 Billy LB - & Cat LB-7 Cat 430E Backhoe 2.0 Billy 6.0 T-64 Dump Truck T-64 0.0 8.0 R-4 Roller Billy Roller Compacter Billy 6.0 20 TE 15 Excavator TE-15 Track Hoe Billy 0.0 8.0 T-84 PU T-84 PU Billy 0.0 8.0 F-8 Pitt E-8 Ex 6.0 2.0 L-10 Pitt L-10 Loader Pitt 6.0 2.0

MISHAP REPORTING

Total operating hrs to date:

(Describe mishaps)

Idle hrs MTD:

40.0

Opr hrs MTD:

64.0

Total:

40.0

64.0

26,311.5

No mishaps reported today

			REPORT NUMBER	Dogo	2 of 2						
CONTRACTORS QUALITY CONTROL RED DAILY LOG OF CONSTRUCTION		EPORT (QCR)	867	rage	3 of 3						
DAILT LOC	OF CONSTRUCTION	/IN	DATE								
			03 May 2021 - Mond	lay							
PROJECT			CONTRACT NUMBER								
Durham Meadows Waterli	ne Remedial Design		W912WJ19C0002								
CONTRACTOR CERTIFICATION On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract plans and specifications, to the best of my knowledge, except as noted above.											
						QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE
						GO NEI NEGENTATIVE O OIGNATURE	-	DAIL	COLEMNATE NO ENTRACE		DAIL