REPORT NUMBER Page 1 of 3 1,008 **CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION** DATE 21 Sep 2021 - Tuesday **PROJECT CONTRACT NUMBER** W912WJ19C0002 Durham Meadows Waterline Remedial Design WEATHER Ludlow Construction Co., Inc. Weather Caused No Delay Temperature Min 49 °F Max 74 °F No Precipitation 3 MPH Wind

QC NARRATIVES

JOB SAFETY

SAFETY:

Crews arrived at 7:00am, Departed at 3:00pm

- *SSHO Rob Peddicord monitored safety and environmental protocols for Ludlow, Fazzino Plumbing, and A&R Electric
- *Ludlow crew worked at 298, 312 Main St; also poured concrete at Booster Sta and Meter Vault
- *A&R Electric worked at Booster Station, then Meter Vault
- *Fazzino Plumbing worked at Booster Sta
- *John Turner Testing also on site to test the concrete
- *GENERAL SAFETY: All persons wearing required PPE for the given task, Safety procedures being followed, AHAs being followed
- *TRAFFIC: Two lane traffic maintained on Rt 17; one CTC flagger used; certs verified
- *LIFTING SAFETY: No lift plan required on this date
- *TRENCHING: Trench safety protocols followed; trench either benched back or trench box used, ladder available every 25ft or trench not entered.

House Installs: Long sections of copper pipe able to be placed in trench without persons entering the trench.

*CUTTING SAFETY: No cutting on this date

WORK PERFORMED TODAY

WORK PERFORMED TODAY Onsite 7:00 AM; Offsite 3:30 PM

PERSONEL: Superintendent 1 Operators 2 Labors 3 Truck Drivers 1 VISITERS:

A&R Electric 1 Fazzino 1 Flagger 1

BILLY'S CREW: House 298 Main Street:

0034 1 Inch Copper = 34.0oot of 1" Copper was installed

House 312 Main Street:

0034 1 Inch Copper = 22.0 Foot of 1" Copper was Installed

0054 Rock and Boulder = 6.66 CYs Was Removed

0034 1 Inch Copper Total = 56 LF

Fazzino installed gas line at Booster Station

A&R installed conduit to new poles

QA/QC:

QA Kurt Mintell discussed Concrete Pour was Discussed with QC Jerry Brandon and Safety Officer Rob Peddicord

PREP/INITIAL DATES

(Preparatory and initial dates held and advance notice)

Preparatory Inspections held today

No preparatory inspections held today

Initial Inspections held today

No initial inspections held today

ACTIVITY START/FINISH

Activity No Description

No activities were started or finished today

QC REQUIREMENTS

Requirement No	Туре	Description	Results
CT-00318	QC Test	Concrete Pour at Booster and Meter Vault Slump 7 Air 5.2	Awaiting Results

ISSUED QA/QC DEFICIENCY

(Describe QA and QC Deficiency items issued)

Item No Location Description

CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION PROJECT Durham Meadows Waterline Remedial Design REPORT NUMBER 1,008 DATE 21 Sep 2021 - Tuesday CONTRACT NUMBER W912WJ19C0002

No QC Deficiency items were issued today

CORRECTED QA/QC DEFICIENCY (Report QC and QA Deficiency items corrected)

Item No Location Description

No QC Deficiency items were corrected today

CONTRACTORS ON SITE (Report first and/or last day contractors were on site)

Name First Day Last Day

No Contractors had their first or last day on the site

LABOR HOURS Employer	Labor Classi	fication			lumber of mployees	Hours Worked
Ludlow Construction Co., Inc.	TRUCK DRI	TRUCK DRIVER, GROUP 1			1.0	8.0
Ludlow Construction Co., Inc.	LABORER,	GROUP 1			3.0	24.0
Ludlow Construction Co., Inc.	CIRCULAR	SAW OPERATOR			0.0	0.0
Ludlow Construction Co., Inc.	PROJECT M	MANAGER			1.0	8.0
Ludlow Construction Co., Inc.	OPERATOR	HEAVY EQUIPMENT 1			2.0	16.0
Ludlow Construction Co., Inc.	SSHO				1.0	8.0
Ludlow Construction Co., Inc.	QUALITY CO	ONTROL SYSTEM MGR			1.0	8.0
Total hrs worked to date:	45,929.5	Hrs worked MTD:	1,236.0	Total:	9.0	72.0

EQUIPMENT HOURS		Idle	Operating
Serial Number	Description	Hours	Hours
531660128	Bobcat Skidsteer S-2 Billy	6.0	2.0
L-5	Cat 950K L-5 Billie	6.0	2.0
E-19 Cat	E-19 Cat 314C Trackhoe Billy	8.0	0.0
T-77 PU	T-77 PU Billy	0.0	8.0
T-27 Dump	T-27 Dump Billy	8.0	0.0
E-9 Track Hoe	E-9 336 Track Hoe Jon	8.0	0.0
LB - & Cat	LB-8 Cat 430E Backhoe Billy	8.0	0.0
T-64	Dump Truck T-64	0.0	8.0
T-65	Ludlow Pickup Truck T-65	6.0	2.0
B-5 Sweeper	B-5 Sweeper Billie	6.0	2.0
R-4 Roller Billy	Roller Compacter Billy	8.0	0.0
TE 15 Excavator	TE-15 Track Hoe Billy	4.0	4.0
T-84 PU	T-84 PU Billy	8.0	0.0
T-86	T-86 Dump Truck Billy	0.0	8.0
L-10 Pitt	L-10 Loader Pitt	6.0	2.0
E-14 Excavator	E-14 EX	4.0	4.0
Total operating hrs to date:	31,471.5 Idle hrs MTD: 1,138.0 Opr hrs MTD: 654.0	Total: 86.0	42.0

MISHAP REPORTING

(Describe mishaps)

No mishaps reported today

	LITY CONTROL REPORT (OCR)		REPORT NUMBER Page 3 of		2 of 2
CONTRACTORS QUALITY CONT		PORT (QCR)	1,008	rage	3 01 3
DAILY LOG OF CONST	RUCTIO	N	DATE		
2 2000. 00101			21 Sep 2021 - Tues	dav	
PROJECT			CONTRACT NUMBER	чиу	
	Decian		W912WJ19C0002		
Durham Meadows Waterline Remedial	Design		VV912VVJ19C0002		
CONTRACTOR CERTIFICATION On behalf of the contractor, I certify that this Report is complete and correct and all equipment and material used and work performed during this Reporting period are in compliance with the contract					
					e with the contract
plans and spe	cifications	s, to the best of my kno	owledge, except as noted abo	ve.	
QC REPRESENTATIVE'S SIGNATURE		DATE	SUPERINTENDENT'S INITIALS		DATE