

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	October 20, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Sunday
Project #:	AECOM: 60445033	Report No:	15
Contractor:	Ludlow Construction	Page:	2 of 7

Payment Items:



Figure 1 – Backfill pile before Sta. 122+92

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	October 20, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Sunday
Project #:	AECOM: 60445033	Report No:	15
Contractor:	Ludlow Construction	Page:	3 of 7




Figure 2 –Plate compacting over 1st-2nd pipe sections

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	October 20, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Sunday
Project #:	AECOM: 60445033	Report No:	15
Contractor:	Ludlow Construction	Page:	4 of 7




Figure 3 – Attaching 3rd pipe section

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	October 20, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Sunday
Project #:	AECOM: 60445033	Report No:	15
Contractor:	Ludlow Construction	Page:	5 of 7




Figure 4 – Cutting service connection on 7th section

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	October 20, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Sunday
Project #:	AECOM: 60445033	Report No:	15
Contractor:	Ludlow Construction	Page:	6 of 7



Figure 5 – 8th section with bedding and warning tape laid overtop

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	October 20, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Sunday
Project #:	AECOM: 60445033	Report No:	15
Contractor:	Ludlow Construction	Page:	7 of 7




Figure 6 – Compacting 2nd lift above 1st-6th sections