



# AECOM

## Daily Report

<b>Project:</b>	Durham Meadows Pipeline Installation	<b>Date:</b>	October 28, 2019
<b>Location:</b>	South Main Street, Middletown CT	<b>Day of Week:</b>	Monday
<b>Project #:</b>	AECOM: 60445033	<b>Report No:</b>	19
<b>Contractor:</b>	Ludlow Construction	<b>Page:</b>	2 of 6

### Payment Items:

**Res. Representative:**

F. Grimberg

**Date:** 10/28/19

## Daily Report

<b>Project:</b>	Durham Meadows Pipeline Installation	<b>Date:</b>	October 28, 2019
<b>Location:</b>	South Main Street, Middletown CT	<b>Day of Week:</b>	Monday
<b>Project #:</b>	AECOM: 60445033	<b>Report No:</b>	19
<b>Contractor:</b>	Ludlow Construction	<b>Page:</b>	3 of 6



Figure 1 – 2<sup>nd</sup> section being placed, 12” RCP storm drain at Sta. 135+59



## Daily Report

<b>Project:</b>	Durham Meadows Pipeline Installation	<b>Date:</b>	October 28, 2019
<b>Location:</b>	South Main Street, Middletown CT	<b>Day of Week:</b>	Monday
<b>Project #:</b>	AECOM: 60445033	<b>Report No:</b>	19
<b>Contractor:</b>	Ludlow Construction	<b>Page:</b>	4 of 6




Figure 2 –Backfill pile at Sta. 133+22



## Daily Report

<b>Project:</b>	Durham Meadows Pipeline Installation	<b>Date:</b>	October 28, 2019
<b>Location:</b>	South Main Street, Middletown CT	<b>Day of Week:</b>	Monday
<b>Project #:</b>	AECOM: 60445033	<b>Report No:</b>	19
<b>Contractor:</b>	Ludlow Construction	<b>Page:</b>	5 of 6



Figure 3 – Removing backfill over sections 1-2



## Daily Report

<b>Project:</b>	Durham Meadows Pipeline Installation	<b>Date:</b>	October 28, 2019
<b>Location:</b>	South Main Street, Middletown CT	<b>Day of Week:</b>	Monday
<b>Project #:</b>	AECOM: 60445033	<b>Report No:</b>	19
<b>Contractor:</b>	Ludlow Construction	<b>Page:</b>	6 of 6



Figure 4 – Trenching for 5<sup>th</sup> section, 4<sup>th</sup> section laid with compacted bedding and warning tape laid overtop