



# AECOM

## Daily Report

<b>Project:</b>	Durham Meadows Pipeline Installation	<b>Date:</b>	November 11, 2019
<b>Location:</b>	South Main Street, Middletown CT	<b>Day of Week:</b>	Monday
<b>Project #:</b>	AECOM: 60445033	<b>Report No:</b>	26
<b>Contractor:</b>	Ludlow Construction	<b>Page:</b>	2 of 7

- Placing, compacting pipe bedding, and laying warning tape  
2215 - 7th pipe section in  
- Placing, compacting pipe bedding, and laying warning tape  
2225 - processed stone placed over pipe sections 1-3  
2240 - laying stone bedding and geotextile under 8th section  
- compacting backfill over pipe sections 5-7  
2250 - 8th pipe section in  
- Placing, compacting pipe bedding, and laying warning tape  
2300 - lunch break, leaving site now

### Payment Items:

**Res. Representative:**

F. Grimberg

**Date:** 11/11/19

## Daily Report

<b>Project:</b>	Durham Meadows Pipeline Installation	<b>Date:</b>	November 11, 2019
<b>Location:</b>	South Main Street, Middletown CT	<b>Day of Week:</b>	Monday
<b>Project #:</b>	AECOM: 60445033	<b>Report No:</b>	26
<b>Contractor:</b>	Ludlow Construction	<b>Page:</b>	3 of 7



Figure 1 – First pipe section in place, placing pipe bedding

## Daily Report

<b>Project:</b>	Durham Meadows Pipeline Installation	<b>Date:</b>	November 11, 2019
<b>Location:</b>	South Main Street, Middletown CT	<b>Day of Week:</b>	Monday
<b>Project #:</b>	AECOM: 60445033	<b>Report No:</b>	26
<b>Contractor:</b>	Ludlow Construction	<b>Page:</b>	4 of 7



Figure 2 – Backfill piles near Sta. 145+38

## Daily Report

<b>Project:</b>	Durham Meadows Pipeline Installation	<b>Date:</b>	November 11, 2019
<b>Location:</b>	South Main Street, Middletown CT	<b>Day of Week:</b>	Monday
<b>Project #:</b>	AECOM: 60445033	<b>Report No:</b>	26
<b>Contractor:</b>	Ludlow Construction	<b>Page:</b>	5 of 7




Figure 3 – Spreading, compacting first backfill lift over pipe sections 1-3

## Daily Report

<b>Project:</b>	Durham Meadows Pipeline Installation	<b>Date:</b>	November 11, 2019
<b>Location:</b>	South Main Street, Middletown CT	<b>Day of Week:</b>	Monday
<b>Project #:</b>	AECOM: 60445033	<b>Report No:</b>	26
<b>Contractor:</b>	Ludlow Construction	<b>Page:</b>	6 of 7



Figure 4 – Backfill pile near Sta. 146+00

## Daily Report

<b>Project:</b>	Durham Meadows Pipeline Installation	<b>Date:</b>	November 11, 2019
<b>Location:</b>	South Main Street, Middletown CT	<b>Day of Week:</b>	Monday
<b>Project #:</b>	AECOM: 60445033	<b>Report No:</b>	26
<b>Contractor:</b>	Ludlow Construction	<b>Page:</b>	7 of 7




Figure 5 – Processed stone layer above pipe sections 1-3