

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 18, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Monday
Project #:	AECOM: 60445033	Report No:	30
Contractor:	Ludlow Construction	Page:	2 of 7

2300 – break time
- Leaving site now

Payment Items:

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 18, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Monday
Project #:	AECOM: 60445033	Report No:	30
Contractor:	Ludlow Construction	Page:	3 of 7




Figure 1 – Preparing to place 2nd pipe section

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 18, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Monday
Project #:	AECOM: 60445033	Report No:	30
Contractor:	Ludlow Construction	Page:	4 of 7



Figure 2 – Storm drain, rusted through, near Sta. 154+08

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 18, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Monday
Project #:	AECOM: 60445033	Report No:	30
Contractor:	Ludlow Construction	Page:	5 of 7



Figure 3 – Backfill pile

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 18, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Monday
Project #:	AECOM: 60445033	Report No:	30
Contractor:	Ludlow Construction	Page:	6 of 7



Figure 4 – Storm drain wrapped in fabric, bedding being placed over pipes

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 18, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Monday
Project #:	AECOM: 60445033	Report No:	30
Contractor:	Ludlow Construction	Page:	7 of 7



Figure 5 – Compacted 2nd backfill lift over pipe sections 1-3