

AECOM

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 3, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Sunday
Project #:	AECOM: 60445033	Report No:	21
Contractor:	Ludlow Construction	Page:	2 of 7

2300 – leaving site now

Payment Items:

Res. Representative:

F. Grimberg

Date: 11/3/19

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 3, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Sunday
Project #:	AECOM: 60445033	Report No:	21
Contractor:	Ludlow Construction	Page:	3 of 7



Figure 1 – Backfill pile just before trench start at Sta. 137+72

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 3, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Sunday
Project #:	AECOM: 60445033	Report No:	21
Contractor:	Ludlow Construction	Page:	4 of 7



Figure 2 –Blow-off and Drain Tee section above ground

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 3, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Sunday
Project #:	AECOM: 60445033	Report No:	21
Contractor:	Ludlow Construction	Page:	5 of 7



Figure 3 – Placing Tee section for blow-off and drain manhole at Sta. 137+73

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 3, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Sunday
Project #:	AECOM: 60445033	Report No:	21
Contractor:	Ludlow Construction	Page:	6 of 7



Figure 4 – Compaction testing 1st backfill lift above Tee section

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 3, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Sunday
Project #:	AECOM: 60445033	Report No:	21
Contractor:	Ludlow Construction	Page:	7 of 7



Figure 5 – 2nd pipe section attached, preparing to place, compact pipe bedding and lay warning tape