

AECOM

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 5, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Tuesday
Project #:	AECOM: 60445033	Report No:	24
Contractor:	Ludlow Construction	Page:	2 of 8

2305 – leaving site now

Payment Items:

Res. Representative:

F. Grimberg

Date: 11/5/19

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 5, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Tuesday
Project #:	AECOM: 60445033	Report No:	24
Contractor:	Ludlow Construction	Page:	3 of 8



Figure 1 – Valve section to be placed at Sta. 141+23 (Little Lane & Oak Terrace)

Daily Report

Project: Durham Meadows Pipeline Installation
Location: South Main Street, Middletown CT
Project #: AECOM: 60445033
Contractor: Ludlow Construction

Date: November 5, 2019
Day of Week: Tuesday
Report No: 24
Page: 4 of 8




Figure 2 – Taking survey point of placed valve section in trench

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 5, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Tuesday
Project #:	AECOM: 60445033	Report No:	24
Contractor:	Ludlow Construction	Page:	5 of 8




Figure 3 – Attaching 1st pipe section to valve section, pipe bedding partially laid

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 5, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Tuesday
Project #:	AECOM: 60445033	Report No:	24
Contractor:	Ludlow Construction	Page:	6 of 8



Figure 4 – Placing 2nd pipe section (Note manual air release in foreground)

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 5, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Tuesday
Project #:	AECOM: 60445033	Report No:	24
Contractor:	Ludlow Construction	Page:	7 of 8



Figure 5 – Compacting 1st backfill lift

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 5, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Tuesday
Project #:	AECOM: 60445033	Report No:	24
Contractor:	Ludlow Construction	Page:	8 of 8




Figure 6 – 3” minus backfill pile dumped next to trench