

AECOM

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 6, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Wednesday
Project #:	AECOM: 60445033	Report No:	25
Contractor:	Ludlow Construction	Page:	2 of 6

- Placing, compacting pipe bedding and laying warning tape
- 2300 – workers taking lunch break
- Leaving site now

Payment Items:

Res. Representative:	F. Grimberg	Date:	11/6/19
-----------------------------	-------------	--------------	---------

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 6, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Wednesday
Project #:	AECOM: 60445033	Report No:	25
Contractor:	Ludlow Construction	Page:	3 of 6




Figure 1 – End of water main at Sta. 143+17, ready to place 1st pipe section

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 6, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Wednesday
Project #:	AECOM: 60445033	Report No:	25
Contractor:	Ludlow Construction	Page:	4 of 6



Figure 2 – Native backfill pile dumped at Sta. 143+17

Daily Report

Project: Durham Meadows Pipeline Installation
Location: South Main Street, Middletown CT
Project #: AECOM: 60445033
Contractor: Ludlow Construction

Date: November 6, 2019
Day of Week: Wednesday
Report No: 25
Page: 5 of 6



Figure 3 – Attaching 3rd pipe section

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	November 6, 2019
Location:	South Main Street, Middletown CT	Day of Week:	Wednesday
Project #:	AECOM: 60445033	Report No:	25
Contractor:	Ludlow Construction	Page:	6 of 6




Figure 4 – Attaching 6th pipe section, 5th section passes under storm drain seen at bottom of picture