

AECOM

Daily Report

| | | | |
|--------------------|---|---------------------|---------------|
| Project: | Durham Meadows Pipeline Installation | Date: | April 2, 2020 |
| Location: | Packinghouse Hill Road, Water tank, Durham & Middletown, CT | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 53 |
| Contractor: | Ludlow Construction | Page: | 2 of 11 |

0945: Ludlow is connecting a 20' section of 8" DIP" to the 10' section that was just installed.

1108: Ludlow is connecting a second 20' section of DIP" to the 20' section that was just installed.

1152: Ludlow is connecting a 12.5' section of DIP" to the second 20' section that was just installed.

1230 Ludlow making the transition from 8" DIP to 6" DIP using a T-fitting and a valve assembly.

1315: Ludlow installing valve box over the valve stem.

1405: Trench at Packinghouse Hill Road has been backfilled compacted, and covered with hot patch.

Payment Items:

Res. Representative:

J. Meunier

Date: 4/2/20

Daily Report

| | | | |
|--------------------|---|---------------------|---------------|
| Project: | Durham Meadows Pipeline Installation | Date: | April 2, 2020 |
| Location: | Packinghouse Hill Road, Water tank, Durham & Middletown, CT | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 53 |
| Contractor: | Ludlow Construction | Page: | 3 of 11 |



Picture 1: Call-before-you-dig markings, made after Comcast lines were severed during the installation of a fire hydrant assembly on Royal Oak Drive.

| | | | |
|-----------------------------|------------|--------------|--------|
| Res. Representative: | J. Meunier | Date: | 4/2/20 |
|-----------------------------|------------|--------------|--------|

Daily Report

| | | | |
|--------------------|---|---------------------|---------------|
| Project: | Durham Meadows Pipeline Installation | Date: | April 2, 2020 |
| Location: | Packinghouse Hill Road, Water tank, Durham & Middletown, CT | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 53 |
| Contractor: | Ludlow Construction | Page: | 4 of 11 |



Picture 2: Paint identifying location of 16" gas line that runs under the northbound lane of Main Street (at the intersection of Main and Royal Oak Drive).

| | | | |
|-----------------------------|------------|--------------|--------|
| Res. Representative: | J. Meunier | Date: | 4/2/20 |
|-----------------------------|------------|--------------|--------|

Daily Report

| | | | |
|--------------------|---|---------------------|---------------|
| Project: | Durham Meadows Pipeline Installation | Date: | April 2, 2020 |
| Location: | Packinghouse Hill Road, Water tank, Durham & Middletown, CT | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 53 |
| Contractor: | Ludlow Construction | Page: | 5 of 11 |



Picture 3: Call-before-you-dig mark out of utilities on the water tank access road. View to the southeast.

| | | | |
|-----------------------------|------------|--------------|--------|
| Res. Representative: | J. Meunier | Date: | 4/2/20 |
|-----------------------------|------------|--------------|--------|

Daily Report

| | | | |
|--------------------|---|---------------------|---------------|
| Project: | Durham Meadows Pipeline Installation | Date: | April 2, 2020 |
| Location: | Packinghouse Hill Road, Water tank, Durham & Middletown, CT | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 53 |
| Contractor: | Ludlow Construction | Page: | 6 of 11 |



Picture 4: 20" DIP being staged next to silt fence along the water tank access road in preparation for upcoming installation.

| | | | |
|-----------------------------|------------|--------------|--------|
| Res. Representative: | J. Meunier | Date: | 4/2/20 |
|-----------------------------|------------|--------------|--------|

Daily Report

| | | | |
|--------------------|---|---------------------|---------------|
| Project: | Durham Meadows Pipeline Installation | Date: | April 2, 2020 |
| Location: | Packinghouse Hill Road, Water tank, Durham & Middletown, CT | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 53 |
| Contractor: | Ludlow Construction | Page: | 7 of 11 |



Picture 5: Ludlow excavators being used at the water tank pad area.

| | | | |
|-----------------------------|------------|--------------|--------|
| Res. Representative: | J. Meunier | Date: | 4/2/20 |
|-----------------------------|------------|--------------|--------|

Daily Report

| | | | |
|--------------------|---|---------------------|---------------|
| Project: | Durham Meadows Pipeline Installation | Date: | April 2, 2020 |
| Location: | Packinghouse Hill Road, Water tank, Durham & Middletown, CT | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 53 |
| Contractor: | Ludlow Construction | Page: | 8 of 11 |



Picture 6: Overview of land clearing at the water tank pad and access road. View to the north/northwest.

| | | | |
|-----------------------------|------------|--------------|--------|
| Res. Representative: | J. Meunier | Date: | 4/2/20 |
|-----------------------------|------------|--------------|--------|

Daily Report

| | | | |
|--------------------|---|---------------------|---------------|
| Project: | Durham Meadows Pipeline Installation | Date: | April 2, 2020 |
| Location: | Packinghouse Hill Road, Water tank, Durham & Middletown, CT | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 53 |
| Contractor: | Ludlow Construction | Page: | 9 of 11 |



Picture 7: View of 6" DIP and valve assembly at the Packinghouse Hill Road fire hydrant assembly installation.

| | | | |
|-----------------------------|------------|--------------|--------|
| Res. Representative: | J. Meunier | Date: | 4/2/20 |
|-----------------------------|------------|--------------|--------|

Daily Report

| | | | |
|--------------------|---|---------------------|---------------|
| Project: | Durham Meadows Pipeline Installation | Date: | April 2, 2020 |
| Location: | Packinghouse Hill Road, Water tank, Durham & Middletown, CT | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 53 |
| Contractor: | Ludlow Construction | Page: | 10 of 11 |



Picture 8: Valve stem extension and fire hydrant assembly installed.

| | | | |
|-----------------------------|------------|--------------|--------|
| Res. Representative: | J. Meunier | Date: | 4/2/20 |
|-----------------------------|------------|--------------|--------|

Daily Report

| | | | |
|--------------------|---|---------------------|---------------|
| Project: | Durham Meadows Pipeline Installation | Date: | April 2, 2020 |
| Location: | Packinghouse Hill Road, Water tank, Durham & Middletown, CT | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 53 |
| Contractor: | Ludlow Construction | Page: | 11 of 11 |



Picture 9: Caution tape placed over installed pipe. Valve box about to be installed over valve stem.

| | | | |
|-----------------------------|------------|--------------|--------|
| Res. Representative: | J. Meunier | Date: | 4/2/20 |
|-----------------------------|------------|--------------|--------|