Daily Report

Project: Date: July 13, 2020 **Durham Meadows Pipeline Installation** Day of Week: Monday Location: Pickett Lane and Main Street, Durham Project #: AECOM: 6061487 **Report No:** 118 **Contractor: Ludlow Construction** Page: 1 of 9

Weather Conditions

Conditions: Daylight hours. Partly sunny. Winds variable 0-9 mph.

Temperature (°F): High 86°F Low 65°F

	Contra			
Trade		#	x	hrs
USACE				
Field Engineer		1	Х	8

Subco	ubcontractors Workforce				
rs	Trade	#	Х	hrs	
	Ludlow Construction				
3	Superintendent	0	Х	8	
	Safety Officer	1	Х	8	
	Foreman	2	Х	8	
	Dump truck Operator	4	Х	8	
	Excavator Operator	4	Х	8	
	Skid Steer/Bucket Loader	1	Х	8	
	Laborers	6	Χ	8	
	Note that some persons				
	Multiple pieces equipment.				
	Sub-contractor	3	Χ	8	
	Municipal Police Detail	0	Χ	8	
	State Police Detail	0	Χ	8	

Equipment in Use			
Туре	#	х	hr
Concrete/Asphalt Road Saw	1	Х	8
Dump truck	5	Х	8
Excavator – Large	3	Х	8
Excavator - Mid-Size	1	Х	8
Excavator - Rubber Wheeled – Rock	0	Х	8
Skid Steer / Bucket Loader	1	Х	8
Rolling Compactor	1	Х	8
Plate Compactor	1	Х	8
Jumping Jack Compactor	1	Х	8
Street Sweeper (Broce Broom)	1	Х	8
Material Hopper	1	Х	8
Pipe saw	1	Х	8
Light Tower	0	Х	8

Visitors: None.

Pipe Connections, Installations, and Other Work

Ludlow continued work on the stream crossing on Pickett Lane at Station ~511+00.

Ludlow installed curb stops today on the east side of Main Street at Stations 160+95, 162+09, 163+01.

Ludlow chlorinated the Main Street water line from Marina Place to Old Cemetery Road.

Compaction Testing

Soil compaction testing was not performed today. Compaction test data for the project can be found here:

https://www.nae.usace.army.mil/Portals/74/docs/Topics/DurhamMeadowsWaterline/CompactionTests/

In addition, soil compaction data is presented in the Contractor Daily Quality Control Reports located here:

Res. Representative:	J. Meunier	Date:	7/13/20



Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	July 13, 2020
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	118
Contractor:	Ludlow Construction	Page:	2 of 9

https://www.nae.usace.army.mil/Missions/Projects-Topics/Durham-Meadows-Water-Lines-Project/

Daily Activities - Stream Crossing, Pickett Lane, Durham

Ludlow continued work on the stream crossing on Pickett Lane at Station \sim 511+00.

0710: Ludlow is mobilizing at the stream crossing at Station $^{\sim}$ 511+00.

0740 Ludlow is excavating on east side of Allyn Brook to connect the 12" DIP coming off the stream crossing to the pipe that was previously is installed on Pickett Lane.

0746: Ludlow is installing a 15' section of 12" DIP east of Allyn Brook, moving towards Pickett Lane.

0818: Ludlow is working to the east of Allyn Brook looking to daylight utilities near the edge of Pickett Lane.

0831: Ludlow is excavating to the east towards Pickett Lane as they continue to place 12" DIP. They are about to install a 20' section of 12" DIP.

0904: Ludlow is daylighting the 12" gate valve at Station 512+02.

0913: Ludlow is installing a 20' section of 12" DIP east of Allyn Brook at Station \sim 511+50 on Pickett Lane.

0955: Ludlow has just installed a 6'10" piece of 12" DIP coming off the gate valve at Station 512+02. Ludlow also installed a 45° bend to the 6'10" piece of 12" DIP.

1137: Ludlow has connected opposing ends of pipe just west of Station 512+02 with a 10' 2" section of 12" DIP that was cut in half to place in trench. The two pieces of DIP were then connected with a 12" sleeve and megalug connections.

1235: Ludlow is cleaning up the stream crossing work area at Station ~511+00 on Pickett Lane.

Daily Activities – Installation of Curb Stops, Durham

Ludlow installed curb stops today on the east side of Main Street at Stations 160+95, 162+09, 163+01.

0714: Ludlow is setting up Station 160+95 on the northbound lane of Main St., Durham. One Ludlow laborer and one private flagger are providing traffic management.

0805: Ludlow is excavating on the northbound side of Main Street, installing a curb stop at 395 Main Street. The curb stop will be located 16' from edge of pavement. A moderately strong odor of naphthalene is coming from the excavated soils. An Eversource representative is present watching the excavation.

0848: Ludlow is beginning to excavate at Station 162+09 on the northbound lane of Main Street to install a curb stop at 391 Main Street. The curb stop will be located 14.5 feet from the edge of pavement.

0945: Ludlow continues to install a curb stop at 391 Main Street, Durham.

1054: Ludlow is excavating at Station 163+01 to install a curb stop at 385 Main Street. The curb stop will be installed 14 feet from

Res. Representative:	J. Meunier	Date:	7/13/20



Daily Report				
Project:	Durham Meadows Pipeline Installation	Date:	July 13, 2020	
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Monday	
Project #:	AECOM: 6061487	Report No:	118	
Contractor:	Ludlow Construction	Page:	3 of 9	
edge of pavement.	Ludlow is backfilling at Station 162+09.			
-	paring to tap the main waterline at Station 2 n for 385 Main Street. Several spots in the tr		_	
1347: Ludlow has f to close up the trer	nished backfilling all three trenches for the or th	urb stops on Main Street. Ludlow is waitii	ng for hot patch to arrive	
Daily Activities – C	nlorination of Water Line, Durham			
Ludlow chlorinated	the Main Street water line from Marina Plac	e to Old Cemetery Road.		
	rking with Superior Special Services to chlori eding the hydrant at the intersection of Talc ne water.		= 1	
•	ening a hydrant at Station 183+60 as part of ng used to chlorinate the water line further r			
	liddletown has one of their personnel station onitoring water pressure on the waterline to			
.225: Ludlow continues with water line chlorination activities on Main Street.				
1350: Ludlow conti	nues with water line chlorination activities o	n Main Street.		

J. Meunier Res. Representative: **Date:** 7/13/20

Daily Report

July 13, 2020 Date: Project: **Durham Meadows Pipeline Installation** Day of Week: Monday Location: Pickett Lane and Main Street, Durham **Report No:** 118 Project #: AECOM: 6061487 **Contractor: Ludlow Construction** Page: 4 of 9



Picture 1: Ludlow installing 12" DIP to the east of Allyn Brook. They are placing the next 20' section in the direction of Pickett Lane, which can be seen in the background. View is to the southeast, looking towards Station 512+00.

Res. Representative: J. Meunier Date: 7/13/20

Daily Report

Date: July 13, 2020 Project: **Durham Meadows Pipeline Installation** Day of Week: Monday Location: Pickett Lane and Main Street, Durham **Report No:** 118 Project #: AECOM: 6061487 **Contractor: Ludlow Construction** Page: **5** of **9**



Picture 2: Ludlow venting the hydrant at the intersection of Talcott Lane and Main Street, Durham, as part of water line chlorination activities. View to the northwest.

Res. Representative: J. Meunier Date: 7/13/20

Daily Report

Project: Date: July 13, 2020 **Durham Meadows Pipeline Installation** Day of Week: Monday Location: Pickett Lane and Main Street, Durham **Report No:** 118 Project #: AECOM: 6061487 **Contractor: Ludlow Construction** Page: **6** of **9**



Picture 3: Subsurface utilities daylighted by Ludlow as they excavated near Station 512+00 while installing 12" DIP. Pickett Lane, Durham.

Res. Representative:	J. Meunier	Date: _7/13/20

Daily Report

July 13, 2020 Durham Meadows Pipeline Installation Date: Project: Day of Week: Monday Location: Pickett Lane and Main Street, Durham **Report No:** 118 Project #: AECOM: 6061487 **Contractor: Ludlow Construction** Page: **7** of **9**



Picture 4: The intersection of Marina Place and Main Street where a 12.5% solution of sodium hypochlorite is introduced into the Main Street water line as part of chlorination activities. View to the south.

Res. Representative: J. Meunier Date: 7/13/20

Daily Report

Project: Date: July 13, 2020 **Durham Meadows Pipeline Installation** Day of Week: Monday Location: Pickett Lane and Main Street, Durham **Report No:** 118 Project #: AECOM: 6061487 **Contractor: Ludlow Construction** Page: 8 of 9




Picture 5: Water observed in trench as Ludlow installed a corporation stop and a curb stop at Station 163+01. Main Street, Durham. View to the east.

Res. Representative:	J. Meunier	Date: 7/13/20

Daily Report

Durham Meadows Pipeline Installation July 13, 2020 Project: Date: Day of Week: Monday Location: Pickett Lane and Main Street, Durham Report No: 118 Project #: AECOM: 6061487 **Contractor: Ludlow Construction** Page: **9** of **9**



Picture 6: Ludlow tapping the main water line to install a corporation stop at Station 163+01.

Res. Representative:	J. Meunier	Date: 7/13/20