Daily Report December 08, 2020 **Project: Durham Meadows Pipeline Installation** Date: Day of Week: Tuesday Location: Main Street, Durham; S. Main Street, Middletown **Report No:** Project #: AECOM: 6061487 213 Page: 1 of 4 **Contractor:** Ludlow Construction Weather Conditions Conditions: Daylight hours: Partly sunny. Winds variable 0-4 mph. Temperature (°F): High 47°F Low 29F **Contractors & Subcontractors Workforce** Equipment in Use Trade # x hrs Trade # x hrs Туре # x hrs USACE udlow Construction Concrete/Asphalt Road Saw 0 x 8 Superintendent 0 х 8 Field Engineer 8 Dump truck 1 х 8 1 х Excavator – Large 8 Safety Officer 0 8 0 х х 8 United Concrete 0 x 4 Foreman 0 х 8 Excavator - Mid-Size 0 х 0 8 Excavator - Rubber Wheeled – Rock 1 х 8 Dump truck Operator х Barnhart 0 x 4 0 8 Skid Steer / Bucket Loader 0 8 Excavator Operator х х 8 Skid Steer/Bucket Loader 0 8 Rolling Compactor 0 х х Х 8 0 8 Plate Compactor 0 х aborers 8 Note that some persons Jumping Jack Compactor 0 х DN Tanks Multiple pieces equipment. Street Sweeper (Broce Broom) 0 х 8 8 Superintendent Material Hopper 0 х 0 Х 8 Laborers 0 x 8 Sub-contractor 0 Х 8 Pipe saw 0 <u>x</u> 8 Municipal Police Detail Light Tower 0 x 8 0 Х 8 State Police Detail 0 Х 8 Visitors: None.

Pipe Connections, Installations, and Other Work

Ludlow and its subcontractors performed several tasks today that included site housekeeping, additional work in the PRV vault, and the painting of fog lines on Route 17 in Durham and Middletown.

Compaction Testing

Soil compaction testing was not performed today. Compaction test data for soil, concrete, and asphalt can be found under the "Related Links" column on the righthand side of the page of the following link:

https://www.nae.usace.army.mil/Missions/Projects-Topics/Durham-Meadows-Water-Lines-Project/

Daily Activities – Miscellaneous activities, Durham

Ludlow and its subcontractors performed several tasks today that included site housekeeping, additional work in the PRV vault, and the painting of fog lines on Route 17 in Durham and Middletown.

0750: Ludlow has one person on site today to clean up the storage areas and the Ludlow trailer at 285 Main Street, Durham.

Res. Representative:

J. Meunier

Date: 12/08/20

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	December 08, 2020
Location:	Main Street, Durham; S. Main Street, Middletown	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	213
Contractor:	Ludlow Construction	Page:	2 of 4

0905: Ludlow continues working to clean up the storage areas and the Ludlow trailer at 285 Main Street, Durham.

1047:United Concrete has one person working inside of the PRV vault located at Station 161+30, installing lights and electrical conduit.

1300: Safety Marking Inc. is staged at 285 Main Street as they prepare to paint fog lines on Route 17 in Durham and Middletown.

1318: Safety Marking Inc. continues to be staged at 285 Main Street, Durham as they prepare to paint fog lines on Route 17 in Durham and Middletown.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	December 08, 2020
Location:	Main Street, Durham; S. Main Street, Middletown	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	213
Contractor:	Ludlow Construction	Page:	3 of 4



Picture 1: The interior of the PRV vault located at Station 161+30. 2" PVC pipe has been installed, connecting a PVC stub that drains water from the drain channel that surrounds the edge of the eastern vault hatch to the sump located on the southern vault wall. View to the southeast.

J. Meunier

Daily Report					
Project:	Durham Meadows Pipeline Installation	Date:	December 08, 2020		
Location:	Main Street, Durham; S. Main Street, Middletown	Day of Week:	Tuesday		
Project #:	AECOM: 6061487	Report No:	213		
Contractor:	Ludlow Construction	Page:	4 of 4		



Picture 2: United Concrete installing metal conduit inside of the PRV vault. View to the northeast.

J. Meunier