Daily Report

Project:Durham Meadows Pipeline InstallationDate:October 5, 2021Location:Maiden Lane, Main Street, Durham; S. Main Street, MiddletownDay of Week:TuesdayProject #:AECOM: 6061487Report No:336

Page: 1 of 15

Contractor: Ludlow Construction

Weather Conditions

Conditions: Daylight hours: Rain/overcast. Winds variable 0-7 mph.

Temperature (°F): High 64°F Low 54°F

Contractors & Subcontractors Workforce					Equipment in Use			
Trade	# x hrs	Trade	#	Χ	hrs	Type # x	hrs	
USACE		Ludlow Construction				Concrete/Asphalt Road Saw 0 x	8	
Field Engineer	1 x 8	Superintendent	1	Χ	8	Dump truck 2 x	8	
		Safety Officer	1	Χ	8	Excavator – Large 0 x	8	
		Foreman	1	Χ	8	Excavator - Mid-Size 1 x	8	
		Dump truck Operator	1	Χ	8	Excavator - Rubber Wheeled 1 x	8	
		Excavator Operator	1	Χ	8	Skid Steer / Bucket Loader 1 x	8	
		Skid Steer/Bucket Loader	1	Χ	8	Rolling Compactor 1 x	8	
		Laborers	4	Χ	8	Plate Compactor 0 x	8	
United Concrete	0 X 8	Note that some persons operate				Jumping Jack Compactor 1 x	8	
Fazzino Plumbing	2 x 8	Multiple pieces equipment.				Street Sweeper (Broce Broom) 1 x	8	
Apuzzo Electric	0 x 8					Material Hopper 0 x	8	
CT Traffic Control	1 x 8	Sub-contractor	3	Χ	8	cutoff saw 0 x	8	
DN Tanks	0 x 8	Municipal Police Detail	0	Χ	8	Light Tower 0 x	8	
		State Police Detail	0	Χ	8			

Visitors: None.

Pipe Connections, Installations, and Other Work

Ludlow installed 1" copper water service lines at the 24 and 36 Maiden Lane residences in Durham. Fazzino Plumbing installed final water service components at the 308, 316, and 321 Main Street, Durham, properties. Ludlow performed minor earth work at the water meter building, grading fill on the west, north, and south sides of the vault.

Daily Activities - Installation of water lines, Main Street, Durham

Ludlow installed 1" copper water service lines at the 24 and 36 Maiden Lane residences in Durham.

0714: Ludlow begins to excavate on the south side of the residence located at 24 Maiden Lane for the installation of a 1" copper water service line.

0825: Ludlow has drilled through the east side of the 24 Maiden Lane residence foundation. The penetration point is located 19" east of the southwest corner of house.

0841: Ludlow has begun to excavate a trench at the 36 Maiden Lane residence for the installation of a 1" copper water service line, starting at the home's curb stop and working north towards the home's eastern foundation.

Res. Representative:	J. Meunier	Date:	10/05/21

Daily Report

October 5, 2021 Project: Date: **Durham Meadows Pipeline Installation** Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday Location: Middletown Project #: AECOM: 6061487 Report No: 336 Page: 2 of 15 Contractor: **Ludlow Construction**

0855: Ludlow is backfilling the trench at 24 Maiden Lane with native fill placed in 1' lifts and compacted with a jumping jack compactor.

0934: Ludlow continues to excavate a trench at the 36 Maiden Lane property for the installation of 1" copper water service line.

0947: Ludlow is raking and seeding loam that they placed at the at 18 Maiden Lane property on those areas of the lawn that were disturbed by the installation of a 1" copper water service line yesterday.

0958: Ludlow has completed excavating a trench between the curb stop and the east side of the foundation of the 36 Maiden Lane residence for the installation of a 1" copper water service line.

1014: Ludlow continues work on installing a 1" copper water service line at the 36 Maiden Lane property. Ludlow is currently placing 1" copper water service line in the open trench.

1129: Ludlow is backfilling the trench they excavated for the installation of a 1" copper water service line at the 36 Maiden Lane property. Ludlow is placing 6" of sand over the 1" copper pipe, followed by caution tape, followed by native and imported fill that they are placing in 1' lifts and compacting with a jumping jack compactor.

1310: Ludlow has finished backfilling the trench they excavated at the 36 Maiden Lane property for the installation of a 1" copper water service line. Ludlow is currently placing grass seed over those portions of the lawn that were disturbed by the installation of the water line.

<u>Daily Activities – Full water service installation activities, Main Street, Durham</u>

Fazzino Plumbing installed final water service components at the 308, 316, and 321 Main Street, Durham, properties.

- 0848: Fazzino Plumbing is installing final water service components at the 308 Main Street residence in Durham.
- 0926: Fazzino continues to install final water service components at the 308 Main Street, Durham, residence.
- 1052: Fazzino Plumbing is installing final water service components at the residence located at 316 Main Street in Durham.
- 1344: Fazzino Plumbing is working at the 321 Main Street property (Durham Health Mart), installing final water service components.
- 1453: Fazzino Plumbing has finished installing final water service components. at the 321 Main Street property.

Daily Activities - Miscellaneous, water meter building, S. Main Street, Middletown

Ludlow performed minor earth work at the water meter building, grading fill on the west, north, and south sides of the vault.

Res. Representative:	J. Meunier	Date:	10/05/21

Daily Report

Project:Durham Meadows Pipeline InstallationDate:October 5, 2021

Location: Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday

Middletown

Project #: AECOM: 6061487 **Report No:** 336

Page: 3 of 15

Contractor: Ludlow Construction



Picture 1: Ludlow excavating a trench at the 24 Maiden Lane property for the installation of a 1" copper water service line. View to the east.

Daily Report

Project:Durham Meadows Pipeline InstallationDate:October 5, 2021

Location: Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday

Middletown

Project #: AECOM: 6061487 **Report No:** 336

Page: 4 of 15

Contractor: Ludlow Construction



Picture 2: Ludlow compacting fill with a jumping jack compactor in the trench that Ludlow excavated at the 24 Maiden Lane property for the installation of a 1" copper water service line. View to the northwest.

Daily Report

Project:Durham Meadows Pipeline InstallationDate:October 5, 2021

Location: Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday

Middletown

Project #: AECOM: 6061487 **Report No:** 336

Page: 5 of 15

Contractor: Ludlow Construction



Picture 3: Ludlow beginning to excavate a trench at the 36 Maiden Lane property for the installation of a 1" copper water service line. View to the north.

Daily Report

Project:Durham Meadows Pipeline InstallationDate:October 5, 2021

Location: Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday

Middletown

Project #: AECOM: 6061487 **Report No:** 336

Page: 6 of 15

Contractor: Ludlow Construction



Picture 4: Trench that Ludlow excavated at the 36 Maiden Lane property for the installation of a 1" copper water service line. View to the north.

Daily Report

Project: Durham Meadows Pipeline Installation **Date:** October 5, 2021

Location: Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday

Middletown

Project #: AECOM: 6061487 **Report No:** 336

Page: 7 of 15

Contractor: Ludlow Construction



Picture 5: Trench that Ludlow excavated at the 36 Maiden Lane property for the installation of a 1" copper water service line. View to the south.

Daily Report

Project: Durham Meadows Pipeline Installation **Date:** October 5, 2021

Location: Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday

Middletown

Project #: AECOM: 6061487 **Report No:** 336

Page: 8 of 15

Contractor: Ludlow Construction



Picture 6: Ludlow spreading grass see on a portion of the lawn of the 24 Maiden Lane residence that was disturbed during the installation of a 1" copper water service line. View to the northwest.

Daily Report

Project:Durham Meadows Pipeline InstallationDate:October 5, 2021

Location: Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday

Middletown

Project #: AECOM: 6061487 **Report No:** 336

Page: 9 of 15

Contractor: Ludlow Construction



Picture 7: 1" copper water service line that Ludlow has passed through the eastern foundation wall of the 36 Maiden Lane residence. View to the west.

Daily Report

Project:Durham Meadows Pipeline InstallationDate:October 5, 2021

Location: Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday

Middletown

Project #: AECOM: 6061487 **Report No:** 336

Page: 10 of 15

Contractor: Ludlow Construction



Picture 8: 1" copper water service line that Ludlow brought into the 36 Maiden Lane residence through eastern foundation wall. View to the south.

Daily Report

Project:Durham Meadows Pipeline InstallationDate:October 5, 2021

Location: Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday

Middletown

Project #: AECOM: 6061487 **Report No:** 336

Page: 11 of 15

Contractor: Ludlow Construction



Picture 9: Ludlow placing sand bedding and warning tape over the 1"water service at the 36 Maiden Lane property. View to the north.

Daily Report

Project:Durham Meadows Pipeline InstallationDate:October 5, 2021

Location: Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday

Middletown

Project #: AECOM: 6061487 **Report No:** 336

Page: 12 of 15

Contractor: Ludlow Construction



Picture 10: Ludlow placing native fill over the 6" of sand they placed over a 1" copper water service line they installed at the 36 Maiden Lane property. View to the north.

Daily Report

Project:Durham Meadows Pipeline InstallationDate:October 5, 2021

Location: Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday

Middletown

Project #: AECOM: 6061487 **Report No:** 336

Page: 13 of 15

Contractor: Ludlow Construction



Picture 11: Final water service components that Fazzino Plumbing installed at the 308 Main Street, Durham, residence.

Res. Representative:	J. Meunier	Date: _ 10/05/21

Daily Report

Project:Durham Meadows Pipeline InstallationDate:October 5, 2021

Location: Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday

Middletown

Project #: AECOM: 6061487 **Report No:** 336

Page: 14 of 15

Contractor: Ludlow Construction



Picture 12: Final water service components that Fazzino Plumbing installed at the 316 Main Street, Durham, residence.

Res. Representative:	J. Meunier	Date: 10/05/21

Daily Report

Project:Durham Meadows Pipeline InstallationDate:October 5, 2021

Location: Maiden Lane, Main Street, Durham; S. Main Street, Day of Week: Tuesday

Middletown

Project #: AECOM: 6061487 **Report No:** 336

Page: 15 of 15

Contractor: Ludlow Construction



Picture 13: Final water service components that Fazzino Plumbing installed at the 321 Main Street, Durham, residence.

Res. Representative:	J. Meunier	Date:	10/05/21