## **AFCOM**

Location:

#### **Daily Report**

Project: December 17, 2021 **Durham Meadows Pipeline Installation** Date: Day of Week: Friday

**Report No:** 385 AECOM: 6061487

Project #: Page: 1 of 5

**Contractor: Ludlow Construction** 

Weather Conditions

Conditions: Daylight hours: Sunny. Winds variable 0-5 mph.

Shared Access Driveway, Middletown

Temperature (°F): High 55°F Low 37°F

	Contr	acto	ors (	& Su
Trade		#	Х	hrs
USACE				
Field Engineer		3	Х	8
Eagle Fence		2	Χ	8
Fazzino Plumbing		0	Χ	8
United Concrete		0	Χ	8
Frontier		0	Х	8
Apuzzo Electric		0	Х	8
CT Traffic Control		0	Х	8
A&R Electrical		0	Х	8
		l		

bcontractors Workforce			
Trade	#	Χ	hrs
Ludlow Construction			
Superintendent	0	Χ	8
Safety Officer	0	Χ	8
Foreman	1	Χ	8
Dump truck Operator	0	Χ	8
Excavator Operator	0	Χ	8
Skid Steer/Bucket Loader	0	Χ	8
Laborers	0	Χ	8
Note that some persons operate			
Multiple pieces equipment.			
Sub-contractor	2	Χ	8
Municipal Police Detail	0	Χ	8
State Police Detail	0	Χ	8

Equipment in Use			
Туре	#	х	hrs
Concrete/Asphalt Road Saw	0	х	8
Dump truck	0	Х	8
Excavator – Large	0	Х	8
Excavator - Mid-Size	0	Х	8
Excavator - Rubber Wheeled	0	Х	8
Skid Steer / Bucket Loader	0	Χ	8
Rolling Compactor	0	Х	8
Plate Compactor	0	Х	8
Jumping Jack Compactor	0	Х	8
Street Sweeper (Broce Broom)	0	Х	8
Material Hopper	0	Х	8
Cutoff saw	0	Х	8
Light Tower	0	Х	8

Visitors:

None.

#### Pipe Connections, Installations, and Other Work

Eagle Fence and Guardrail continued installing a permanent fence around the water tank work zone located east of the Shared Access Driveway in Middletown.

#### Daily Activities - Fence installation, Shared Access Driveway, Middletown

Eagle Fence and Guardrail continued installing a permanent fence around the water tank work zone located east of the Shared Access Driveway in Middletown.

0710: Eagle Fence and Guardrail have returned to the water tank work zone to resume the installation of a permanent fence that will surround the water tank and the altitude valve vault.

0836: Eagle Fence and Guardrail continues to work on installing a permanent fence at the water tank work zone. Eagle has to let the concrete that was placed yesterday set up so they can't begin attaching the top wire or other parts of the fence to the posts yet. Eagle is currently removing the piles of dirt that were left next to each fence post hole when they were augured open.

Res. Representative:	J. Meunier	Date:	12/17/21

#### **Daily Report**

Project: Date: December 17, 2021 **Durham Meadows Pipeline Installation** Day of Week: Friday Location: Shared Access Driveway, Middletown Project #: AECOM: 6061487 **Report No:** 385 Page: 2 of 5 **Contractor: Ludlow Construction** 

1034: Eagle Fence and Guardrail continues to remove removing the piles of dirt that were left next to each fence post hole when they were augured open.

1252: Eagle Fence and Guardrail continues to remove removing the piles of dirt that were left next to each fence post hole when they were augured open.

1335: Eagle Fence and Guardrail continues to remove removing the piles of dirt that were left next to each fence post hole when they were augured open.

1417: Eagle Fence and Guardrail continues to remove removing the piles of dirt that were left next to each fence post hole when they were augured open. Eagle has also started to place the wire brackets on the top of each fence post.

Res. Representative:	J. Meunier	Date:	12/17/21

### **Daily Report**

**Project:** Durham Meadows Pipeline Installation **Date:** December 17, 2021

Location: Shared Access Driveway, Middletown Day of Week: Friday

**Project #:** AECOM: 6061487 **Report No:** 385

Page: 3 of 5

**Contractor:** Ludlow Construction



Picture 1: Eagle Fence and Guardrail grading soil around the fence posts they installed at the water tank work zone on December 16, 2021. View to the north.

Res. Representative: J. Meunier Date: 12/17/21

## **Daily Report**

**Project:** Durham Meadows Pipeline Installation **Date:** December 17, 2021

Location: Shared Access Driveway, Middletown Day of Week: Friday

**Project #:** AECOM: 6061487 **Report No:** 385

Contractor: Ludlow Construction 4 of 5

Eagle Fonce & Guirdrail

Botton

Botto

Picture 2: Eagle Fence and Guardrail placing soil that was displaced during the installation of the fence posts into the bucket of a bobcat to be moved elsewhere. View to the northwest.

Res. Representative: J. Meunier Date: 12/17/21

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:December 17, 2021

Location: Shared Access Driveway, Middletown Day of Week: Friday

**Project #:** AECOM: 6061487 **Report No:** 385

Page: 5 of 5

**Contractor:** Ludlow Construction



Picture 3: Eagle Fence and Guardrail placing a wire bracket on top of a fence post at the water tank work zone. View to the northwest.

Res. Representative: J. Meunier Date: 12/17/21