| | | | | Daily | Rep | or | Ċ | | |
|--------------------|---------|-------|-------|---------------------------------|--------|-------|------|---------------------------------------|--------------|
| Project: | Durha | am N | 1ead | lows Pipeline Installation | | | | Date: Ma | rch 31, 2022 |
| Location: | Maple | e Ave | enue | e, Maiden Lane, and Talcott Lan | e, Du | irha | m | Day of Week: | Thursday |
| Project #: | AECO | M: 6 | 0614 | 487 | | | | Report No: | 399 |
| | | | | | | | | Page: | 1 of 22 |
| Contractor: | Ludlo | w Cc | onstr | ruction | | | | | |
| | | | | | | | | · · · · · · · · · · · · · · · · · · · | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Weather | Cond | itior | IS | | |
| Conditions: | | Da | vligh | t hours: Partly cloudy. Wind va | ariabl | e 0- | 19 m | ւթի. | |
| Temperature (°F): | | Hig | | 63°F Low 37°F | | | | | |
| remperature (1). | | 1118 | 511 | | | | | | |
| (| Contrac | ctors | & SI | ubcontractors Workforce | | | | Equipment in Use | |
| Trade | # | ‡ x | hrs | s Trade | # | Х | hrs | Туре | # x hrs |
| USACE | | | | Ludlow Construction | | | | Concrete/Asphalt Road Saw | 0 x 8 |
| Field Engineer | 1 | 1 x | 8 | Superintendent | 0 | Х | 8 | Dump truck | 0 x 8 |
| | | | | Safety Officer | 0 | Х | 8 | Excavator – Large | 0 x 8 |
| | | | | Foreman | 1 | Х | 8 | Excavator - Mid-Size | 0 x 8 |
| | | | | Dump truck Operator | 0 | Х | 8 | Excavator - Rubber Wheeled | 0 x 8 |
| | | | | Excavator Operator | 0 | Х | 8 | Skid Steer / Bucket Loader | 0 x 8 |
| Knapp Engineering | (| о х | 8 | Skid Steer/Bucket Loader | 0 | Х | 8 | Rolling Compactor | 0 x 8 |
| Fazzino Plumbing | 1 | 1 X | 8 | Laborers | 0 | Х | 8 | Plate Compactor | 0 x 8 |
| United Concrete | (|) Х | 8 | Note that some persons operate | | | | Jumping Jack Compactor | 0 x 8 |
| Frontier | (| Эх | 8 | Multiple pieces equipment. | | | | Street Sweeper (Broce Broom) | 0 x 8 |
| Apuzzo Electric | 2 | 2 x | 8 | | | | | Material Hopper | 0 x 8 |
| CT Traffic Control | (| Эх | 8 | Sub-contractor | 3 | Х | 8 | Cutoff saw | 0 x 8 |
| A&R Electrical | (| Эх | 8 | Municipal Police Detail | 0 | Х | 8 | Light Tower | 0 x 8 |
| | | | | State Police Detail | 0 | Х | 8 | | |
| | | | | | | | | | |
| Visitors: None | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Pipe Connections, Installations, and Other Work

Apuzzo Electric disconnected the existing pump control boxes, feed wires back to the main electrical panel, disconnected wires from the panel, and installed new copper bonding wires from the main electrical panel to the new water services at 235 Main Street; 162, 184, 206, 212R, and 254 Maple Avenue; 105 Maiden Lane; and 25 Talcott Lane. Fazzino Plumbing and Ludlow mobilize to the following addresses today to change the water filters on the recently-installed final water service components and perform a 4-moth inspection of the systems: 120, 167, 196, 208, 216, 242, 248, 176, 228, 228R, 236, 238, 252, 256, 257, 265, 267, 316 Main Street; 19 Maiden Lane, and 129 Maple Avenue.

Daily Activities – Installation of new bonding wire, Durham

Apuzzo Electric disconnected the existing pump control boxes, feed wires back to the main electrical panel, disconnected wires from the panel, and installed new copper bonding wires from the main electrical panel to the new water services at 235 Main Street; 162, 184, 206, 212R, and 254 Maple Avenue; 105 Maiden Lane; and 25 Talcott Lane, Durham.

0750: Apuzzo Electric arrives at the at 235 Main Street, Durham residence to install ground wires to the recently installed final water system components.

Res. Representative:

J. Meunier

Date: 3/31/22

Daily Report

| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
|-------------|---|--------------|----------------|
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 2 of 22 |
| | | • | : |

0818: Apuzzo Electric has finished installing ground wires to the recently installed final water system components at the 235 Maple Avenue residence and is currently mobilizing to the 254 Maple Avenue residence to perform the same.

0846: Apuzzo Electric has just finished installing ground wires to the recently installed final water system components at the 254 Maple Avenue residence and is mobilizing to the 212R Maple Avenue, Durham, residence to perform the same.

0900: Apuzzo Electric is working at the 212 Maple Avenue, Durham, residence installing ground wires to the recently installed final water system components.

0915: Apuzzo Electric arrives at 105 Maiden Lane, Durham, residence to install ground wires to the recently installed final water system components. Fazzino Plumbing and Ludlow continue to work at the 252 Main Street, Durham, residence.

0948: Apuzzo Electric is working at the 162 Maple Avenue, Durham, residence to install ground wires to the recently installed final water system components.

1000: Apuzzo Electric is mobilizing to the 206 Maple Avenue, Durham, residence to install ground wires to the recently installed final water system components.

1007: Apuzzo Electric is at the 206 Maple Avenue, Durham, residence installing ground wires to the recently installed final water system components.

1036: Apuzzo Electric has finished installing ground wires to the recently installed final water system components at the 206 Maple Avenue, Durham residence.

1037: Apuzzo Electric has mobilized to 184 Maple Avenue, Durham, to install ground wires to the recently installed final water system components.

1052: Apuzzo Electric has finished installing ground wires to the recently installed final water system components at the 184 Maple Avenue, Durham, residence.

1054: Apuzzo Electric has mobilized to the 25 Talcott Lane, Durham, residence to install ground wires to the recently installed final water system components.

1111: Apuzzo Electric has mobilized to restaurant at 235 Main Street, Durham, to install ground wires to the recently-installed final water system components.

Daily Report

| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
|-------------|---|--------------|----------------|
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 3 of 22 |

Daily Activities – Filter change and 4-month inspection activities, Durham

Fazzino Plumbing and Ludlow mobilize to the following addresses today to change the water filters on the recently-installed final water service components and perform a 4-moth inspection of the systems: 120, 167, 196, 208, 216, 242, 248, 176, 228, 228R, 236, 238, 252, 256, 257, 265, 267, 316 Main Street; 19 Maiden Lane, and 129 Maple Avenue.

0805: Fazzino Plumbing and Ludlow mobilize to the 19 Maiden Lane, Durham, residence to change the water filter on the recently-installed final water service components.

0816: Fazzino Plumbing mobilizes to the 19 Maiden Lane, Durham residence to change the water filter on the recently-installed final water service components. They are unable to make contact with the owner and mobilize to the 242 Main Street, Durham, residence instead.

0823: Fazzino Plumbing and Ludlow just finished changing the water filter and performing a 4-month inspection of the final water service components at the 242 Main Street, Durham, residence. Fazzino Plumbing and Ludlow are mobilizing to the 248 Main Street, Durham, residence next to perform the same.

0829: Fazzino Plumbing and Ludlow have mobilized to the 248 Main Street, Durham, residence to change out the water filter and perform a 4-month inspection of the recently-installed final water service components.

0833: Fazzino Plumbing and Ludlow are mobilizing to the 176 Main Street, Durham, residence to change out the water filter and perform a 4-month inspection of the recently-installed final water service components.

0846: Fazzino Plumbing and Ludlow have finished at the 176 Main Street residence and are now mobilizing to the 265 and 267 Main Street residences to change out the water filter and perform a 4-month inspection of the system.

0851: Fazzino Plumbing and Ludlow have mobilized to 267 Main Street, Durham, residence to change out the water filter and perform a 4-month inspection of the system.

0906: Fazzino Plumbing and Ludlow have finished changing out the water filter and performing a 4-month inspection of the recently-installed final water system components at the 265 Main Street, Durham, residence.

0909: Fazzino Plumbing and Ludlow have mobilized to 252 Main Street, Durham, residence to change out the water filter and perform a 4-month inspection of the system.

0927: Fazzino Plumbing and Ludlow have mobilized to 216 Main Street, Durham, residence to change out the water filter and perform a 4-month inspection of the system.

0941: Fazzino Plumbing and Ludlow have mobilized to 208 Main Street, Durham, residence to change out the water filter and perform a 4-month inspection of the system.

0951: Fazzino Plumbing and Ludlow have mobilized to 167 Main Street, Durham, residence to change out the water filter and perform a 4-month inspection of the system.

Res. Representative:

Daily Report

| | 4 1 | | |
|-------------|---|--------------|----------------|
| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 4 of 22 |

0954: Fazzino Plumbing and Ludlow have mobilized to 168 Main Street, Durham, residence to change out the water filter and perform a 4-month inspection of the system.

1006: Fazzino Plumbing finishes changing out the water filter at the 168 Main Street, Durham, residence.

1006: Fazzino Plumbing and Ludlow have mobilized to 256 Main Street, Durham, residence to change out the water filter and perform a 4-month inspection of the system.

1024: Fazzino Plumbing and Ludlow have mobilized to the 316 Main Street, Durham, residence to change out the water filter and perform a 4-month inspection of the system.

1036: Fazzino Plumbing and Ludlow have finished changing out the water filter and performing a 4-month inspection of the recently-installed final water system components at the 316 Main Street, Durham, residence.

1153: Fazzino Plumbing and Ludlow arrive at the church located at 196 Main Street, Durham, to change the water filter on the recently-installed final water service components and perform a four-month inspection.

1215: Fazzino Plumbing and Ludlow finish changing out the water filter on the recently-installed final water service components and performing a four-month inspection at 196 Main Street, Durham.

1221: Fazzino Plumbing and Ludlow have mobilized to the residence located at 129 Maple Avenue, Durham, to change the water filter on the recently-installed final water service components and perform a four-month inspection.

1233: Fazzino Plumbing and Ludlow have mobilized to the residence located at the 120 Main Street, Durham, residence to change the water filter on the recently-installed final water service components and perform a four-month inspection.

1248: Fazzino Plumbing and Ludlow have just finished changing out the water filter on the recently-installed final water service components and performing a four-month inspection at the 120 Main Street, Durham, residence.

1307: Fazzino Plumbing and Ludlow have just finished changing out the water filter on the recently-installed final water service components and performing a four-month inspection at the 228 Main Street building and are currently mobilizing to the 228R Main Street building to perform the same.

1315: Fazzino Plumbing and Ludlow have mobilized to the church located at 236 Main Street, Durham, to change out the water filter on the recently-installed final water service components and perform a four-month inspection.

1322: Fazzino Plumbing and Ludlow have mobilized to the market located at 238 Main Street, Durham, to change out the water filter on the recently-installed final water service components and perform a four-month inspection.

1354: Fazzino Plumbing and Ludlow just with filter change and inspection activities at the 257 Main Street, Durham, residence.

1400: Fazzino Plumbing has arrived at the 19 Maiden Lane, Durham, residence to change the water filter on the newly-installed final water service components and to perform a 4-month inspection of the system.

1411 Fazzino Plumbing and Ludlow have finished filter change and inspection activities at the 19 Maiden Lane property and are preparing to depart the site for the day.

Res. Representative:

Daily Report


| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
|-------------|---|--------------|----------------|
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 5 of 22 |

Additional Information

Fazzino Plumbing and Ludlow changed out water filters and performed a 4-month inspection at the following residences: 227/227A, 202, 307, 153, 151R, 243, and 262 Main Street, Durham; and 18 and 35 Maiden Lane, Durham.

Daily Report

| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
|-------------|---|--------------|----------------|
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 6 of 22 |



Picture 1: Fazzino Plumbing changing out the filter on the recently-installed final water system at the 19 Maiden Lane, Durham, residence.

Daily Report

| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
|-------------|---|--------------|----------------|
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 7 of 22 |



Picture 2: Apuzzo Electric installing a ground line to the final water service components at the 25 Talcott Lane, Durham, residence.

Daily Report


| | · · · · · · · · · · · · · · · · · · · | | |
|-------------|---|--------------|----------------|
| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 8 of 22 |



Picture 3: Fazzino Plumbing changing out the filter on the recently installed final water system at the 120 Main Street, Durham, residence.

Daily Report

| | · · · | | |
|-------------|---|--------------|----------------|
| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 9 of 22 |



Picture 4: Fazzino Plumbing changing out the filter on the recently-installed final water system at the 129 Maple Avenue, Durham, residence.

Daily Report


| | <i>i i i</i> | | |
|-------------|---|--------------|------------------------|
| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 10 of 22 |



Picture 5: Apuzzo Electric installing a ground line to the final water service components at the 162 Maple Avenue, Durham, residence.

Daily Report


| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
|-------------|---|-------------------|------------------------|
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 11 of 22 |



Picture 6: Fazzino Plumbing changing out the filter on the recently installed final water system at the 196 Main Street, Durham, building.

Daily Report

| | <i>7</i> 1 | | |
|-------------|---|--------------|------------------------|
| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 12 of 22 |



Picture 7: Apuzzo Electric installing a ground line to the final water service components at the 206 Maple Avenue, Durham, residence.

Daily Report

| | <i>1</i> 1 | | |
|-------------|---|--------------|----------------|
| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 13 of 22 |



Picture 8: Apuzzo Electric installing a ground line to the final water service components at the 212R Maple Avenue, Durham, residence.

Daily Report


| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
|-------------|---|--------------|----------------|
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 14 of 22 |



Picture 9: Fazzino Plumbing changing out the filter on the recently installed final water system at the 228 Main Street, Durham, residence.

Daily Report


| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
|-------------|---|--------------|------------------------|
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 15 of 22 |



Picture 10: Fazzino Plumbing changing out the filter on the recently installed final water system at the 228R Main Street, Durham, residence.

Daily Report


| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
|-------------|---|-------------------|------------------------|
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 16 of 22 |



Picture 11: Apuzzo Electric installing a ground line to the final water service components at the 235 Main Street, Durham, building.

Daily Report

| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
|-------------|---|--------------|------------------------|
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 17 of 22 |



Picture 12: Apuzzo Electric installing a ground line to the final water service components at the 235 Maple Avenue, Durham, residence.

Daily Report


| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
|-------------|---|--------------|------------------------|
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 18 of 22 |



Picture 13: Fazzino Plumbing changing out the filter on the recently installed final water system at the 236 Main Street, Durham, building.

Daily Report


| | <i>i</i> 1 | | |
|-------------|---|--------------|------------------------|
| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 19 of 22 |



Picture 14: Fazzino Plumbing changing out the filter on the recently installed final water system at the 238 Main Street, Durham, building.

Daily Report

| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
|-------------|---|--------------|------------------------|
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 20 of 22 |



Picture 15: Apuzzo Electric installing a ground line to the final water service components at the 105 Maiden Lane, Durham, residence.

Daily Report

| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
|-------------|---|--------------|------------------------|
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 21 of 22 |



Picture 16: Fazzino Plumbing changing out the filter on the recently installed final water system at the 248 Main Street, Durham, residence.

Daily Report

| | 7 1 | | |
|-------------|---|--------------|----------------|
| Project: | Durham Meadows Pipeline Installation | Date: | March 31, 2022 |
| Location: | Maple Avenue, Maiden Lane, and Talcott Lane, Durham | Day of Week: | Thursday |
| Project #: | AECOM: 6061487 | Report No: | 399 |
| Contractor: | Ludlow Construction | Page: | 22 of 22 |



Picture 17: Fazzino Plumbing changing out the filter on the recently installed final water system at the 257 Main Street, Durham, residence.