

AECOM

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	May 06, 2022
Location:	Long Hill Road and the Shared Access Driveway, Middletown	Day of Week:	Friday
Project #:	AECOM: 6061487	Report No:	420
Contractor:	Ludlow Construction	Page:	2 of 7

1340: Ludlow chalking the perimeter of the tank for a reference of depth when pouring the concrete next week.

1330: Ludlow is adding gravel along the perimeter of the fence to a depth of approximately 4 inches.

1440: Ludlow is departing the water tank work zone for the day.

Res. Representative:

K. Bennett

Date: 04/06/22

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	May 06, 2022
Location:	Long Hill Road and the Shared Access Driveway, Middletown	Day of Week:	Friday
Project #:	AECOM: 6061487	Report No:	420
Contractor:	Ludlow Construction	Page:	4 of 7



Picture 2: Ludlow cuts the wire mesh sheets to fit within in each 15' section.

Res. Representative:

K. Bennett

Date: 04/06/22

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	May 06, 2022
Location:	Long Hill Road and the Shared Access Driveway, Middletown	Day of Week:	Friday
Project #:	AECOM: 6061487	Report No:	420
Contractor:	Ludlow Construction	Page:	6 of 7



Picture 4: Ludlow chalks the perimeter of the tank for a reference of depth when pouring the concrete.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	May 06, 2022
Location:	Long Hill Road and the Shared Access Driveway, Middletown	Day of Week:	Friday
Project #:	AECOM: 6061487	Report No:	420
Contractor:	Ludlow Construction	Page:	7 of 7



Picture 5: Ludlow adds gravel along the perimeter of the fence to a depth of approximately 4 inches.