

AECOM

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	June 15, 2022
Location:	Maple Avenue and Maiden Lane, Durham; Talcott Ridge Drive, Middletown	Day of Week:	Wednesday
Project #:	AECOM: 60614871	Report No:	447
Contractor:	Ludlow Construction	Page:	1 of 4

Weather Conditions

Conditions: Daylight hours: Mostly Cloudy. Wind variable 0-6 mph.
 Temperature (°F): High 82°F Low 63°F

Contractors & Subcontractors Workfor57				Equipment in Use			
Trade	#	x	hrs	Trade	#	X	hrs
USACE				Ludlow Construction			
Field Engineer	2	x	8	Superintendent	0	X	8
				Safety Officer	0	X	8
Flow Tech	0	x	8	Foreman	1	X	8
Matt Chlor	0	x	8	Dump truck Operator	0	X	8
A&J Construction	0	x	8	Excavator Operator	2	X	8
Grela Well Drilling	3	X	8	Skid Steer/Bucket Loader	1	X	8
Fazzino Plumbing	0	X	8	Laborers	4	X	8
United Concrete	0	x	8	Note that some persons operate			
Knapp Engineering	0	x	8	Multiple pieces equipment.			
Apuzzo Electric	0	x	8				
Alarm Systems, Inc.	0	x	8	Sub-contractor	3	X	8
A&R Electrical	0	x	8	Municipal Police Detail	0	X	8
				State Police Detail	0	X	8

Type	#	x	hrs
Concrete/Asphalt Road Saw	0	x	8
Dump truck	2	x	8
Excavator – Large	1	x	8
Excavator - Mid-Size	0	x	8
Excavator - Rubber Wheeled	1	x	8
Skid Steer / Bucket Loader	0	x	8
Rolling Compactor	1	x	8
Plate Compactor	0	x	8
Jumping Jack Compactor	1	x	8
Street Sweeper (Broce Broom)	1	x	8
Material Hopper	0	x	8
Cutoff saw	1	x	8
Light Tower	0	x	8

Visitors: None.

Pipe Connections, Installations, and Other Work

Ludlow repairing curbs on Talcott Ridge Drive. Grela Well Drilling and Ludlow performing well decommissioning work on Maple Avenue and Maiden Lane. Ludlow re-paving Maiden Lane.

Daily Activities – Miscellaneous Activities, Middletown

1030: Ludlow crew on Talcott Ridge Drive repairing curbs near 88 Talcott Ridge Dr. Paving crew near intersection of Maiden Lane and Pickett Lane.

1320: Ludlow Crew on Talcott Ridge Drive finishing curb repair work. Paving crew is working their way west along the north side of Maiden Lane.

Daily Activities – Well decommissioning activities, Durham

1320: Grela finishing well abandonment at 24 Maiden Lane. Well abandonment in progress at 236 Maple Avenue.

1430: Ludlow backfilling well excavation at 236 Maple Avenue.

Res. Representative:	A. Bogucki	Date:	6/15/22
-----------------------------	------------	--------------	---------

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	June 15, 2022
Location:	Maple Avenue and Maiden Lane, Durham; Talcott Ridge Drive, Middletown	Day of Week:	Wednesday
Project #:	AECOM: 60614871	Report No:	447
Contractor:	Ludlow Construction	Page:	2 of 4



Photo 1: Grela Well Drilling filling well casing at 24 Maiden Lane with sand. View to the northwest.

Res. Representative:

A. Bogucki

Date: 6/15/22

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	June 15, 2022
Location:	Maple Avenue and Maiden Lane, Durham; Talcott Ridge Drive, Middletown	Day of Week:	Wednesday
Project #:	AECOM: 60614871	Report No:	447
Contractor:	Ludlow Construction	Page:	3 of 4



Photo 2: New asphalt surface on Maiden Lane near Brick Lane intersection. View to the east.

Res. Representative:

A. Bogucki

Date: 6/15/22

AECOM

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	June 15, 2022
Location:	Maple Avenue and Maiden Lane, Durham; Talcott Ridge Drive, Middletown	Day of Week:	Wednesday
Project #:	AECOM: 60614871	Report No:	447
Contractor:	Ludlow Construction	Page:	4 of 4



Photo 3: Ludlow equipment adjacent to 236 Maple Avenue. Crew was finishing backfill of abandoned well head. View to the southwest.

Res. Representative:

A. Bogucki

Date: 6/15/22