#### **Daily Report**

Project: June 22, 2022 **Durham Meadows Pipeline Installation** Date:

Day of Week: Wednesday Location: Maple Avenue and Maiden Lane, Durham

**Report No:** 452 Project #: AECOM: 6061487 Page: 1 of 14

**Contractor:** Ludlow Construction, Laydon Industries

Weather Conditions

Conditions: Daylight hours: Cloudy/rain. Wind variable 0-1 mph.

Temperature (°F): High 64°F Low 57°F

Contr	act	ors	& Sı	bcontractors Workfor57
Trade	#	Х	hrs	Trade
USACE				Ludlow Construction
Field Engineer	1	Х	8	Superintendent
				Safety Officer
Flow Tech	0	Х	8	Foreman
Matt Chlor	0	Χ	8	Dump truck Operator
A&J Construction	0	Χ	8	Excavator Operator
Grela Well Drilling	3	Χ	8	Skid Steer/Bucket Loa
Fazzino Plumbing	0	Χ	8	Laborers
United Concrete	0	Χ	8	Note that some persons operate
Knapp Engineering	0	Х	8	Multiple pieces equipment.
Apuzzo Electric	0	Х	8	
Alarm Systems, Inc.	0	Х	8	Sub-contractor
A&R Electrical	0	Х	8	Municipal Police Deta

			Τ.
Trade	#	Χ	hrs
Ludlow Construction			
Superintendent	0	Χ	8
Safety Officer	0	Χ	8
Foreman	1	Χ	8
Dump truck Operator	0	Χ	8
Excavator Operator	1	Χ	8
Skid Steer/Bucket Loader	0	Χ	8
Laborers	2	Χ	8
Note that some persons operate			
Multiple pieces equipment.			
Sub-contractor	3	Χ	8
Municipal Police Detail	0	Χ	8
State Police Detail	0	Χ	8

Equipment in Use			
Type	#	Х	hrs
Concrete/Asphalt Road Saw	0	х	8
Dump truck	2	Χ	8
Excavator – Large	1	Х	8
Excavator - Mid-Size	0	Х	8
Excavator - Rubber Wheeled	0	Х	8
Skid Steer / Bucket Loader	0	Х	8
Rolling Compactor	1	Х	8
Plate Compactor	0	Х	8
Jumping Jack Compactor	0	Х	8
Street Sweeper (Broce Broom)	1	Х	8
Material Hopper	0	Х	8
Cutoff saw	1	Х	8
Light Tower	0	Х	8

Visitors:

None.

#### Pipe Connections, Installations, and Other Work

Ludlow continued the installation of a 2" copper water service line at the 114 Maiden Lane, Durham, property. Laydon placed loam next to the asphalt curbing they installed yesterday.

#### Daily Activities - installation of water lines, Durham

Ludlow continued the installation of a 2" copper water service line at the 114 Maiden Lane, Durham, property.

0709: Ludlow begins to mobilize back to the 114 Maiden Lane, Durham, property to resume the installation of a 2" copper water service line.

0757: Ludlow has excavated on both sides of a stone wall located on the northwest corner of the 114 Maiden Lane, Durham, residence. Ludlow is preparing to use a pneumatic mole to punch a hole beneath the field stone wall and run a 2" copper water service line beneath it.

Res. Representative:	J. Meunier	Date:	6/22/22

#### **Daily Report**

**Durham Meadows Pipeline Installation** June 22, 2022 Project: Date: Day of Week: Wednesday Location: Maple Avenue and Maiden Lane, Durham Project #: AECOM: 6061487 Report No: 452 Page: 2 of 14 Contractor: Ludlow Construction, Laydon Industries

0837: Ludlow succeeded in using a pneumatic mole to punch a hole beneath the stone wall located on the northwest corner of the 114 Maiden Lane residence. Ludlow is currently inserting 2" copper pipe beneath the stone wall and is advancing it towards the residence.

0935: Ludlow has backfilled over the 2" copper water service line they ran beneath the stone wall located on the northwest corner of the 114 Maiden Lane residence. Ludlow backfilled over the copper pipe in 1' lifts and compacted the material with a jumping jack. Ludlow continues to excavate a trench down the driveway of the 114 Maiden Lane property, moving south towards Maiden Lane.

1011: Ludlow continues to excavate a trench down the driveway of the 114 Maiden Lane property, moving south towards Maiden Lane as they continue to install a 2" copper water service line.

1212: Ludlow continues to excavate a trench down the driveway of the 114 Maiden Lane property, moving south towards Maiden Lane as they continue to install a 2" copper water service line.

1317: Ludlow has backfilled over most of the ~240' of 2" copper water service line to installed today at the 114 Maiden Lane property. Ludlow is currently using a skid steer and a plate compactor to grade and compact the areas where they backfield over the 2" copper pipe they installed.

1404: Ludlow continues to use a skid steer and a plate compactor to grade and compact the areas where they backfield over the 2" copper pipe they installed.

1432 Ludlow begins to demobilize from the 114 Maiden Lane property for the day. Heavy rain continues to fall.

#### Daily Activities - Maple Avenue paving activities, Durham

Laydon placed loam next to the asphalt curbing they installed yesterday.

0732: Laydon musters in the parking lot of the 280 Main Street, Durham, property as they prepare to place loam on the west side of the asphalt curbing they installed yesterday in the west side of Maple Avenue, Durham.

0817: Laydon is currently placing loam on the west side of the asphalt curbing they placed yesterday on the east side of the 248 Maple Avenue, Durham, property.

0856: Laydon continues to work in a southwards direction on Maple Avenue, continuing to place loam on the west side of the asphalt curbing they installed yesterday.

0917: Laydon has progressed as far as 230 Maple Avenue as they continue to work southwards, placing loam on the west side of the asphalt curbing they installed yesterday.

1028: Laydon has progressed as far as 206 Maple Avenue as they continue to work southwards, placing loam on the west side of the asphalt curbing they installed yesterday.

1155: Laydon has progressed as far as 188 Maple Avenue as they continue to work southwards, placing loam on the west side of the asphalt curbing they installed yesterday.

Res. Representative:	J. Meunier	Date:	6/22/22

### **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	June 22, 2022
Location:	Maple Avenue and Maiden Lane, Durham	Day of Week:	Wednesday
Project #:	AECOM: 6061487	Report No:	452
Contractor:	Ludlow Construction, Laydon Industries	Page:	<b>3</b> of <b>14</b>

1243: Laydon continues to work southwards, placing loam on the west side of the asphalt curbing they installed yesterday on Maple Avenue.

1255: Laydon has progressed as far as 158 Maple Avenue as they continue to work southwards, placing loam on the west side of the asphalt curbing they installed yesterday.

1336: Heavy rain is currently falling. Laydon has finished placing loam on the west side of the curbing they installed yesterday on the west side of Maple Avenue.

Res. Representative:	J. Meunier	Date:	6/22/22

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 22, 2022

Location: Maple Avenue and Maiden Lane, Durham Day of Week: Wednesday

**Project #:** AECOM: 6061487 **Report No:** 452

Page: 4 of 14

**Contractor:** Ludlow Construction, Laydon Industries



Picture 1: Ludlow excavating on the west side of a stone wall located next to the northwest corner of the 114 Maiden Lane, Durham, residence as they work to install a 2" copper water service line. View to the south.

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 22, 2022

Location: Maple Avenue and Maiden Lane, Durham Day of Week: Wednesday

**Project #:** AECOM: 6061487 **Report No:** 452

Contractor: Ludlow Construction, Laydon Industries 5 of 14



Picture 2: Laydon placing loam on the west side of Maple Avenue on the 248 Maple Avenue, Durham property. View to the southeast.

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 22, 2022

Location: Maple Avenue and Maiden Lane, Durham Day of Week: Wednesday

**Project #:** AECOM: 6061487 **Report No:** 452

Page: 6 of 14

**Contractor:** Ludlow Construction, Laydon Industries



Picture 3: Ludlow having excavated on both sides of the stone wall located next to the northwest corner of the 114 Maiden Lane, Durham, residence where they will use a pneumatic mole to punch a hole beneath the wall to install a 2" copper water service line. View to the west.

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 22, 2022

Location: Maple Avenue and Maiden Lane, Durham Day of Week: Wednesday

**Project #:** AECOM: 6061487 **Report No:** 452

Page: 7 of 14

**Contractor:** Ludlow Construction, Laydon Industries



Picture 4: Ludlow running a 2" copper water service line beneath the stone wall located next to the northwest corner of the 114 Maiden Lane, Durham, residence. View to the southeast.

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 22, 2022

Location: Maple Avenue and Maiden Lane, Durham Day of Week: Wednesday

**Project #:** AECOM: 6061487 **Report No:** 452

Page: 8 of 14

**Contractor:** Ludlow Construction, Laydon Industries



Picture 5: Laydon raking out loam they have placed on the west side of asphalt curbing they placed yesterday east of the 230 Maple Avenue, Durham, property. View to the north.

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 22, 2022

Location: Maple Avenue and Maiden Lane, Durham Day of Week: Wednesday

**Project #:** AECOM: 6061487 **Report No:** 452

Page: 9 of 14

**Contractor:** Ludlow Construction, Laydon Industries



Picture 6: The east side of a stone wall located next to the northwest corner of the 114 Maiden Lane, Durham, residence after Ludlow installed a 2" copper water service line and backfilled over it. View to the west.

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 22, 2022

Location: Maple Avenue and Maiden Lane, Durham Day of Week: Wednesday

**Project #:** AECOM: 6061487 **Report No:** 452

Contractor: Page: 10 of 14

Ludlow Construction, Laydon Industries

Picture 7: Ludlow preparing to use a brass union to connect two sections of 2" copper water service line at the 114 Maiden Lane, Durham, property.

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 22, 2022

Location: Maple Avenue and Maiden Lane, Durham Day of Week: Wednesday

**Project #:** AECOM: 6061487 **Report No:** 452

Contractor: Page: 11 of 14

Ludlow Construction, Laydon Industries



Picture 8: Ludlow excavating down the driveway of the 114 Maiden Lane, Durham, property as they install a 2" copper water service line. View to the southwest.

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 22, 2022

Location: Maple Avenue and Maiden Lane, Durham Day of Week: Wednesday

**Project #:** AECOM: 6061487 **Report No:** 452

Contractor: Ludlow Construction, Laydon Industries Page: 12 of 14



Picture 9: Ludlow installing a 2" copper water service line in the trench they excavated down the driveway of the 114 Maiden Lane, Durham, property. View to the south.

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 22, 2022

Location: Maple Avenue and Maiden Lane, Durham Day of Week: Wednesday

**Project #:** AECOM: 6061487 **Report No:** 452

Contractor: Page: 13 of 14

Ludlow Construction, Laydon Industries



Picture 10: Ludlow compacting the material that was backfilled over the 2" copper water service line they installed at the 114 Maiden Lane, Durham, property. View to the northwest.


### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 22, 2022

Location: Maple Avenue and Maiden Lane, Durham Day of Week: Wednesday

**Project #:** AECOM: 6061487 **Report No:** 452

Contractor: Ludlow Construction, Laydon Industries Page: 14 of 14



Picture 11: Ludlow grading and compacting the material that was backfilled over the 2" copper water service line they installed at the 114 Maiden Lane, Durham, property. View to the west.