### **AFCOM**

#### **Daily Report**

Project: **Durham Meadows Pipeline Installation** June 30, 2022 Date: Day of Week: Thursday Location: Pickett Lane, Durham **Report No:** 458 Project #: AECOM: 6061487 Page: 1 of 11 Contractor: **Ludlow Construction** Weather Conditions Daylight hours: Sunny. Wind variable 0-6 mph. Conditions: Temperature (°F): High 84°F Low 57°F Contractors & Subcontractors Workforce Equipment in Use # x hrs # X hrs Trade Trade Type # x hrs USACE Ludlow Construction Concrete/Asphalt Road Saw 0 x 8 Field Engineer 2 x 8 1 Superintendent 0 Χ 8 Dump truck Х Safety Officer 0 Χ 8 Excavator – Large 1 x 8 Χ Flow Tech 0 8 Foreman 1 Χ 8 Excavator - Mid-Size 0 x 8 Matt Chlor Χ Dump truck Operator 0 0 x 8 0 8 Χ 8 Excavator - Rubber Wheeled 0 x 8 A&J Construction 0 Χ 8 Excavator Operator 1 Χ 8 Skid Steer / Bucket Loader Χ x 8 Grela Well Drilling 0 8 Skid Steer/Bucket Loader 0 Χ Rolling Compactor 8 Fazzino Plumbing 0 Χ 8 Laborers 2 Χ 8 Plate Compactor 8 x 0 Note that some persons operate United Concrete Χ 8 0 x 8 0 Jumping Jack Compactor Multiple pieces equipment. Knapp Engineering 1 Х 8 Street Sweeper (Broce Broom) 1 x 8 Material Hopper Apuzzo Electric 0 8 x 0 Х 8 Alarm Systems, Inc. 0 Sub-contractor Cutoff saw 1 x 8 Х 8 0 Χ 8 A&R Electrical 0 Χ 8 Municipal Police Detail Light Tower 0 x 8 0 Χ 8

#### Pipe Connections, Installations, and Other Work

None.

Visitors:

Ludlow installed a catch basin on the north side of Pickett Lane, Durham, at Station 500+50. Knapp Engineering continued work on the SCADA system.

Χ

#### Daily Activities - installation of water lines, Durham

Ludlow installed a catch basin on the north side of Pickett Lane, Durham, at Station 500+50.

State Police Detail

0715: Ludlow is staging at the intersection of Pickett Lane and Main Street in Durham to begin installing catch basins.

0752: Ludlow continues mobilizing to the intersection of Pickett in Main Street.

0824: Ludlow is hand excavating on the north side of Picket Lane at Station 500+50 in order to locate subsurface utilities before installing a new catch basin. Ludlow is also excavating a test pit on the south side of Pickett Lane at Station 500+50 to daylight subsurface utilities.

Res. Representative:	J. Meunier	Date:	6/30/22

#### **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	June 30, 2022
Location:	Pickett Lane, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	458
Contractor:	Ludlow Construction	Page:	2 of 11

0829: Ludlow is saw cutting around the old catch basin located on the north side of Pickett Lane at Station 500+50 as they prepare to remove the old catch basin and install a new one.

0910: Ludlow continues to excavate a test pit located on the south side of Pickett Lane to identify subsurface utilities.

0947: Ludlow is excavating at Station 500+50 on the north side of Pickett where they just removed an old catch basin and are preparing to install a new catch basin.

1035: Ludlow has excavated ~6.5' below surface grade at Station 500+50 on the north side of Picket Lane as they work to install a new catch basin.

1112: Ludlow has backfilled the test pit they excavated on the south side of Pickett Lane at Station 500+50. Ludlow is in the process of backfilling another test they conducted immediately south of the driveway for the 175 and 177R Main Street residences (approximately Station 500+45).

1212: Ludlow has just placed a load of  $\frac{3}{2}$  stone into the excavation located on the north side of Pickett Lane as they continue the installation of a new catch basin at Station 500+50.

1252: Ludlow continues installing a catch basin on the north side of Picket Lane at Station 500+50. Ludlow is also trenching across Picket Lane to remove a section of 12" RCP.

1336: Ludlow is replacing a section of 12" RCP on the westbound lane of Pickett Lane at Station 500+50. Ludlow will be replacing the RCP with new section of RCP.

1428: Ludlow is installing a new section of 12" RCP on the westbound lane of Pickett Lane at Station 500+50.

1507: Ludlow is closing up the excavations they made during the installation of a catch basin and a section of 12" RCP at Station 500+50 on Pickett Lane.

Res. Representative:	J. Meunier	Date:	6/30/22

#### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 30, 2022

Location: Pickett Lane, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 458

Page: 3 of 11

**Contractor:** Ludlow Construction



Picture 1: Ludlow hand excavating at Station 500+50 on the north side of Pickett Lane, Durham, to located subsurface utilities before installing a new catch basin. View to the southwest.

Res. Representative:	J. Meunier	Date:	6/30/22
	ı — — — — — — — — — — — — — — — — — — —	<del></del>	-,,

#### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 30, 2022

Location: Pickett Lane, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 458

Contractor: Ludlow Construction Page: 4 of 11



Picture 2: Ludlow excavating at Station 500+50 on the south side of Pickett Lane, Durham, to locate subsurface utilities. View to the southeast.

Res. Representative:	J. Meunier	Date:	6/30/22
	ı — — — — — — — — — — — — — — — — — — —	<del></del>	-,,

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 30, 2022

Location: Pickett Lane, Durham


**Project #:** AECOM: 6061487 **Report No:** 458

Page: 5 of 11

Thursday

Day of Week:

**Contractor:** Ludlow Construction



Picture 3: Ludlow saw-cutting around a catch basin that they are replacing today on Pickett Lane, Durham. View to the west.

Res. Representative:	J. Meunier	Date:	6/30/22

### **Daily Report**

Project: June 30, 2022 **Durham Meadows Pipeline Installation** Date: Thursday

Day of Week: Location: Pickett Lane, Durham

Project #: AECOM: 6061487 **Report No:** 458

> Page: **6** of **11**

**Contractor: Ludlow Construction** 



Picture 4: Subsurface utilities that Ludlow daylighted on the south side of Picket Lane at Station 500+50. View to the southwest.

Res. Representative:	J. Meunier	Date:	6/30/22
•			

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 30, 2022

Location: Pickett Lane, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 458

Contractor: Ludlow Construction Page: 7 of 11



Picture 5: Ludlow excavating on the north side of Picket Lane at Station 500+50 after removing the existing catch basin. View to the south.

Res. Representative:	J. Meunier	Date:	6/30/22

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 30, 2022

Location: Pickett Lane, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 458

Page: 8 of 11

**Contractor:** Ludlow Construction



Picture 6: Ludlow placing ConSeal tape to a section of the catch basin they are about to install at Station 500+50 on the north side of Pickett Lane.

Res. Representative:	J. Meunier	Date:	6/30/22	

#### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 30, 2022

Location: Pickett Lane, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 458

Contractor: Ludlow Construction Page: 9 of 11



Picture 7: Ludlow excavating across the westbound lane of Pickett Lane as they work to replace a section of 12" RCP that will connect to the south side of the catch basin the just installed. View to the south.

Res. Representative:	J. Meunier	Date:	6/30/22

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 30, 2022

Location: Pickett Lane, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 458

Contractor: Ludlow Construction Page: 10 of 11



Picture 8: Ludlow installing a section of 12" RCP that will connect to the south side of the catch basin the just installed. View to the north.

Res. Representative:	J. Meunier	Date:	6/30/22

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:June 30, 2022

Location: Pickett Lane, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 458

Contractor: Ludlow Construction Page: 11 of 11



Picture 9: Ludlow compacting fill around sections of a catch basin they are installing on the north side of Pickett Lane at Station 500+50. View to the southeast.

			2/22/22
Res. Representative:	J. Meunier	Date:	6/30/22