			Daily F	lep	ort	•		
Project: [	Durham Me	eado	ws Pipeline Installation				Date:	July 07, 2022
Location:	Main Stroo		rham				Day of Week:	Thursday
	Main Street	., Du	mam					
Project #:	AECOM: 60	6148	37				Report No:	462
							Page:	<b>1</b> of <b>8</b>
Contractor:	Ludlow Con	stru	ction					
		_		_	_	_		
			Weather C	andi	tion	~		
C ditions	David					S		
Conditions:	-	-	hours: Sunny. Wind variable 0	)-/ m	iph.			
Temperature (°F):	High	ı	78°F Low 62°F					
Contractors & Subcontractors Workforce Equipment in Use								
Trade	- I I I	hrs	Trade	#	х	hrs	Туре	# x hrs
USACE			Ludlow Construction			111.5	Concrete/Asphalt Road Saw	0 x 8
Field Engineer	1 x	8	Superintendent	0	Х	8	Dump truck	0 x 8
	×		Safety Officer	1	X	8	Excavator – Large	0 x 8
Jay's Landscaping	0 X	8	Foreman	0	X	8	Excavator - Mid-Size	0 x 8
West State Mechanic		8	Dump truck Operator	0	X	8	Excavator - Rubber Wheeled	0 x 8
A&J Construction	0 X	8	Excavator Operator	0	X	8	Skid Steer / Bucket Loader	0 x 8
Grela Well Drilling	0 X	8	Skid Steer/Bucket Loader	0	Х	8	Rolling Compactor	0 x 8
Fazzino Plumbing	0 X	8	Laborers	0	Х	8	Plate Compactor	0 x 8
United Concrete	0 X	8	Note that some persons operate				Jumping Jack Compactor	0 x 8
Knapp Engineering	0 x	8	Multiple pieces equipment.				Street Sweeper (Broce Broom)	0 x 8
Apuzzo Electric	0 x	8					Material Hopper	0 x 8
Alarm Systems, Inc.	0 x	8	Sub-contractor	1	Х	8	Cutoff saw	0 x 8
A&R Electrical	0 x	8	Municipal Police Detail	0	Х	8	Light Tower	0 x 8
			State Police Detail	0	Х	8		
Visitors: None.								

#### Pipe Connections, Installations, and Other Work

Ludlow contractor West State Mechanical Inc. continued work at the Durham Manufacturing facility located at 201 Main Street in Durham to install a backflow preventer, 4" copper water line, and other hardware associated with the facility's water service.

#### Daily Activities - Installation of water service hardware, 201 Main Street, Durham

Ludlow contractor West State Mechanical Inc. continued work at the Durham Manufacturing facility located at 201 Main Street in Durham to install a backflow preventer, 4" copper water line, and other hardware associated with the facility's water service.

0708: West State Mechanical has returned to the Durham Manufacturing facility to resume work on the plumbing associated with the municipal water service that was recently brought into the facility.

0956: West State Mechanical continues to install a 4" copper water service line on the ceiling of the Durham Manufacturing facility.

				4
Res. Representative:	J. Meunier	Date:	7/07/22	

#### **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	July 07, 2022
Location:	Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	462
Contractor:	Ludlow Construction	Page:	<b>2</b> of <b>8</b>

1042: West State Mechanical has secured the backflow preventer to the stand they fabricated and installed on the west wall of the Durham Manufacturing facility.

1157: West State Mechanical continues to install a 4" copper water service line on the ceiling of the Durham Manufacturing facility.

1228: West State Mechanical continues to install a 4" copper water service line on the ceiling of the Durham Manufacturing facility.

1350: West State Mechanical continues to install a 4" copper water service line on the ceiling of the Durham Manufacturing facility.

1416: West State Mechanical has finished installing 4" copper water service line on the ceiling of the Durham Manufacturing facility for the day.

Res. Representative:	J. Meunier	Date:	7/07/22

#### **Daily Report**

	- 7 - 1 -		
Project:	Durham Meadows Pipeline Installation	Date:	July 07, 2022
Location:	Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	462
Contractor:	Ludlow Construction	Page:	<b>3</b> of <b>8</b>



Picture 1: West State Mechanical installing a 4" copper water service line on the ceiling of the Durham Manufacturing facility.

Res. Representative:	J. Meunier	Date:	7/07/22

### **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	July 07, 2022
Location:	Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	462
Contractor:	Ludlow Construction	Page:	<b>4</b> of <b>8</b>



Picture 2: Pipe support that West State Mechanical is installing on the ceiling of the Durham Manufacturing Facility as they install a 4" copper water service line.

Res. Representative:	J. Meunier	Date:	7/07/22

#### **Daily Report**

Project:	Durham Maadawa Dinalina Installation	Date:	July 07, 2022
Project.	Durham Meadows Pipeline Installation	Date.	•
Location:	Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	462
Contractor:	Ludlow Construction	Page:	5 of 8




Picture 3: A section of 4" copper water feed line that West State Mechanical installed on the ceiling of the Durham Manufacturing facility.

J. Meunier

Date:

#### **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	July 07, 2022
Location:	Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	462
Contractor:	Ludlow Construction	Page:	<b>6</b> of <b>8</b>




Picture 4: A section of 4" copper water feed line that West State Mechanical installed on the ceiling of the Durham Manufacturing facility.

Res. Representative:	J. Meunier	Date:	7/07/22

#### **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	July 07, 2022
Location:	Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	462
Contractor:	Ludlow Construction	Page:	<b>7</b> of <b>8</b>



Picture 5: A section of 4" copper water feed line that West State Mechanical installed on the ceiling of the Durham Manufacturing facility.

Res. Representative:	J. Meunier	Date:	7/07/22	

### **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	July 07, 2022
Location:	Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	462
Contractor:	Ludlow Construction	Page:	8 of 8



Picture 6: Backflow preventer that West State Mechanical installed on the west side of the Durham Manufacturing facility next to where the water service enters the building.

Res. Representative:	J. Meunier	Date:	7/07/22