						Daily I	₹ер	ort	t					
Project:	urh	am	ı M	ead	ow	s Pipeline Installation				Date:	July 2	25,	20	122
Location: P	icke	ickett Lane and Main Street, Durham			Day of Week:	Monday		lay						
Project #:	AECOM: 6061487			Report No:			4	74						
.,										Page:			1 o	f 8
Contractor: L	udlo	w	Cor	nstr	uct	ion								
-										-				
Conditions:		r	Dav	diah	t h	Weather (ours: Sunny. Wind variable (
			•	_		•	J-7 II	ıpıı.						
Temperature (°F):		1	High	n	ŏ	6°F Low 68°F						_	_	_
Со	ntra	icto	ors	& S	ubo	contractors Workforce				Equipment in Use				_
Trade		#	Х	hrs		Trade	#	Χ	hrs	Type		#	Х	hr
USACE						Ludlow Construction				Concrete/Asphalt Road Saw		0	Х	8
Field Engineer		1	Х	8		Superintendent	0	Χ	8	Dump truck		1	Х	8
						Safety Officer	1	Χ	8	Excavator – Large		1	Х	8
KTM Electrical		0	Χ	8		Foreman	1	Χ	8	Excavator - Mid-Size		0	Х	8
West State Mechanica	al	0	Χ	8		Dump truck Operator	1	Χ	8	Excavator - Rubber Wheeled		0	Х	8
A&J Construction		0	Χ	8		Excavator Operator	1	Χ	8	Skid Steer / Bucket Loader		0	Х	8
Grela Well Drilling		0	Χ	8		Skid Steer/Bucket Loader	1	Χ	8	Rolling Compactor		0	Х	8
Fazzino Plumbing		0	Χ	8		Laborers	2	Χ	8	Plate Compactor		1	Х	8
Jnited Concrete		0	Χ	8		Note that some persons operate				Jumping Jack Compactor		1	Х	8
Knapp Engineering		0	Х	8		Multiple pieces equipment.				Street Sweeper (Broce Broom)		0	Х	8
Apuzzo Electric		0	Х	8						Material Hopper		0	Χ	8
Alarm Systems, Inc.		0	Х	8		Sub-contractor	0	Χ	8	Cutoff saw		1	Χ	8
A&R Electrical		0	Х	8		Municipal Police Detail	0	Χ	8	Light Tower		0	Х	8
						State Police Detail	0	Χ	8					

Pipe Connections, Installations, and Other Work

None.

Visitors:

Ludlow began the installation of a water meter vault at Station 525+75 on Pickett Lane, Durham. Ludlow collected water quality samples for laboratory analysis from the Durham Manufacturing facility and the 4" and 8" DIP water lines they recently installed at the Coginchaug Regional High School property.

<u>Daily Activities – Installation of water services, Pickett Lane, Durham</u>

Ludlow began the installation of a vault at Station 525+75 on Pickett Lane, Durham.

0721: Ludlow is mobilizing to Station 525+75 on Pickett Lane, Durham, where they are preparing to install a water meter vault on the south side of the road.

0814: Ludlow is reviewing the plans for the vault installation at Station 525+75 relative to the location of subsurface utilities.

0820: Ludlow is reconfiguring a trench box they plan to use during the installation of a vault at Station 525+75.

Res. Representative:	J. Meunier	Date:	7/25/22	

Daily Report

	<u> </u>		
Project:	Durham Meadows Pipeline Installation	Date:	July 25, 2022
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	474
Contractor:	Ludlow Construction	Page:	2 of 8

0824: Ludlow is working with hand tools to daylight subsurface utilities within the footprint of the vault installation work zone located at Station 525+75.

0900: Ludlow has daylighted an existing 4" PVC waterline on the south side of the vault footprint at Station 525+75.

0931: Ludlow continues to excavate at Station 525+75 for the installation of a vault.

1019: Ludlow continues to excavate at Station 527+75. Ludlow also continues to use hand tools to locate subsurface utilities.

1104: Ludlow continues to excavate at Station 525+75.

1158: Ludlow continues to excavate for the installation of a vault. Ludlow is currently draining the 50' of 4" DIP they previously installed at Station 525+75 through a 1" blowoff that they are directing to a catch basin located at Station ~525+49.

1258: Ludlow has continued to excavate the footprint of the vault they are installing at Station 525+75. Ludlow has temporarily removed a section of gray, 2" PVC conduit and the electrical lines located inside.

1556: Ludlow has set a trench box in the excavation they made for the installation of a vault at Station 525+75.

1417: Ludlow has finished work for the day at Station 525+75 and is preparing to secure the excavation with steel plates.

1444: Ludlow has secured the work zone at Station 525+75 on Picket Lane and is preparing to depart the work zone.

Daily Activities – Water testing activities, Durham

Ludlow collected water quality samples for laboratory analysis from the Durham Manufacturing facility and the 4" and 8" DIP water lines they recently installed at the Coginchaug Regional High School property.

0920: Ludlow has just finished collecting water samples from the Durham Manufacturing facility that will be submitted for E.coli/coliform and HPC analysis.

1057: Ludlow has just finished collecting water samples from the 4" DIP line they recently installed at the Coginchaug Regional High School property. These samples will be submitted for E.coli/coliform and HPC analysis.

1210: Ludlow has just finished collecting water samples from the 8" DIP line they recently installed at the Coginchaug Regional High School property. These samples will be submitted for E.coli/coliform and HPC analysis.

Res. Representative:	J. Meunier	Date:	7/25/22

Daily Report

Project:Durham Meadows Pipeline InstallationDate:July 25, 2022

Location: Pickett Lane and Main Street, Durham Day of Week: Monday

Project #: AECOM: 6061487 **Report No:** 474

Contractor: Ludlow Construction Page: 3 of 8



Picture 1: Ludlow using an excavator and hand tools to locate subsurface utilities located within the footprint of where they are working to install a vault at Station 525+75. View to the east.

Res. Representative:	J. Meunier	Date:	7/25/22

Daily Report

Project:Durham Meadows Pipeline InstallationDate:July 25, 2022

Location: Pickett Lane and Main Street, Durham Day of Week: Monday

 Project #:
 AECOM: 6061487
 Report No:
 474

 Page:
 4 of 8

Contractor: Ludlow Construction



Picture 2: Ludlow excavating the footprint of the vault they are installing at Station 525+75 on Pickett Lane, Durham. View to the east.

Res. Representative:	J. Meunier	Date:	7/25/22

Daily Report

Project:Durham Meadows Pipeline InstallationDate:July 25, 2022

Location: Pickett Lane and Main Street, Durham Day of Week: Monday

Project #: AECOM: 6061487 **Report No:** 474

Contractor: Ludlow Construction Page: 5 of 8



Picture 3: Ludlow draining the 50' of 4" DIP they previously installed at Station 525+75 through a 1" blowoff that they are directing to a catch basin located at Station ~525+49.

Res. Representative:	J. Meunier	Date:	7/25/22

Daily Report

Project:Durham Meadows Pipeline InstallationDate:July 25, 2022

Location: Pickett Lane and Main Street, Durham Day of Week: Monday

Project #: AECOM: 6061487 **Report No:** 474

Contractor: Ludlow Construction Page: 6 of 8



Picture 4: View of the excavation that Ludlow has made for the installation of a vault at Station 525+75. Note the 4" PVC water line that Ludlow has daylighted. View to the southeast.


Res. Representative:	J. Meunier	Date:	7/25/22

Daily Report

Project:Durham Meadows Pipeline InstallationDate:July 25, 2022Location:Pickett Lane and Main Street, DurhamDay of Week:MondayProject #:AECOM: 6061487Report No:474

Page: **7** of **8**

Contractor: Ludlow Construction



Picture 5: Chain of custody associated with the water quality samples that Ludlow collected for laboratory analysis from the Durham Manufacturing facility and the 4" and 8" DIP water lines they recently installed at the Coginchaug Regional High School property.

Res. Representative:	J. N	Meunier	 Date:	_	25/22	

Daily Report

Project: July 25, 2022 **Durham Meadows Pipeline Installation** Date:

Day of Week: Monday Location: Pickett Lane and Main Street, Durham

Project #: AECOM: 6061487 **Report No:** 474 8 of 8

Page: **Contractor: Ludlow Construction**



Picture 6: Trench box that Ludlow has set in the excavation they made for the installation of a vault at Station 525+75.

Res. Representative:	J. Meunier	Date:	7/25/22